STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

O		

AMENDED REPORT □ (highlight changes)

	A DOLIO A TIONI FOR DEDMIT TO DOLL						IINERAL LEASE NO: 47502	6. SURFACE: Indian	
1A. TYPE OF WO	A. TYPE OF WORK: DRILL  REENTER DEEPEN DEEPEN Ute Indian Tribe								
B. TYPE OF WE	B TYPE OF WELL OIL GAS IZ OTHER SINGLE ZONE MILLTIPLE ZONE IZ 8. UNIT OF CA AGREEMENT NAME:								
			- · · · · · · · · · · · · · · · · · · ·			_ IN	/A		
2. NAME OF OPE	•						VELL NAME and NUMBER		
	r & Co., LLC						te Tribal 6-16-1		
475 17th St	3. ADDRESS OF OPERATOR: 475 17th St Suite 1200 CITY Denver STATE CO ZIP 80202 PHONE NUMBER: (303) 292-0949 Wildcat								
4. LOCATION OF WELL (FOOTAGES)  11. QTR/QTR, SECTION, TOWNSHIP, RANGE, MERIDIAN:									
AT SURFACE:	1846 FNL 2	065 FWL				SE	ENW 16 14	S 20E S	
AT PROPOSED	PRODUCING ZONE	: SAME	438415	14	-109.684468				
			EAREST TOWN OR POST	OFFICE:			COUNTY:	13. STATE: UTAH	
See Topo	o Map "A" (At	ttached)				U	intah		
15. DISTANCE TO	NEAREST PROPE	RTY OR LEASE	LINE (FEET)	16. NUMBER O	F ACRES IN LEASE:	17. NUMBE	R OF ACRES ASSIGNED	TO THIS WELL:	
1846					1280			40	
	O NEAREȘT WELL ( R) ON THIS LEASE (		MPLETED, OR	19. PROPOSED	DEPTH:	20. BOND (	DESCRIPTION:		
3080	ON THIS LEASE (	FEET)			5,000	RLB0	008085		
21. ELEVATIONS	(SHOW WHETHER	DF, RT, GR, E	TC.):	22. APPRÓXIM	ATE DATE WORK WILL START:	23. ESTIMA	TED DURATION:		
6838 GR				10/1/200	06	3 Wee	eks		
24.	24. PROPOSED CASING AND CEMENTING PROGRAM								
SIZE OF HOLE	CASING SIZE, G	RADE, AND WE	EIGHT PER FOOT S	ETTING DEPTH	CEMENT TYPE, QU	JANTITY, YIELI	D, AND SLURRY WEIGH	T	
12-1/4"	9-5/8"	J-55	36#	300	Standard Type 5	120 sac	ks 1.18	3 15.6	
8-3/4"	5-1/2"	J-55	15.5#	5,000	Hi-Fill & Poz Prem	979 sac	ks 3.84 & 1.2	5 11 & 14.35	
							***		
25.		**	•	ATTA	CHMENTS				
VERIFY THE FOL	LOWING ARE ATTA	CHED IN ACC	ORDANCE WITH THE UTA		ONSERVATION GENERAL RULES:				
					1				
✓ WELL PL	AT OR MAP PREPA	RED BY LICEN	SED SURVEYOR OR ENG	SINEER	COMPLETE DRILLING PLAN				
EVIDENCE OF DIVISION OF WATER RIGHTS APPROVAL FOR USE OF WATER FORM 5, I					FORM 5, IF OPERATOR IS P	ERSON OR CO	MPANY OTHER THAN T	HE LEASE OWNER	
		<del>''</del>							
	Peff Var	าตเ			TITLE Vice Presiden	t of Oper	ations		
NAME (PLEASE									
SIGNATURE	~/// <sub>1</sub>	N 7			DATE BIZZ C	6			
(This space for Sta	ite uge afity	,					RECE	EIVED	
		La					AUG 2	4 2006	
API NUMBER AS	signed:	3-047	38506	<u></u>	APPROVAL:		DIV. OF OIL, G	AS & MINING	

### T14S, R20E, S.L.B.&M. Found Set Marked Stone. Found Set Pile of stones. Marked Stone. \$89.55'W - 79.60 (G.L.O.) Pile of stones. N89'46'47''W - 5216.85' (Meas.) 1/4 Corner is missing N00'39'29"E (Basis of Bearings) 2613.31" (Measured) 2065 Proposed (Computed) NO.03'W (G.L.O.) Found Set Marked Stone, Pile of stones. **WELL LOCATION:** UTE TRIBAL 6-16-14-20 ELEV. UNGRADED GROUND = 6837.7' NO0'54'10" S89'51'W - 79.70 (G.L.O.) Found Set Marked Stone, Pile of stones.

### $\triangle$ = Section corners located

BASIS OF ELEVATION IS BENCH MARK 60 WF 1952 LOCATED IN THE SW 1/4 OF SECTION 35, T14S, R20E, S.L.B.&M. THE ELEVATION OF THIS BENCH MARK IS SHOWN ON THE FLAT ROCK MESA 7.5 MIN. QUADRANGLE AS BEING 7363'.

UTE TRIBAL 6-16-14-20 (Proposed Well Head) NAD 83 Autonomous

LATITUDE = 39' 36' 05.29" LONGITUDE = 109' 41' 06.37"

### MILLER, DYER & CO. LLC

WELL LOCATION, UTE TRIBAL 6-16-14-20, LOCATED AS SHOWN IN THE SE 1/4 NW 1/4 OF SECTION 16, T14S, R20E, S.L.B.&M. UINTAH COUNTY, UTAH.



#### NOTES:

- 1. Well footages are measured at right angles to the Section Lines.
- 2. Bearings are based on Global Positioning Satellite observations.
- 3. The proposed well bears \$47\*58'40"E 2768.82' from the Northwest Corner of Section 16.


THIS IS TO CERTIFY THAT THE ABOVE PLAT WAS PREPARED FROM FIELD NOTES OF SUMMER OF AND THAT THE SAME ARE TRUE AND CORRECT OF THE BEST OF MY KNOWLEDGE AND BELIEF.

REGISTERED LAND SURVEYOR REGISTRATION NO COMPANY OF STATE OF STATE


### TIMBERLINE LAND SURVEYING, INC.

38 WEST 100 NORTH. - VERNAL, UTAH 84078 (435) 789-1365

`		
DATE SURVEYED: 07-17-06	SURVEYED BY: K.R.K.	SHEET
DATE DRAWN: 07-20-06	DRAWN BY: M.W.W.	2
SCALE: 1" = 1000'	Date Last Revised:	OF 10



### 8-06 Miller Dyer Ute Tribal 16-14-20



6838 -4900 -1938



### 08-06 Miller Dyer Ute Tribal 6-16-14-20

Operator:

Miller, Dyer & Co., LLC

Surface String type:

Project ID: 43-047-38506

Location:

**Uintah County** 

**Environment:** 

Design parameters:

**Collapse** 

Mud weight:

8.600 ppg

Design is based on evacuated pipe.

Minimum design factors: Collapse:

Design factor

1.125

H2S considered?

Surface temperature:

No 75 °F 82 °F

Bottom hole temperature: Temperature gradient:

1.40 °F/100ft

Minimum section length:

300 ft

**Burst:** 

Design factor

1.00

Cement top:

Surface

**Burst** 

Max anticipated surface

No backup mud specified.

pressure:

1,816 psi

Internal gradient: Calculated BHP

0.120 psi/ft 1,876 psi

Tension:

8 Round STC: 8 Round LTC:

**Buttress:** Premium:

Body yield:

1.60 (J) 1.50 (J) 1.50 (B)

1.80 (J) 1.80 (J)

Tension is based on buoyed weight. Neutral point: 436 ft

Re subsequent strings: Next setting depth:

Non-directional string.

Next mud weight: Next setting BHP:

5.000 ft 9.300 ppg 2,416 psi 19.250 ppg

Fracture mud wt: Fracture depth: Injection pressure:

5,000 ft 5,000 psi

Run Seq	Segment Length (ft)	Size (in)	Nominal Weight (lbs/ft)	Grade	End Finish	True Vert Depth (ft)	Measured Depth (ft)	Drift Diameter (in)	Internal Capacity (ft³)
1	500	9.625	36.00	J <b>-</b> 55	ST&C	50Ó	500	8.796	217
Run Seq	Collapse Load (psi)	Collapse Strength (psi)	Collapse Design Factor	Burst Load (psi)	Burst Strength (psi)	Burst Design Factor	Tension Load (Kips)	Tension Strength (Kips)	Tension Design Factor
1	223	2020	9.043	1876	3520	1.88	/ 16	394	25.08 J

Prepared

Helen Sadik-Macdonald

Div of Oil, Gas & Minerals

Phone: 801-538-5357 FAX: 801-359-3940

Date: October 18,2006 Salt Lake City, Utah

by: Remarks:

Collapse is based on a vertical depth of 500 ft, a mud weight of 8.6 ppg. The casing is considered to be evacuated for collapse purposes. Collapse strength is based on the Westcott, Dunlop & Kemler method of biaxial correction for tension.

Burst strength is not adjusted for tension.

Well name:

08-06 Miller Dyer Ute Tribal 6-16-14-20

Operator:

Miller, Dyer & Co., LLC

String type:

Production

Location:

Uintah County

Project ID:

43-047-38506

Design parameters:

Collapse

Mud weight:

9.300 ppg

Design is based on evacuated pipe.

Minimum design factors:

Collapse:

Design factor 1.125 **Environment:** 

H2S considered? Surface temperature: No 75 °F

Bottom hole temperature: Temperature gradient:

145 °F 1.40 °F/100ft

Minimum section length: 1,500 ft

Burst:

Design factor

1.00

1.80 (J) 1.80 (J)

1.60 (J)

1.50 (J)

Cement top:

63 ft

**Burst** 

Max anticipated surface

pressure:

1,316 psi

Internal gradient: Calculated BHP

0.220 psi/ft 2,416 psi

No backup mud specified.

**Tension:** 

8 Round STC: 8 Round LTC:

Buttress: Premium:

Body yield:

1.50 (B)

Non-directional string.

Tension is based on buoyed weight. Neutral point: 4,297 ft

Run Seq	Segment Length (ft)	Size (in)	Nominal Welght (lbs/ft)	Grade	End Finish	True Vert Depth (ft)	Measured Depth (ft)	Drift Diameter (in)	Internal Capacity (ft³)
1	5000	5.5	15.50	J-55	ST&C	5000	5000	4.825	668.2
Run Seq	Collapse Load (psi)	Collapse Strength (psi)	Collapse Design Factor	Burst Load (psi)	Burst Strength (psi)	Burst Design Factor	Tension Load (Kips)	Tension Strength (Kips)	Tension Design Factor
1	2416	4040	1.672	2416	4810	1.99	67	202	3.03 J

Prepared

by:

Helen Sadik-Macdonald

Div of Oil, Gas & Minerals

Phone: 801-538-5357

FAX: 801-359-3940

Date: October 18,2006 Salt Lake City, Utah

Remarks:

Collapse is based on a vertical depth of 5000 ft, a mud weight of 9.3 ppg. The casing is considered to be evacuated for collapse purposes. Collapse strength is based on the Westcott, Dunlop & Kemler method of biaxial correction for tension.

Burst strength is not adjusted for tension.

From:

Robert Clark

To: Date: Whitney, Diana 9/5/2006 9:52:52 AM

Subject:

RDCC short turn around items

items

43.047. 38506

The following comments are provided in response to short turn around items RDCC #6996 through RDCC #6999, and RDCC #7030 through RDCC #7032.

RDCC #6996, Comments begin: The Flying J Oil & Gas Inc proposal to drill the Knight 14-30 wildcat well, in Uintah County, may require a permit, known as an Approval Order, from the Executive Secretary of the Air Quality Board. If any compressor or pump stations are constructed at the site, a permit application, known as a Notice of Intent (NOI), should be submitted to the Executive Secretary at the Utah Division of Air Quality at 150 N. 1950 West, Salt Lake City, Utah, 84116 for review according to the Utah Air Quality Rule R307-401. Permit: Notice of Intent and Approval Order. A copy of the rules is found at <a href="https://www.rules.utah.gov/publicat/code/r307/r307.htm">www.rules.utah.gov/publicat/code/r307/r307.htm</a>.

The proposed project is also subject to Utah Air Quality Rule R307-205-5, Fugitive Dust, due to the fugitive dust that is generated during the excavating phases of the project. These rules apply to construction activities that disturb an area greater than 1/4 acre in size. A permit, known as an Approval Order, is not required from the Executive Secretary of the Air Quality Board, but steps need to be taken to minimize fugitive dust, such as watering and/or chemical stabilization, providing vegetative or synthetic cover or windbreaks. A copy of the rules may be found at www.rules.utah.gov/publicat/code/r307/r307.htm. Comments end.

RDCC # 6997, Comments begin: The Flying J Oil & Gas Inc proposal to drill the Deep Creek 2-30 wildcat well, in Uintah County, may require a permit, known as an Approval Order, from the Executive Secretary of the Air Quality Board. If any compressor or pump stations are constructed at the site, a permit application, known as a Notice of Intent (NOI), should be submitted to the Executive Secretary at the Utah Division of Air Quality at 150 N. 1950 West, Salt Lake City, Utah, 84116 for review according to the Utah Air Quality Rule R307-401. Permit: Notice of Intent and Approval Order. A copy of the rules is found at www.rules.utah.gov/publicat/code/r307/r307.htm.

The proposed project is also subject to Utah Air Quality Rule R307-205-5, Fugitive Dust, due to the fugitive dust that is generated during the excavating phases of the project. These rules apply to construction activities that disturb an area greater than 1/4 acre in size. A permit, known as an Approval Order, is not required from the Executive Secretary of the Air Quality Board, but steps need to be taken to minimize fugitive dust, such as watering and/or chemical stabilization, providing vegetative or synthetic cover or windbreaks. A copy of the rules may be found at <a href="https://www.rules.utah.gov/publicat/code/r307/r307.htm">www.rules.utah.gov/publicat/code/r307/r307.htm</a>. Comments End.

RDCC #6998, Comments begin: The Flying J Oil & Gas Inc proposal to drill the Knight 16-30 wildcat well, in Uintah County, may require a permit, known as an Approval Order, from the Executive Secretary of the Air Quality Board. If any compressor or pump stations are constructed at the site, a permit application, known as a Notice of Intent (NOI), should be submitted to the Executive Secretary at the Utah Division of Air Quality at 150 N. 1950 West, Salt Lake City, Utah, 84116 for review according to the Utah Air Quality Rule R307-401. Permit: Notice of Intent and Approval Order. A copy of the rules is found at <a href="https://www.rules.utah.gov/publicat/code/r307/r307.htm">www.rules.utah.gov/publicat/code/r307/r307.htm</a>.

The proposed project is also subject to Utah Air Quality Rule R307-205-5, Fugitive Dust, due to the fugitive dust that is generated during the excavating phases of the project. These rules apply to construction activities that disturb an area greater than 1/4 acre in size. A permit, known as an Approval Order, is not required from the Executive Secretary of the Air Quality Board, but steps need to be taken to minimize fugitive dust, such as watering and/or chemical stabilization, providing vegetative or synthetic cover or windbreaks. A copy of the rules may be found at <a href="https://www.rules.utah.gov/publicat/code/r307/r307.htm">www.rules.utah.gov/publicat/code/r307/r307.htm</a>. Comments end.

RDCC #6999, Comments begin: The Flying J Oil & Gas Inc proposal to drill the Eliason 6-30 wildcat well, in Uintah County, may require a permit, known as an Approval Order, from the Executive Secretary of the Air Quality Board. If any compressor or pump stations are constructed at the site, a permit application, known as a Notice of Intent (NOI), should be submitted to the Executive Secretary at the Utah Division of Air Quality at 150 N. 1950 West, Salt Lake City, Utah, 84116 for review according to the Utah Air Quality Rule R307-401. Permit: Notice of Intent and Approval Order. A copy of the rules is found at <a href="https://www.rules.utah.gov/publicat/code/r307/r307.htm">www.rules.utah.gov/publicat/code/r307/r307.htm</a>.

The proposed project is also subject to Utah Air Quality Rule R307-205-5, Fugitive Dust, due to the fugitive dust that is generated during the excavating phases of the project. These rules apply to construction activities that disturb an area greater than 1/4 acre in size. A permit, known as an Approval Order, is not required from the Executive Secretary of the Air Quality Board, but steps need to be taken to minimize fugitive dust, such as watering and/or chemical stabilization, providing vegetative or synthetic cover or windbreaks. A copy of the rules may be found at <a href="https://www.rules.utah.gov/publicat/code/r307/r307.htm">www.rules.utah.gov/publicat/code/r307/r307.htm</a>. Comments end.

RDCC # 7030, Comments begin: The Miller, Dyer & Co., LLC proposal to drill the Ute Tribal 8-16-14-20 wildcat well, in Uintah County, may require a permit, known as an Approval Order, from the Executive Secretary of the Air Quality Board. If any compressor or pump stations are constructed at the site, a permit application, known as a Notice of Intent (NOI), should be submitted to the Executive Secretary at the Utah Division of Air Quality at 150 N. 1950 West, Salt Lake City, Utah, 84116 for review according to the Utah Air Quality Rule R307-401. Permit: Notice of Intent and Approval Order. A copy of the rules is found at <a href="https://www.rules.utah.gov/publicat/code/r307/r307.htm">www.rules.utah.gov/publicat/code/r307/r307.htm</a>.

The proposed project is also subject to Utah Air Quality Rule R307-205-5, Fugitive Dust, due to the fugitive dust that is generated during the excavating phases of the project. These rules apply to construction activities that disturb an area greater than 1/4 acre in size. A permit, known as an Approval Order, is not required from the Executive Secretary of the Air Quality Board, but steps need to be taken to minimize fugitive dust, such as watering and/or chemical stabilization, providing vegetative or synthetic cover or windbreaks. A copy of the rules may be found at www.rules.utah.gov/publicat/code/r307/r307.htm Comments end.

RDCC # 7031, Comments begin: The Miller, Dyer & Co., LLC proposal to drill the Ute Tribal 16-16-14-20 wildcat well, in Uintah County, may require a permit, known as an Approval Order, from the Executive Secretary of the Air Quality Board. If any compressor or pump stations are constructed at the site, a permit application, known as a Notice of Intent (NOI), should be submitted to the Executive Secretary at the Utah Division of Air Quality at 150 N. 1950 West, Salt Lake City, Utah, 84116 for review according to the Utah Air Quality Rule R307-401. Permit: Notice of Intent and Approval Order. A copy of the rules is found at www.rules.utah.gov/publicat/code/r307/r307.htm.

The proposed project is also subject to Utah Air Quality Rule R307-205-5, Fugitive Dust, due to the fugitive dust that is generated during the excavating phases of the project. These rules apply to construction activities that disturb an area greater than 1/4 acre in size. A permit, known as an Approval Order, is not required from the Executive Secretary of the Air Quality Board, but steps need to be taken to minimize fugitive dust, such as watering and/or chemical stabilization, providing vegetative or synthetic cover or windbreaks. A copy of the rules may be found at <a href="https://www.rules.utah.gov/publicat/code/r307/r307.htm">www.rules.utah.gov/publicat/code/r307/r307.htm</a> Comments end.

RDCC # 7032, Comments begin: The Miller, Dyer & Co., LLC proposal to drill the Ute Tribal 6-16-14-20 wildcat well, in Uintah County, may require a permit, known as an Approval Order, from the Executive Secretary of the Air Quality Board. If any compressor or pump stations are constructed at the site, a permit application, known as a Notice of Intent (NOI), should be submitted to the Executive Secretary at the Utah Division of Air Quality at 150 N. 1950 West, Salt Lake City, Utah, 84116 for review according to the Utah Air Quality Rule R307-401. Permit: Notice of Intent and Approval Order. A copy of the rules is found at <a href="https://www.rules.utah.gov/publicat/code/r307/r307.htm">www.rules.utah.gov/publicat/code/r307/r307.htm</a>.

The proposed project is also subject to Utah Air Quality Rule R307-205-5, Fugitive Dust, due to the fugitive dust that is generated during the excavating phases of the project. These rules apply to construction activities that disturb an area greater than 1/4 acre in size. A permit, known as an Approval Order, is not required from the Executive Secretary of the Air Quality Board, but steps need to be taken to minimize fugitive dust, such as watering and/or chemical stabilization, providing vegetative or synthetic cover or windbreaks. A copy of the rules may be found at www.rules.utah.gov/publicat/code/r307/r307.htm Comments end.

Robert Clark Division of Air Quality 536-4435

CC:

Mcneill, Dave; Wright, Carolyn

items

### FORM, 3

STATE OF UTAH
DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL, GAS AND MINING

AMENDED REPORT	

(highlight changes)

	-	APPLICA <sup>*</sup>	TION FOR	PERMIT TO	DRILL			5. MINERA ML-475	LLEASE NO: 502	6. SURFACE: Indian	
1A. TYPE OF WO	TYPE OF WORK: DRILL 🗹 REENTER 🗌 DEEPEN 🗌								7. IF INDIAN, ALLOTTEE OR TRIBE NAME: Ute Indian Tribe		
B. TYPE OF WE	ili: OIL 🗌	GAS 🗸	OTHER	SIN	GLE ZONE	MULTIPLE ZON	₽Z		CA AGREEMENT	NAME:	
2. NAME OF OPE								9. WELL N	AME and NUMBER	-	
Miller, Dye	r & Co., LLC	<i>;</i>				PHONE NUMBER:			ibal 6-16-14 AND POOL, OR W		
		) <sub>CITY</sub> Denv	er <sub>sta</sub>	TE CO ZIP 802		(303) 292-0949		Wildca	•	ILECAT.	
	WELL (FOOTAGE	•	61294	· ov	39.6	01541		11. QTR/QT MERIDIA		WNSHIP, RANGE,	
	1846 FNL		*	2 ,				SENW	16 149	S 20E S	
AT PROPOSED	PRODUCING ZOI	NE: SAME	43841	514	109.4	,84468	ĺ				
14. DISTANÇE IN	MILES AND DIRE	CTION FROM NEA	REST TOWN OR PO	ST OFFICE:				12. COUNT	Y:	13. STATE: UTAH	
	o Map "A" ( <i>A</i>	•						Uintah			
	O NEAREST PROF	PERTY OR LEASE	LINE (FEET)	16. NUMBER O	F ACRES IN LEAS		17. NU	MBER OF A	CRES ASSIGNED		
1846						1280		VID DEAGO		40	
APPLIED FO	O NEAREST WELL R) ON THIS LEASE	. (DRILLING, COMI (FEET)	PLETED, OR	19. PROPOSED	DEPTH:	E 000		ND DESCR			
3080	SHOW WHETHE	R DF, RT, GR, ET	<u>- 1</u> .	22 APPROYIMA	ATE DATE WORK	5,000		B00080			
6838 GR	, (On Own While the		J. J.	10/1/200		THE GIVEN		/eeks			
		<del></del>								•	
24.			PROPOS	ED CASING A	ND CEMENT	ING PROGRAM					
SIZE OF HOLE	CASING SIZE,	GRADE, AND WEI	GHT PER FOOT	SETTING DEPTH		CEMENT TYPE, QUA	ANTITY, Y	/IELD, AND	SLURRY WEIGHT		
12-1/4"	9-5/8"	J-55	36#	300	Standard 7	Гуре 5	120 s	acks	1.18	3 15.6	
8-3/4"	5-1/2"	J-55	15.5#	5,000	Hi-Fill & Po	oz Prem	979 s	acks	3.84 & 1.25	11 & 14.35	
							-				
···· ·								******			
				<del></del>							
	<del> </del>										
*	<u> </u>										
25.	·			ATTA	CHMENTS						
VERIFY THE FO	LLOWING ARE AT	TACHED IN ACCO	RDANCE WITH THE	JTAH OIL AND GAS C	ONSERVATION G	ENERAL RULES:					
WELL PL	AT OR MAP PREP	PARED BY LICENS	ED SURVEYOR OR E	NGINEER	<b>✓</b> coм	IPLETE DRILLING PLAN					
☐ EVIDEN	CE OF DIVISION O	E WATER RIGHTS	APPROVAL FOR US	E OF WATER	□ FOR	M 5, IF OPERATOR IS PE	RSON OF	R CÓMPAN	OTHER THAN T	HELEASE OWNER	
			THE THE THE	E OI MAILEN							
						\( \( \)					
NAME (PLEASE	PRINT) Jeff Vá	The state of the s			TITLE	Vice President	t of Op	peration	IS		
SIGNATURE_	<u> </u>	<u> </u>			DATE	8/22/0	6				
(This space for Sta	ate use of it	-				-			RECE	IVED	
	, , ,								AUG 2		
ADI NUMBER :	elones 's	13.002	3850W		g papagan an e e e				AUU 2	T 4000	
API NUMBER AS	OIGNED:	, 7/	<u> </u>		APPROVAL:			mi	V OF OIL O		

DIV. OF OIL, GAS & MINING

### DRILLING PLAN MILLER, DYER & CO. LLC

### UTE TRIBAL #6-16-14-20 SENW Section 16 T14S-R20E

### 1. <u>Estimated Formation Tops</u>

Estimated Formation Tops: MD
Green River Surface

Wasatch 2,350' Oil and/or gas

anticipated > 3,000'

Mesaverde 4,600' Gas

### 2. Pressure Control Equipment

Schematic attached (Diagram "A")

Blow Out Preventer (BOP) will be equipped as follows:

- A. Type: Eleven (11) Inch double Gate Hydraulic 3,000 psi BOP mounted on a 3,000 psi casinghead.
  - a. One set of blind rams (above)
  - b. One set of pipe rams (below)
  - c. Appropriate fill, kill and choke lines will be 2" x 2,000 psi working pressure

### B. Auxiliary Equipment:

Auxiliary equipment to include upper Kelly cock with a handle, a floor safety valve with subs to fit all drill string connections in use, and a string float valve.

A rotating head will be installed above the blow-out preventer to divert any hydrocarbons in the drilling mud away from the rig floor.

- C. Pressure Rating: 3,000 psi WP
- D. Testing Procedure:

### Hydraulic Ram-Type BOP

At a minimum, the BOP, choke manifold, and related equipment will be pressure tested to the approved working pressure of the BOP stack of 3,000 psi. This pressure will be maintained for a period of at least ten (10) minutes or until the requirements of the test are met, whichever is longer.

At a minimum, the above pressure test will be performed:

- 1) When the BOP is initially installed.
- 2) Whenever any seal subject to test pressure is broken.
- 3) Following related repairs; and

### 4) At thirty (30) day intervals

In addition to the above, the pipe and blind rams will be activated each trip, but no more that once each day.

### E. Choke Manifold Equipment:

All choke lines will be straight lines; turns will use tee blocks, or targeted running tees, and will be anchored to prevent whip and vibration. The manifold will have two (2) manual chokes and a pressure gauge.

### F. Accumulator:

The accumulator will have sufficient capacity to open the hydraulically controlled choke line valve, if so equipped, close all rams plus the annular BOP, and retain a minimum of 200 psi above precharge on the closing manifold without the use of the closing unit pumps. The fluid reservoir capacity will be double the usable fluid volume of the accumulator system capacity, and the fluid level of the reservoir will be maintained to the manufacturer's recommendations.

### G. Miscellaneous Information:

The choke manifold and BOP ram extensions rods with hand wheels will be located outside the rig substructure. The hydraulic BOP closing unit will be located at least 25 feet from the well head, but readily accessible to the driller. Exact location and configuration of the hydraulic BOP closing unit will depend on the layout of the particular rig contracted to drill this well.

A flare line will be installed from the choke manifold to a flare pit, extending a minimum of 125 feet from the center of the drill hole.

The BOP and related pressure control equipment will be installed, tested and maintained in compliance with the specifications and requirements of the Onshore oil and Gas Order Number 2.

### 3. Auxiliary Equipment

- a. Kelly cock Yes
- b. Float sub at bit No
- c. Mud logger & instrumentation Yes
- d. Full-opening safety valve on rig floor Yes
- e. Rotating head No

#### 4. **Casing Program**

	Setting Depth	Hole Size	Casing O.D.	Grade	Weight/Ft.	Thread
Conductor	40'	20"	16"	Conductor	0.250" wall	
Surface	0' - 300'	12-1/4"	9-5/8"	J-55	36#	STC
Production	0'- 5,000'	8-3/4"	5-1/2"	J-55	15.5#	STC

Subject to review on the basis of actual conditions encountered. Production casing depth will be adjusted based on results.

### **Cement Program**

Conductor Casing: 0'-40'

Ready Mix to surface

### Surface Casing: 0' - 300'

### Cement:

0'-300' 15.6 ppg Standard Type V 2% CaCl2 1/4 #/sk cello flake Cement yield = 1.18 ft3/sk w/ 5 gal/sk water Annular volume = 300' \* 0.3132 ft3/ft = 94.0 ft3

Excess = 50%

Total volume w/ excess = 94.0 ft 3 \* 1.50 = 141.0 ft 3

**Cement Requirement =** 141.0 ft 3 / 1.18 ft 3/sk = 120 sks

### Production Casing: 0'-5,000'

### Lead Cement:

0'-2500'

11.0 ppg Halliburton Hi-Fill (or equivalent)

16% Bentonite (light weight additive)

0.75% Econolite (light weight additive)

10 #/sk gilsonite (lost circulation additive)

0.25 #/sk Flocele (lost circulation additive)

3% salt

1% HR-7 (retarder)

Cement yield = 3.84 ft3/sk w/ 23 gal/sk water

Volume inside surface casing = 300' \* 0.2691 ft3/ft = 80.7 ft3

Excess = 0%

Annular volume =  $2200^{\circ} * 0.2526 \text{ ft} 3/\text{ft} = 555.7 \text{ ft} 3$ 

Excess = 35%

Annular volume w/ excess = 555.7 ft 3 \* 1.35 = 750.2 ft 3

Total volume = 80.7 + 750.2 = 830.9 ft3

Lead Cement Requirement = 830.9 ft 3 / 3.84 ft 3/sk = 216 sks

### Tail Cement:

2500'-5000' plus shoe joint

14.35 ppg 50/50 Poz Premium

0.6% Halad® - 322 (Low Fluid Loss Control)

2% Microbond M (Cement Material)

5% Salt

1/4 #/sk Flocele (Loct Circulation Additive)

0.2% HR-5 (Retarder)

Cement yield = 1.25 ft3/sk w/ 5.46 gal/sk water

Annular volume = 2500' \* 0.2526 ft3/ft = 631.5 ft3

Excess = 50%

Total annular volume w/ excess = 631.5 ft 3 \* 1.50 = 947.3 ft 3

Shoe volume = 45' \* 0.1336 ft3/ft = 6.0 ft3

Excess (shoe) = 0%

Total volume w/ excess (incl. shoe) = 947.3 + 6.0 = 953.3 ft3

Tail Cement Requirement = 953.3 ft3 / 1.25 ft3/sk = 763 sks

### Displacement Volume:

4955' \* 0.0238 bbl/ft = 117.9 bbls

### 5. <u>Mud Program</u> (visual monitoring)

Interval	Mud Type	Weight	Viscosity	Fluid Loss
0'-	Water/Gel/Lime/Native	8.3-8.6 ppg	33-36 sec/qt	N/C
2,400'	Clays			
2,400'-	KCl/Polymer or	9.0-9.3 ppg	38-42 sec/qt	8-10cc
5000'	DAP/Polymer			

Sufficient mud materials to maintain mud properties, control lost circulation, contain a "gas" kick, and rebuild an active mud system will be available on location during drilling operations.

### 6. Testing, Logging, Coring

- a. Drill stem tests non anticipated
- b. Electric logs DIL/SP/GR, FDC/CNL/CAL/PE/GR, both from TD to surface

c. Coring – possible sidewall coring in the Dakota, Cedar Mountain, Morrison and Entrada.

## 7. <u>Anticipated Bottom Hole Pressure and Temperature, and other Potential Hazards</u>

### A. Bottom Hole Pressure:

Maximum anticipated bottom hole pressure is 2,165 psi (calculated at 0.433 psi/ft. at the 5,000' level of the Mesaverde). This normal pressure gradient is consistent with pressures seen in the nearby Flat Rock Field. Therefore, the maximum anticipated surface pressure is 1065 psi (bottom hole pressure minus the pressure of a partially evacuated hole calculated at 0.22 psi/ft.).

### B. Bottom Hole Temperature:

The bottom hole temperature anticipated in this wellbore is approximately 120 degrees Fahrenheit at 5,000 TVD. This anticipated temperature is consistent with the temperatures encountered in wells drilled previously to similar depths in the Flat Rock Field.

### C. Abnormal Pressures or Temperatures:

As demonstrated above, no abnormal pressures or temperatures are anticipated in this well.

### D. Potential Hazards:

No hydrogen sulfide (H<sub>2</sub>S) gas or other potential hazards have been encountered or are known to exist in any well drilled to similar depths in the general area.

### 8. Anticipated Starting Date and Duration

Spud Date: Upon governmental approval and drilling rig availability

Duration of Operations:

- 1) Drilling: Approximately 10 days.
- 2) Completion: Approximately 10 days

### **Drilling Notification:**

The spud date will be reported orally to the Utah Division of Oil, Gas & Mining, 24 hours prior to spudding, unless otherwise instructed in the site specific conditions of approval.

### SURFACE USE PLAN MILLER, DYER & CO. LLC

### UTE TRIBAL 6-16-14-20 SENW Section 16 T14S-R20E

### 1. Existing Roads:

- a. Topographic Map "A" shows the vicinity of the well, including a portion of the Agency Draw Road. This road is reached from Ouray, Utah, by following the Seep Ridge Road south to Buck Canyon; taking the Buck Canyon road west to the Willow Creek Road; then north on the Willow Creek Road to Santio Crossing, which is at the junction of the Willow Creek Road and the Agency Draw Road. The Flat Rock Mesa Road then continues 3.2 miles to the Flat Rock Field.
- b. Topographic Map "B" shows the point approximately 55 miles south of Ouray where the access road to the well departs from the Flat Rock Mesa Road. Beyond this point the access road consists of 0.7 mile of existing lease road leading to an existing well pad in the NENE of Section 29-R14E-R20E. Four miles of new road trending North will lead to a 4,110' access road for the Ute Tribal 6-16-14-20 location.

### 2. Planned Access Road: (refer to Topographic Map "D")

- a. Length of new road will be approximately 200 feet.
- b. The right-of-way width is 30' (15' on either side of the centerline) with a 20-foot wide running surface.
- c. Maximum grade will be less than 2%
- d. No turn-outs are planned.
- e. The new road will be crowned, ditched and dipped to provide adequate drainage.
- f. Culverts will be used if necessary.
- g. No gates are cattle guards will be needed. Nor will any existing facilities be modified.
- h. The proposed road was flagged when the location was staked.
- i. The authorized officer will be contacted at least 24 hours in advance of commencement of construction of the access road and well pad.

### 3. Location of Existing Wells:

a. The nearest producing well is the Flat Rock #3-29-14-20, located approximately 2.5 miles southwest of the proposed well location in Section 29-T14S-R20E.

### 4. Location of Existing and/or Proposed Facilities:

a. There are no existing facilities on the proposed well pad. All proposed facilities will be contained within the proposed location site (see attached "Location Layout"). Topographic Map "D" shows the proposed route for a gas line, to be co-located in the access road right-of-way, and connected to the Miller, Dyer & Co. LLC gathering system.

b. The operator will submit information concerning proposed on and off well pad facilities once production has been established by applying for approval of subsequent operations.

### 5. Location and Type of Water Supply:

- a. Miller, Dyer & Co. existing water supply well the Ute Tribal 30-4A, located in the NENW Section 30-T14S-R20E on Indian surface has been approved by the Ute Indian Tribe. The existing BIA water permit number for the well is #14-20-H62-5069.
- b. Some produced water from existing wells may be used for drilling. Fresh water may also be taken at a point of diversion at Santio Crossing from Willow Creek in the SESE Section 29-T12S-R21E, SLB&M, if available during the drought. This water will be taken under the terms of the Ute Oilfield Water Service's state filing.
- c. Water will be transported by truck on the Agency Draw and Flat rock Mesa roads.

### 6. Source of Construction Materials:

- a. It is anticipated that any construction materials will be needed for the drilling phase of this project. Gravel, shale or road base materials needed to upgrade access roads and well pad will be obtained from the operator's pit located on SITLA land near Chimney Rock.
- b. The entire well site and all access roads to be upgraded for built are located on lands held in trust by the federal government for the Ute Indian Tribe.
- c. All construction materials used in building the well pad and access road will be native materials accumulated during construction. In the event that additional materials are needed, they will be obtained from the operator's existing pit on SILTA land or from private sources.

### 7. Methods for Handling Waste Disposal:

- a. Methods and locations for safe containment and disposal of the following materials:
  - 1. Drill cuttings will be buried in the reserve pit.
  - 2. Garbage and trash will be contained in trash baskets and hauled to a sanitary landfill. There will be no burning of trash on the location at any time.
  - 3. Salts will be kept in proper containers and salvaged for future use or disposed of at an approved facility.
  - 4. Chemicals will be kept in proper containers and salvaged for future use or disposed of at an approved facility.
  - 5. Sewage waste will be contained in portable chemical toilets serviced by a commercial sanitary service.
- b. Drilling fluids will be contained in the reserve pit and mud tanks. To the extent possible, drilling fluids and water will be saved for use at future drilling locations. Unusable drilling fluids and water will be disposed of in an approved manner upon the completion of the well.

- c. No chemicals subject to reporting under SARA Title III (hazardous materials) in an amount greater that 10,000 pounds will be used, produced, stored, transported, or disposed of annually in association with the drilling, testing, of this well. Furthermore, extremely hazardous substances, as defined in 40 CFR 355, in threshold planning quantities, will not be used, produced, stored, transported, or disposed of in association with the drilling, testing, or completing of this well.
- d. Reserve pit and waste water disposal:
  - 1. The reserve pit will be constructed so as not to lead, break, or allow the discharge of fluids.
  - 2. The reserve pit will be lined with 12 mil plastic nylon reinforced liner installed over sufficient bedding material to cover any exposed rocks. The pit will be fenced on three sides with 39" net wire, topped with a minimum of one strand of barbed wire. All wire will be stretched prior to attachment to the corner posts. The fourth side will be fenced when drilling activities are completed to allow drying.
  - 3. The closure of the reserve pit will follow the Guidance for Reserve Pit Closure as found in the Environmental Handbook of the State of Utah, Division of Oil, Gas & Mining.
    - a) The reserve pit will be closed within one year following drilling and completion of a well (R649-16.3).
    - b) Liquid in a pit will be allowed to either evaporate or be removed. If removed, it will be disposed of properly, some options are injection (in this well or another), hauled to a permitted disposal facility, or re-used at another well.
    - c) The pit liner may be cut off above the cuttings/mud level and hauled to a landfill, or folded in and processed along with other pit contents and covered. No remnants of liner material will be exposed at the surface when pit closure is complete. Pit area will be mounded so as not to allow ponding of water and drainage diverted around as not to allow erosion of the old pit site.
  - 4. A closed drilling system will not be used as there is no irrigable land, floodplains, or lands under crop production.
  - 5. In accordance with Onshore Order No. 7, a permanent disposal method and location will be applied for within 90 days of establishing production.
  - 6. After first production:
    - a) Produced waste water will be confined to the reserve pit, or a storage tank for a period not to exceed 90 days.
    - b) During the 90 day period, in accordance with Onshore Order No. 7, an application for approval of a permanent disposal method and location, along with the required water analysis will be submitted to the authorized officer.

c) No produced water will be used for dust or weed control of any kind. Should spills of oil, produced water, or hazardous materials occur, the area of the spill will be re-mediated and contaminated soil and recovered oil or hazardous materials will be hauled to an approved disposal facility.

### 8. Ancillary Facilities:

a. No airstrips will be built. Mobile living quarters and office facilities for supervisors, geologists, mud engineers, mud loggers and air compressor personnel will be confined to the drilling location as shown on the "Location Layout" diagram. The drilling crew will be housed on location.

### 9. Well Site Layout:

- a. Refer to attached "Typical Cross Section" diagram for cuts and fills and relation to topography.
- b. Refer to "Location Layout" diagram for location of mud tanks, reserve and flare pits, pipe racks, living facilities and top soil stockpiles.
- c. Refer to "Location Layout" diagram for rig orientation, access road and parking area. Parking area will be in the northeast corner of the location.

### 10. Plans for Restoration of the Surface:

- a. Producing well location
  - 1. Immediately upon well completion the location and surrounding area will be cleared of all tubing, equipment, debris, materials, trash and junk not required for production.
  - 2. Immediately upon well completion any hydrocarbons on the reserve pit will be removed and disposed of properly.
  - 3. The reserve pit and that portion of the location not needed for production facilities/operations will be re-contoured to the approximate natural contours. The reserve pit will be reclaimed within 90 days of the date of well completion, or as soon thereafter as is practical. Before any dirt work takes place, the reserve pit must be completely dry and all cans, barrels, pipe, etc removed. The liner will be perforated and torn prior to backfilling.
  - 4. Access roads will be graded and maintained to prevent erosion and accommodate year-round traffic.
  - 5. All disturbed areas not needed for operations will be seeded with the mixture required by the BIA in the manner specified by the BIA.

### b. Dry Hole/Abandoned Location

1. At such time as it is determined that the well is to be plugged and abandoned, the operator will submit a subsequent report of abandonment to the BLM and the BIA. The BLM will attach plugging conditions of approval, and the BIA will attach conditions of approval for the restoration of the surface.

### 11. Surface Ownership:

a. Access roads and location are held in trust for the Ute Indian Tribe by the Unites States. The operator has obtained a right-of-way with the BIA and submitted payment for damages as specified in its Exploration and Development Agreement with the Ute Indian Tribe.

### 12. Additional Information:

- a. The operator will inform all persons in the area who are associated with this project that they will be subject to prosecution for knowingly disturbing historic or archaeological sites, or for collecting artifacts. If historic or archaeological materials are uncovered during construction, the operator will immediately stop work that might further disturb such materials, and will inform the assigned monitor and the authorized officer (AO) at the BIA. Within five working days the AO will inform the operator as to:
  - 1. Whether the materials appear to be eligible for the National Register of Historic Places;
  - 2. The mitigation measures the operator will likely have to undertake before the site can be used (assuming in situ preservation is not necessary); and
  - 3. A time frame for the AO to complete an expedited review under 36 CFR 900.11 to confirm, through the State Historic Preservation Officer, that the findings of the AO are correct and that mitigation is appropriate.
- b. If the operator wishes at any time to relocate activities to avoid the cost of mitigation and/or the delays associated with this process, the AO will assume responsibility for whatever recordation and stabilization of the exposed materials may be required. Otherwise, the operator will be responsible for mitigation costs. The AO will provide technical and procedural guidelines for the conduct of mitigation. Upon verification from the AO that required mitigation has been completed, the operator will be allowed to resume construction.
- c. At the request of the Ute Indian Tribe, a 30'-wide fire break will be bladed around the perimeter of the location.
- 13. Lessee's or Operator's Representative and Certification:
  - a. Jeff Lang, Vice President of Operations

Miller, Dyer & Co. LLC 475 17<sup>th</sup> Street, Suite 1200

Denver, CO 80202

Office: 303 292 0949 Ext 102


FAX: 303 292 3901 Cell: 303 503 3730

Email: <u>ieff@millerdyer.com</u>


I hereby certify that I have inspected the proposed drill site and access road; that I am familiar with the conditions which currently exist; that the statements made in this plan are true and correct to the best of my knowledge; and that the work associated with the operations proposed here will be performed by Miller, Dyer & Co. LLC, and its

contractors an subcontractors in conformity with the plan and the terms and conditions under which it is approved. This statement is subject to the provisions of 18 U.S.C. 1001 for the filing of a false statement.

<b>C</b>		
Please be advised that Miller, Dyer & Co. In Tribal #8-16-14-20 well; SENE of Section Uintah County, Utah; and is responsible for ands. Bond coverage is provided by Certife Bore Date	16, T14S-R20E and all proceed up the operations conducted up	ducing zones; pon the leased
The onsite inspection for this well was concentrated in the onsite inspection were:	lucted on	_, 2006
Kolby Kay, Timberline Land Surveying John E. Dyer, Miller, Dyer & Co. LLC		
Ute Indian Tribe		
Ute Indian Tribe		
(contractor)		
BIA rep		
State of Utah rep		
<del></del>		



Choke Manifold Requirement (3000 psi WP)



# Driving Directions MILLER, DYER & CO. LLC Ute Tribal 6-16-14-20 Section 16, T14S, R20E, S.L.B.&M.

PROCEED IN A WESTERLY DIRECTION FROM VERNAL, UTAH ALONG U.S. HIGHWAY 40 APPROXIMATELY 14 MILES TO THE JUNCTION OF STATE HIGHWAY 88. TURN LEFT AND PROCEED IN A SOUTHERLY DIRECTION ALONG STATE HIGHWAY 88 APPROXIMATELY 17 MILES TO OURAY, UTAH. FROM OURAY, PROCEED IN A SOUTHERLY DIRECTION ALONG THE SEEP RIDGE ROAD (COUNTY B ROAD 2810) APPROXIMATELY 29.4 MILES TO ITS INTERSECTION WITH THE BUCK CANYON ROAD (COUNTY B ROAD 5460). TURN RIGHT AND PROCEED IN A SOUTHWESTERLY DIRECTION ALONG COUNTY B ROAD 5460 APPROXIMATELY 3.2 MILES TO WILLOW CREEK. TURN RIGHT AND PROCEED IN A NORTHWESTERLY DIRECTION ALONG THE WILLOW CREEK ROAD (COUNTY B ROAD 5120) APPROXIMATELY 2.1 MILES TO ITS INTERSECTION WITH THE AGENCY DRAW ROAD (COUNTY B ROAD 5340). TURN LEFT AND PROCEED IN A WESTERLY THEN SOUTHWESTERLY DIRECTION ALONG COUNTY B ROAD 5340 APPROXIMATELY 2.5 MILES TO ITS INTERSECTION WITH THE FLAT ROCK ROAD (COUNTY B ROAD 5450). TURN LEFT AND PROCEED IN A SOUTHERLY DIRECTION ALONG COUNTY B ROAD 5450 APPROXIMATELY 10.9 MILES TO THE FLAT ROCK MESA ROAD. PROCEED IN A SOUTHWESTERLY DIRECTION ALONG THE FLAT ROCK MESA ROAD APPROXIMATELY 2.8 MILES TO ITS INTERSECTION WITH THE BLACK KNOLLS ROAD. CONTINUE IN A WESTERLY THEN NORTHWESTERLY DIRECTION ALONG THE FLAT ROCK MESA ROAD APPROXIMATELY 2.9 MILES TO THE NORTH FORK OF THE FLAT ROCK MESA ROAD. TURN RIGHT AND PROCEED IN A NORTHERLY DIRECTION ALONG THE NORTH FORK OF THE FLAT ROCK MESA ROAD APPROXIMATELY 0.3 MILES TO A SERVICE ROAD. TURN RIGHT AND PROCEED IN AN EASTERLY DIRECTION ALONG THE SERVICE ROAD APPROXIMATELY 0.7 MILES TO AN EXISTING WELL PAD. PROCEED IN A SOUTHEASTERLY DIRECTION ACROSS THE WELL PAD APPROXIMATELY 350 FEET TO THE PROPOSED ACCESS ROAD FOR THE 8-16-14-20 WELL. FOLLOW ROAD FLAGS IN AN EASTERLY THEN NORTHERLY DIRECTION APPROXIMATELY 4.0 MILES TO THE PROPOSED ACCESS ROAD. FOLLOW ROAD FLAGS IN A SOUTHWESTERLY DIRECTION APPROXIMATELY 4,110 FEET TO THE PROPOSED LOCATION.

TOTAL DISTANCE FROM VERNAL, UTAH TO THE PROPOSED WELL LOCATION IS APPROXIMATELY 90.6 MILES IN A SOUTHERLY DIRECTION.




PHOTO VIEW: FROM CORNER #5 TO LOCATION STAKE

CAMERA ANGLE: NORTHEASTERLY




PHOTO VIEW: FROM BEGINNING OF PROPOSED ROAD

CAMERA ANGLE: SOUTHWESTERLY

### MILLER, DYER & CO. LLC

Ute Tribal 6-16-14-20 SECTION 16, T14S, R20E, S.L.B.&M. 1846' FNL & 2065' FWL

LOCATION	PHOTOS

DATE TAKEN: 07-17-06 DATE DRAWN: 07-20-06 REVISED:


TAKEN BY: M.S.B.


DRAWN BY: M.W.W.


SHEET

Timberline Land Surveying, Inc.
38 West 100 North Vernal, Utah 84078
(435) 789-1365


1 OF 10










# MILLER, DYER & CO. LLC TYPICAL PRODUCTION LAYOUT UTE TRIBAL 6-16-14-20 Dump Lines Separator, Dehydrator & Meter 2 300 bbl Tanks & Berm Insulated 2" Flow line ● WELL HEAD PIT AREA ACCESS Section 16, T14S, R20E, S.L.B.&M. Qtr/Qtr Location: SE NW Footage Location: 1846' FNL & 2065' FWL Date Surveyed: 07-17-06 Date Drawn: 07-20-06 Timberline (435) 789-1365 Land Surveying, Inc. 38 WEST 100 NORTH VERNAL, UTAH 84078 Date Last Revision: SHEET 6 Surveyed By: M.S.B.. Drawn By: M.W.W. Scale: 1" = 50'**OF 10**










APD RECEIVED: 08/24/2006		API NO. ASSI	GNED: 43-04	7-38506	
WELL NAME: UTE TRIBAL 6-16-14-20					
OPERATOR: MILLER, DYER & CO, LLC ( N2580 )		PHONE NUMBER: 303-292-0949			
CONTACT: JEFF LANG					
PROPOSED LOCATION: SENW 16 140S 200E		INSPECT LOCATN BY: / /			
SURFACE: 1846 FNL 2065 FWL		Tech Review	Initials	Date	
BOTTOM: 1846 FNL 2065 FWL		Engineering	DKO	10/20/06	
COUNTY: UINTAH  LATITUDE: 39.60154 LONGITUDE: -109.6845  UTM SURF EASTINGS: 612948 NORTHINGS: 4384151		Geology			
		Surface			
LEASE TYPE: 3 - State  LEASE NUMBER: ML-47502  SURFACE OWNER: 2 - Indian	100777	PROPOSED FORMA COALBED METHAN		₹D	
Plat    Dond: Fed[] Ind[] Sta[] Fee[]   (No. RLB0008085	LOCATION AND SITING:  R649-2-3.  Unit:  R649-3-2. General Siting: 460 From Qtr/Qtr & 920' Between Wells  R649-3-3. Exception  Drilling Unit Board Cause No: Eff Date: Siting:  R649-3-11. Directional Drill				
STIPULATIONS:  1- Coin Stip  2- Spain & Stip  3- STATEMENT					



## WORKSHEET APPLICATION FOR PERMIT TO DRILL

APD RECEIVED: 08/24/2006	API NO. ASSIGNED: 43-047-38506		
WELL NAME: UTE TRIBAL 6-16-14-20			
OPERATOR: MILLER, DYER & CO, LLC ( N2580 )	PHONE NUMBER: 303-292-0949		
CONTACT: JEFF LANG			
PROPOSED LOCATION:	INSPECT LOCATN BY: / /		
SENW 16 140S 200E	Tech Review Initials Date		
SURFACE: 1846 FNL 2065 FWL BOTTOM: 2450 FNL 1660 FWL	Engineering		
COUNTY: UINTAH	Geology		
LATITUDE: 39.60154 LONGITUDE: -109.6845  UTM SURF EASTINGS: 612948 NORTHINGS: 43841	Surface		
FIELD NAME: WILDCAT ( 1			
LEASE TYPE: 3 - State  LEASE NUMBER: ML-47502  SURFACE OWNER: 2 - Indian	PROPOSED FORMATION: WINGT COALBED METHANE WELL? NO		
Plat Bond: Fed[] Ind[] Sta[] Fee[] (No. RLB0008085 ) Potash (Y/N) Oil Shale 190-5 (B) or 190-3 or 190-13 Water Permit (No. SEE FILE ) RDCC Review (Y/N) (Date: 09/15/2006 ) Fee Surf Agreement (Y/N) Intent to Commingle (Y/N)	LOCATION AND SITING:  R649-2-3.  Unit: R649-3-2. General		
COMMENTS:STIPULATIONS:			

T14S R20E

UTE TRIBAL 6-16-14-20 @

UTE TRIBAL 8-16-14-20 €

> UTE TRIBAL 16-16-14-20 ®

OPERATOR: MILLER, DYER & CO (N2580)

SEC: 16 T.14S R. 20E

FIELD: WILDCAT (001)

**COUNTY: UINTAH** 

SPACING: R649-3-11 / DIRECTIONAL DRILLING

Field Status

ABANDONED

ACTIVE

COMBINED

INACTIVE

PROPOSED

STORAGE

TERMINATED

Unit Status

EXPLORATORY
GAS STORAGE
NF PP OIL
NF SECONDARY
PENDING
PI OIL
PP GAS

PI OIL
PP GAS
PP GEOTHERML
PP OIL
SECONDARY
TERMINATED

Wells Status

GAS INJECTION

GAS STORAGE

LOCATION ABANDONED

NEW LOCATION

PRODUCING GAS
PRODUCING OIL

SHUT-IN GAS
SHUT-IN OIL
TEMP. ABANDONED

TEST WELL

WATER INJECTION


WATER SUPPLY
WATER DISPOSAL
DRILLING



nan Oli Gas and Milling



PREPARED BY: DIANA MASON DATE: 26-JUNE-2007



Utah Division of Oil, Gas and Mining 10/23/2006

Page 1

APD No

API WellNo

Status

Well Type GW

Surf Ownr I

**CBM** 

No

136

43-047-38506-00-00

**Surface Owner-APD** 

MILLER, DYER & CO, LLC

Unit

Well Name UTE TRIBAL 6-16-14-20 Field

Type of Work

Location

WILDCAT SENW 16 14S 20E S 0 FL 0 FL

GPS Coord (UTM) 612948E 4384151N

#### Geologic Statement of Basis

Miller, Dyer & Co. proposes to set 500 feet of surface casing and 5,000 feet of production casing, both cemented to the surface. A search of Division of Water Rights records shows no water wells within a 10,000 foot radius of the center of Section 16. The base of the moderately saline water is estimated at 2,600 feet. The surface formation at the proposed location is the Green River Formation. The Green River Formation is made up of interbedded sandstones, limestones and shales. Fresh water can be expected to be found in the upper Green River. The proposed casing and cementing program should cover the entire Green River section and adequately protect the Green River aquifer.

**Brad Hill** 

10/23/2006

**APD Evaluator** 

Date / Time

#### **Surface Statement of Basis**

The Ute Indian Tribe is the surface owner at this location. The operator is responsible for obtaining any needed permits or rights of way before causing any surface disturbance or drilling.

Brad Hill

10/23/2006

**Onsite Evaluator** 

Date / Time

#### Conditions of Approval / Application for Permit to Drill

Category

Condition

None

### STATE ACTIONS

## **Resource Development Coordinating Committee Public Lands Policy Coordination Office**

## 5110 State Office Building

SLC, UT 84114

Phone No. 53	7-9230
1. State Agency	2. Approximate date project will start:
Oil, Gas and Mining	
1594 West North Temple, Suite 1210	Upon Approval or September 14, 2006
Salt Lake City, UT 84114-5801	
3. Title of proposed action:	
Application for Permit to Drill	
4. Description of Project:	
Miller, Dyer & Co., LLC proposes to drill the Ute lease ML-47502, Uintah County, Utah. This action is of resource issues affecting state interests. The Divis administrative agency in this action and must issue ag	s being presented to the RDCC for consideration ion of Oil, Gas and Mining is the primary
5. Location and detailed map of land affected (site loc	ation map required, electronic GIS map
preferred)	
(include UTM coordinates where possible) (indicate c	* *
1846' FNL 2065' FWL, SE/4	•
Section 16, Township 14 South, Range	20 East, Uintah County, Utah
6. Possible significant impacts likely to occur:  Surface impacts include up to five acres of surface phase (estimated for five weeks duration). If oil and a location will be reclaimed back to a net disturbance or road, pipeline, or utility infrastructure. If no oil or gar reclaimed.	gas in commercial quantities is discovered, the f between one and two acres – not including
7. Identify local government affected	
a. Has the government been contacted? No.	
b. When?	
c. What was the response?	
d. If no response, how is the local government(s) l	ikely to be impacted?
8. For acquisitions of land or interests in land by DW representative and state senator for the project area. representative, state senator near project site, if appli a. Has the representative and senator been contact	Name and phone number of state cable:
9. Areawide clearinghouse(s) receiving state action: Uintah Basin Association of Governments	(to be sent out by agency in block 1)
10. For further information, contact:	11. Signature and title of authorized officer
Diana Whitney Phone: (801) 538-5312	Gil Hunt, Associate Director  Date: August 31, 2006

#### FORM 3

# STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING

AMENDED REPORT	Г
	_
(highlight changes)	

APPLICATION FOR PERMIT TO DRILL					5. MINER	RAL LEASE NO: 7502	6. SURFACE: Indian				
1A. TYPE OF WO	DRK: D	RILL 🔽	REENTER [		DEEPEN					IAN, ALLOTTEE OR ndian Tribe	TRIBE NAME:
B. TYPE OF WE	LL: OIL 🗌	gas 🗹	OTHER		SIN	IGLE ZONE [		√E ☑		or CA AGREEMENT !	VAME:
2. NAME OF OPE		<u> </u>							9. WELL	NAME and NUMBER	
Miller, Dye		<u>ن</u>					PHONE NUMBER:			Tribal 6-16-14 D AND POOL, OR WI	
475 17th S		CILI	ver s	TATE C	O ZIP 80	202	(303) 292-0949		Wilde		
	1846 FNL	Í							MERI		
	PRODUCING ZO								SEN	N 16 148	S 20E S
14. DISTANCE IN	MILES AND DIRE	ECTION FROM NI	EAREST TOWN OR F	POST OF	FICE:		****		12. COU	NTY:	13. STATE:
See Topo	Мар "А" (л	Attached)							Uinta	ah	UTAH
	NEAREST PROF	PERTY OR LEAS	E LINE (FEET)		16. NUMBER O	F ACRES IN LEA		17. N	UMBER OF	ACRES ASSIGNED	
1846	O NEAREST WELL	/DBILLING COL	ADI ETED. OR	_	19. PROPOSEI	) DEDTU	1280	20.0	OND DESC	PIRTION	40
	R) ON THIS LEASE		WELETED, OR		19. PROPUSEL	J DEFIN.	5,000	1	LB0008		
	(SHOW WHETHE	R DF, RT, GR, E	TC.):		22. APPROXIM	ATE DATE WOR	·			DURATION:	
6838 GR					10/1/200	06		3 '	Weeks		
				<u> </u>							
24.						ND CEMEN	ITING PROGRAM				
SIZE OF HOLE			EIGHT PER FOOT	SET	TING DEPTH	Ot a said a said			•	ID SLURRY WEIGHT	
12-1/4"	9-5/8"	J-55	36#			Standard			sacks	1.18	
8-3/4"	5-1/2"	J-55	15.5#		5,000	Hi-Fill & F	Poz Prem	976	sacks	3.84 & 1.25	11 & 14.35
25.					ATTA	CHMENTS					
VERIFY THE FOL	LOWING ARE AT	TACHED IN ACC	ORDANCE WITH THI	E UTAH (	OIL AND GAS C	ONSERVATION	GENERAL RULES:				
<b>✓</b> WELL PL	AT OR MAP PREE	PARED BY LICEN	SED SURVEYOR OR	FNGIN	=EP	<b> </b>   <b> </b>	OMPLETE DRILLING PLAN				
_			S APPROVAL FOR U					-DOON (	D 0014D4	ABY OTHER THAN T	IE LEADE OWNED
	E OF BIVISION O	F WATER RIGHT	S AFFROVAL FOR C	03E OF 1	VALER		DRM 5, IF OPERATOR IS PI	ERSON	JR COMPA	NT OTHER THAN IF	IE LEASE OWNER
	low I	than	<del></del>		·		⊾ Vice Presiden	t of C	\noratio	.na	
NAME (PLEASE	PRINT) Jen La	7 -	4			TITL	Vice Presiden	COIC	perauc	) 15	
SIGNATURE		1 1				DAT	E 10 11 C	٠.			
(This space for Sta	te use enly)	1				oproved tah Divis					
					-	Gas and					
API NUMBER AS	SIGNED:	13-047.	35506		_	APPROVAL			REC	EIVED	
	Ĕ.				Date: _	0-23-	0611		OCT	1 3 2006	
(11/2001)	Aci	deral Appro Non is Nece	val of this esary		By:	ons on Reverse S	b) GHW	DIV.	OF OIL,	GAS & MININ	G

#### MILLER, DYER & CO. LLC T14S, R20E, S.L.B.&M. Found Set Marked Stone. Found Set Pile of stones. Marked Stone. WELL LOCATION, UTE TRIBAL 6-16-14-20, S89'55'W - 79.60 (G.L.O.) Pile of stones. LOCATED AS SHOWN IN THE SE 1/4 NW 1/4 N89'46'47"W - 5216.85' (Meas.) 1/4 Corner OF SECTION 16, T14S, R20E, S.L.B.&M. is missing UINTAH COUNTY, UTAH. of Bearings) 1846' N00'39'29"E 2065 SCALE Proposed (Computed) (G.L.O.) NOTES: 1. Well footages are measured at right Found Set angles to the Section Lines. Marked Stone. W.50.0N Pile of stones. 2. Bearings are based on Global Positioning 6 Satellite observations. 3. The proposed well bears S47'58'40"E 2768.82' from the Northwest Corner of (Meas.) **WELL LOCATION:** Section 16. UTE TRIBAL 6-16-14-20 ELEV. UNGRADED GROUND = 6837.7THIS IS TO CERTIFY THAT THE ABOVE PLAT WAS PREPARED FROM FIELD NOTES OF ACTUAL SURVEYS MADE BY ME OR UNDER WOOD SUMMER OF AND THAT THE SAME ARE TRUE AND CORRECT TO THE BEST OF MY KNOWLEDGE AND BELIEF. 9 N00'54'10"E S89\*51'W - 79.70 (G.L.O.) Found Set TIMBERLINE LAND SURVEYING, INC. Marked Stone, 38 WEST 100 NORTH. - VERNAL, UTAH 84078 Pile of stones. (435) 789-1365UTE TRIBAL 6-16-14-20 = SECTION CORNERS LOCATED DATE SURVEYED: (Proposed Well Head) SURVEYED BY: K.R.K. BASIS OF ELEVATION IS BENCH MARK 60 WF 1952 07-17-06 NAD 83 Autonomous LOCATED IN THE SW 1/4 OF SECTION 35, T14S, DATE DRAWN: LATITUDE = $39^{\circ} 36' 05.29''$ DRAWN BY: M.W.W. R20E, S.L.B.&M. THE ELEVATION OF THIS BENCH 07-20-06 LONGITUDE = $109^{\circ}$ 41' 06.37' MARK IS SHOWN ON THE FLAT ROCK MESA 7.5 MIN. Date Last Revised: SCALE: 1'' = 1000'QUADRANGLE AS BEING 7363'.

SHEET

OF 10

### 4. Casing Program

	Setting Depth	Hole Size	Casing O.D.	Grade	Weight/Ft.	Thread
Conductor	40'	20"	16"	Conductor	0.250" wall	
Surface	0' - 500'	12-1/4"	9-5/8"	J-55	36#	STC
Production	0'- 5,000'	8-3/4"	5-1/2"	J-55	15.5#	STC

• Subject to review on the basis of actual conditions encountered. Production casing depth will be adjusted based on results.

### **Cement Program**

## Conductor Casing: 0'-40'

Ready Mix to surface

## Surface Casing: 0' - 500'

#### Cement:

0'-500'

15.6 ppg Standard Type V

2% CaCl2

1/4 #/sk cello flake

Cement yield = 1.18 ft3/sk w/ 5 gal/sk water

Annular volume = 500' \* 0.3132 ft3/ft = 156.6 ft3

Excess = 105% (Assumes 18% washout or 14.5" hole diameter)

Total volume w/ excess = 156.6 ft 3 \* 2.05 = 321.0 ft 3

**Cement Requirement** = 321.0 ft 3 / 1.18 ft 3/sk = 272 sks

#### Production Casing: 0'-5,000'

#### Lead Cement:

0'-2500'

11.0 ppg Halliburton Hi-Fill (or equivalent)

16% Bentonite (light weight additive)

0.75% Econolite (light weight additive)

10 #/sk gilsonite (lost circulation additive)

0.25 #/sk Flocele (lost circulation additive)

3% salt

1% HR-7 (retarder)

Cement yield = 3.84 ft3/sk w/ 23 gal/sk water

Volume inside surface casing = 500' \* 0.2691 ft3/ft = 134.6 ft3

Excess = 0%

Annular volume = 2000' \* 0.2526 ft<sup>3</sup>/ft = 505.2 ft<sup>3</sup>

Excess = 35%

Annular volume w/ excess = 505.2 ft3 \* 1.35 = 682.0 ft3

Total volume = 134.6 + 682.0 = 816.6 ft3

Lead Cement Requirement = 816.6 ft 3 / 3.84 ft 3/sk = 213 sks

#### Tail Cement:

2500'-5000' plus shoe joint

14.35 ppg 50/50 Poz Premium

0.6% Halad® - 322 (Low Fluid Loss Control)

2% Microbond M (Cement Material)

5% Salt

1/4 #/sk Flocele (Loct Circulation Additive)

0.2% HR-5 (Retarder)

Cement yield = 1.25 ft3/sk w/ 5.46 gal/sk water

Annular volume = 2500' \* 0.2526 ft3/ft = 631.5 ft3

Excess = 50%

Total annular volume w/ excess = 631.5 ft3 \* 1.50 = 947.3 ft3

Shoe volume = 45' \* 0.1336 ft 3/ft = 6.0 ft 3

Excess (shoe) = 0%

Total volume w/ excess (incl. shoe) = 947.3 + 6.0 = 953.3 ft3

Tail Cement Requirement = 953.3 ft3 / 1.25 ft3/sk = 763 sks

#### Displacement Volume:

4955' \* 0.0238 bbl/ft = 117.9 bbls

## 5. <u>Mud Program</u> (visual monitoring)

Interval	Mud Type	Weight	Viscosity	Fluid Loss
0'- 2,400'	Water/Gel/Lime/Native Clays	8.3-8.6 ppg	33-36 sec/qt	N/C
2,400'- 5000'	KCl/Polymer or DAP/Polymer	9.0-9.3 ppg	38-42 sec/qt	8-10cc

Sufficient mud materials to maintain mud properties, control lost circulation, contain a "gas" kick, and rebuild an active mud system will be available on location during drilling operations.

#### 6. Testing, Logging, Coring

- a. Drill stem tests non anticipated
- b. Electric logs DIL/SP/GR, FDC/CNL/CAL/PE/GR, both from TD to surface



## State of Utah

## Department of Natural Resources

MICHAEL R. STYLER Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA Division Director JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

October 23, 2006

Miller, Dyer & Co., LLC 475 17th St., Ste. 1200 Denver, CO 80202

Re:

<u>Ute Tribal 6-16-14-20 Well, 1846' FNL, 2065' FWL, SE NW, Sec. 16, T. 14 South, R. 20 East, Uintah County, Utah</u>

#### Gentlemen:

Pursuant to the provisions and requirements of Utah Code Ann.§ 40-6-1 et seq., Utah Administrative Code R649-3-1 et seq., and the attached Conditions of Approval, approval to drill the referenced well is granted.

This approval shall expire one year from the above date unless substantial and continuous operation is underway, or a request for extension is made prior to the expiration date. The API identification number assigned to this well is 43-047-38506.

Sincerely,

Gil Hunt

Associate Director

pab Enclosures

cc:

**Uintah County Assessor** 

SITLA

<b>Operator:</b>	Miller, Dyer & Co., LLC	
Well Name & Number	Ute Tribal 6-16-14-20	
API Number:	43-047-38506	
Lease:	ML-47502	
<u>-</u>		

Location: SE NW

Sec. 16

**T.** 14 South

**R.** 20 East

#### **Conditions of Approval**

#### 1. General

Compliance with the requirements of Utah Admin. R. 649-1 *et seq.*, the Oil and Gas Conservation General Rules, and the applicable terms and provisions of the approved Application for Permit to Drill.

#### 2. Notification Requirements

The operator is required to notify the Division of Oil, Gas and Mining of the following actions during drilling of this well:

- 24 hours prior to cementing or testing casing
- 24 hours prior to testing blowout prevention equipment
- 24 hours prior to spudding the well
- within 24 hours of any emergency changes made to the approved drilling program
- prior to commencing operations to plug and abandon the well

The following are Division of Oil, Gas and Mining contacts and their work telephone numbers (please leave a voice mail message if the person is not available to take the call):

- Dan Jarvis at (801) 538-5338
- Carol Daniels at (801) 538-5284 (spud)

## 3. Reporting Requirements

All required reports, forms and submittals will be promptly filed with the Division, including but not limited to the Entity Action Form (Form 6), Report of Water Encountered During Drilling (Form 7), Weekly Progress Reports for drilling and completion operations, and Sundry Notices and Reports on Wells requesting approval of change of plans or other operational actions.

- 4. Compliance with the State of Utah Antiquities Act forbids disturbance of archeological, historical, or paleontological remains. Should archeological, historical or paleontological remains be encountered during your operations, you are required to immediately suspend all operations and immediately inform the Trust Lands Administration and the Division of State History of the discovery of such remains.
- 5. State approval of this well does not supersede the required federal approval, which must be obtained prior to drilling.

Page 2 43-047-38506 October 23, 2006

- 6. This proposed well is located in an area for which drilling units (well spacing patterns) have not been established through an order of the Board of Oil, Gas and Mining (the "Board"). In order to avoid the possibility of waste or injury to correlative rights, the operator is requested, once the well has been drilled, completed, and has produced, to analyze geological and engineering data generated therefrom, as well as any similar data from surrounding areas if available. As soon as is practicable after completion of its analysis, and if the analysis suggests an area larger than the quarter-quarter section upon which the well is located is being drained, the operator is requested to seek an appropriate order from the Board establishing drilling and spacing units in conformance with such analysis by filing a Request for Agency Action with the Board.
- 7. Compliance with the Conditions of Approval/Application for Permit to Drill outlined in the Statement of Basis. (Copy Attached)
- 8. Operator shall comply with applicable recommendations resulting from Resource Development Coordinating Committee review. Statements attached.

STATE OF UTAH	FORM 9
DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING	5. LEASE DESIGNATION AND SERIAL NUMBER: ML-47502
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME:
Do not use this form for proposals to drill new wells, significantly deepen existing wells below current bottom-hole depth, reenter	7. UNIT or CA AGREEMENT NAME:
drill horizontal laterals. Use APPLICATION FOR PERMIT TO DRILL form for such proposals.	8. WELL NAME and NUMBER:
1. TYPE OF WELL OIL WELL GAS WELL OTHER	Ute Tribal #6-16-14-20
2. NAME OF OPERATOR: Miller, Dyer & Co. LLC	9. API NUMBER: 4304738506
3. ADDRESS OF OPERATOR: PHONE N	UMBER: 10. FIELD AND POOL, OR WILDCAT:
475 17th Street, Ste 1200 CITY Denver STATE CO ZIP 80202 (303)	292-0949
4. LOCATION OF WELL FOOTAGES AT SURFACE: 1846 FNL 2065 FWL	соинту: Uintah
051111 40 440 005	
QTR/QTR, SECTION, TOWNSHIP, RANGE, MERIDIAN: SENW 16 14S 20E	STATE: UTAH
11. CHECK APPROPRIATE BOXES TO INDICATE NATURE OF NO	TICE, REPORT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF	ACTION
NOTICE OF INTENT	REPERFORATE CURRENT FORMATION
(Submit in Duplicate) ALTER CASING FRACTURE TREAT	SIDETRACK TO REPAIR WELL
Approximate date work will start: CASING REPAIR NEW CONSTRUCTION	TEMPORARILY ABANDON
CHANGE TO PREVIOUS PLANS OPERATOR CHANGE	TUBING REPAIR
CHANGE TUBING PLUG AND ABANDON	VENT OR FLARE
SUBSEQUENT REPORT CHANGE WELL NAME PLUG BACK	WATER DISPOSAL
(Submit Original Form Only)  CHANGE WELL STATUS  PRODUCTION (START)	(RESUME) WATER SHUT-OFF
Date of work completion:  COMMINGLE PRODUCING FORMATIONS RECLAMATION OF W	ELL SITE OTHER:
CONVERT WELL TYPE RECOMPLETE - DIFFI	RENT FORMATION
Miller, Dyer & Co. LLC now plans to drill the subject well to a total depth of 12 originally permitted as a 5,000' Wasatch test. Revised engineering plans and enclosed. Miller, Dyer & Co. LLC requests that all well information remain confidential.	400' to test the Wingate formation. The well was
\( \text{\text{\$\sigma}} \)	o Procident of Operations
NAME (PLEASE PRINT) PEFFOR H. Lang.	e President of Operations
SIGNATURE DATE 3/2	3/2007
SIGNATURE CTATE	

(This space for State use only)

OF UTAH DIVISION OF OIL, GAS, AND MINING DATE: 8/30/07

RECEIVED MAR 2 6 2007

## DRILLING PLAN MILLER, DYER & CO. LLC

### UTE TRIBAL #6-16-14-20 SENW Section 16 T14S-R20E

#### 1. Estimated Formation Tops

Estimated Formation Tops:	<u>MD</u>	
Green River	Surface	
Wasatch	3,426"	Oil and/or gas anticipated >
		3,000'
Mesaverde	4,574'	Gas
Castlegate Sandstone	6,468'	Gas
Mancos Shale	6,752'	Gas
Dakota Sandstone	10,625'	Gas
Cedar Mountain	10,688'	Gas
Morrison	10,914'	Gas
Curtis	11,441'	Gas
Entrada Sandstone	11,520'	Gas
Carmel	11,874'	Gas
Wingate	11,994'	Gas
TD	12,400'	

#### 2. Pressure Control Equipment

Schematic attached (Diagram "A")

Blow Out Preventer (BOP) will be equipped as follows:

- A. Type: Eleven (11) inch double gate hydraulic 3,000 psi BOP plus a 3000 psi annular preventer mounted on a 3,000 psi casinghead.
  - a. One set of blind rams (above)
  - b. One set of pipe rams (below)
  - c. Appropriate fill, kill and choke lines will be 3,000 psi working pressure

Note: The calculation of maximum anticipated surface pressure is detailed in Section 7. This calculation is based on the maximum anticipated bottom-hole pressure and a partially evacuated hole. According to this calculation, a 3000 psi BOP and annular preventer will be sufficient to drill this well safely. However, depending on the actual rig contracted for this well, a 5000 psi system may come with the rig. If so, all testing will be done to 5000 psi specifications.

#### B. Auxiliary Equipment:

Auxiliary equipment to include upper Kelly cock with a handle, a floor safety valve with subs to fit all drill string connections in use, and a string float valve.

C. Pressure Rating: 3,000 psi WP

D. Testing Procedure:

#### **Hydraulic Ram-Type BOP**

At a minimum, the BOP, choke manifold, and related equipment will be pressure tested to the approved working pressure of the BOP stack of 3,000 psi. This pressure will be maintained for a period of at least ten (10) minutes or until the requirements of the test are met, whichever is longer.

At a minimum, the above pressure test will be performed:

- 1) when the BOP is initially installed,
- 2) whenever any seal subject to test pressure is broken,
- 3) following related repairs, and
- 4) at thirty (30) day intervals.

In addition to the above, the pipe and blind rams will be activated each trip, but no more than once each day.

#### E. Choke Manifold Equipment:

All choke lines will be straight lines; turns will use tee blocks, or targeted running tees, and will be anchored to prevent whip and vibration. The manifold will have two (2) manual chokes and a pressure gauge.

#### F. Accumulator:

The accumulator will have sufficient capacity to open the hydraulically controlled choke line valve, if so equipped, close all rams plus the annular BOP, and retain a minimum of 200 psi above precharge on the closing manifold without the use of the closing unit pumps. The fluid reservoir capacity will be double the usable fluid volume of the accumulator system capacity, and the fluid level of the reservoir will be maintained to the manufacturer's recommendations.

#### G. Miscellaneous Information:

The choke manifold and BOP ram extensions rods with hand wheels will be located outside the rig substructure. The hydraulic BOP closing unit will be located at least 25 feet from the well head, but readily accessible to the driller. Exact location and configuration of the hydraulic BOP closing unit will depend on the layout of the particular rig contracted to drill this well.

A flare line will be installed from the choke manifold to a flare pit, extending a minimum of 100 feet from the center of the drill hole.

The BOP and related pressure control equipment will be installed, tested and maintained in compliance with the specifications and requirements of the Onshore Oil and Gas Order Number 2.

## 3. Auxiliary Equipment

- a. Kelly cock Yes
- b. Float sub at bit No
- c. Mud logger & instrumentation Yes
- d. Full-opening safety valve on rig floor Yes
- e. Rotating head No

## 4. <u>Casing Program</u>

	Setting Depth	Hole Size	Casing O.D.	Grade	Weight/Ft.	Thread
Conductor	40'	26"	20"	Conductor	0.250" wall	
Surface	3,200	12-1/4"	9-5/8"	J-55	36#	LTC
Production	0'-1,750	8-3/4"	5-1/2"	N-80	17#	Buttress
	1,750'- 10,400'	8-3/4"	5-1/2"	N-80	17#	LTC
	10,400'- 12,400'	8-3/4"	5-1/2"	P-110	17#	LTC

 Subject to review on the basis of actual conditions encountered. Production casing depth will be adjusted based on results.

## **Cement Program**

Conductor Casing: 0'-40'

Ready Mix to surface

Surface Casing: 0' - 3200'

Lead Cement: 0'-2700' 11.0 ppg Premium Lite II cement 10% bwoc Bentonite 0.5% bwoc Sodium Metasilicate 5 #/sk Kol Seal 0.25 #/sk Cello Flake

```
3% bwow Potassium Chloride
```

Cement yield = 3.38 ft3/sk w/ 20.5 gal/sk water

Annular volume (in open hole) = 2660' \* 0.3132 ft3/ft = 833.1 ft3

Excess = 75%

Total volume (open hole) w/ excess = 833.1 ft3 \* 1.75 = 1457.9 ft3

Annular volume (in conductor) = 40' \* 1.5687 ft 3/ft = 62.7 ft 3

Excess = 0%

Total volume (open hole & conductor) = 1521 ft3

## Lead Cement Requirement = 1521 ft3 / 3.38 ft3/sk = 450 sks

#### Tail Cement:

2700'-3200' plus shoe joint

15.8 ppg Class G

2% bwoc Calcium Chloride

0.25 #/sk Cello Flake

Cement yield = 1.17 ft3/sk w/ 5 gal/sk water

Annular volume (in open hole) = 500' \* 0.3132 ft3/ft = 156.6 ft3

Excess = 75%

Total volume (open hole) w/ excess = 156.6 ft 3 \* 1.75 = 274.1 ft 3

Shoe volume = 40' \* 0.4341 ft 3/ft = 17.4 ft 3

Excess (shoe) = 0%

Total volume (open hole & shoe) = 313.2 + 19.5 = 291 ft3

## Tail Cement Requirement = 291 ft3 / 1.17 ft3/sk = 249 sks

### Displacement Volume:

3160' \* 0.0773 bbl/ft = 244.3 bbls

#### Top Out Cement:

0-200' (displaced down backside w/ 1" string)

15.8 ppg Class G

2% bwoc Calcium Chloride

0.25 #/sk Cello Flake

Cement yield = 1.17 ft3/sk w/ 5 gal/sk water

Annular volume = 200' \* 0.3132 ft3/ft = 62.6 ft3

Excess = 100%

Total volume w/ excess = 62.6 ft 3 \* 2.0 = 125.2 ft 3

Top Out Cement Requirement = 125.2 ft3 / 1.17 ft3/sk = 107 sks

#### **Production Casing: 0'-12,400'** (DV Tool @ 10,000')

#### Stage 1

#### Cement:

10,000'-12,400'

13.0 ppg Premium Lite II High Strength cement (or equivalent)

0.05 #/sk Static Free

0.8% bwoc R-3

```
3% bwow Potassium Chloride
        0.25 #/sk Cello Flake
        0.9% bwoc FL-25
         1 gal / 100 sk FP-6L
        0.25% bwoc Silica Flour
        0.2% bwoc BA-59
        Cement yield = 2.34 ft3/sk w/ 11.85 gal/sk water
        Annular volume = 2400' * 0.2526 ft3/ft = 606.2 ft3
        Excess = 25\%
        Total volume w/ excess = 606.2 \text{ ft} 3 * 1.25 = 757.8 \text{ ft} 3
        Shoe volume = 40^{\circ} * 0.1305 \text{ ft} 3/\text{ft} = 5.2 \text{ ft} 3
        Excess (shoe) = 0\%
        Total volume w/ excess (incl. shoe) = 757.8 + 5.2 = 763 ft3
        Stage 1 Cement Requirement = 763 \text{ ft} 3 / 2.34 \text{ ft} 3/\text{sk} = 326 \text{ sks}
Displacement Volume:
        (12,400'-40') * 0.0232 \text{ bbl/ft} = 286.8 \text{ bbls}
Stage 2 (DV tool to 500' inside surface casing)
Lead Cement:
        2,700'-9,384'
        11.2 ppg Premium Lite II cement (or equivalent)
        3 #/sk CSE
        0.3% bwoc R-3
        3% bwow Potassium Chloride
        10% bwoc Bentonite
        0.2% bwoc Sodium Metasilicate
        Cement yield = 3.15 ft3/sk w/ 19 gal/sk water
        Volume inside surface casing = 500' * 0.2691 ft3/ft = 134.6 ft3
        Excess = 0\%
        Annular volume = 6184' * 0.2526 ft3/ft = 1562.1 ft3
        Excess = 25\%
        Annular volume w/ excess = 1562.1 \text{ ft}3 * 1.25 = 1952.6 \text{ ft}3
        Total volume = 134.6 + 1952.6 = 2087 ft3
        Lead Cement Requirement = 2087 \text{ ft} 3 / 3.15 \text{ ft} 3/\text{sk} = 663 \text{ sks}
Tail Cement:
        9,384' - 10,000'
        13.0 ppg Premium Lite II High Strength cement (or equivalent)
        0.05% bwoc Static Free
        0.4% bwoc R-3
        3% bwow Potassium Chloride
       0.9% bwoc FL-25
        1 gal / 100 sk FP-6L
       0.2% bwoc Sodium Metasilicate
       0.2% bwoc BA-59
       Cement yield = 1.94 ft3/sk w/ 10 gal/sk water
       Annular volume = 616' * 0.2526 \text{ ft}3/\text{ft} = 155.6 \text{ ft}3
       Excess = 25\%
```

## Annular volume w/ excess = 155.6 ft3 \* 1.25 = 194 ft3 Tail Cement Requirement = 100 sks

Displacement Volume:

10,000' \* 0.0232 bbl/ft = 232 bbls

## 5. <u>Mud Program</u> (visual monitoring)

Interval	Mud Type	Weight	Viscosity	Fluid Loss
0'-	Water/Gel/Lime/Native	8.3-8.6 ppg	33-36 sec/qt	N/C
2,400'	Clays		_	
2,400'-	KCl/Polymer or	9.0-9.3 ppg	38-42 sec/qt	8-10cc
12,400'	DAP/Polymer			

Sufficient mud materials to maintain mud properties, control lost circulation, contain a "gas" kick, and rebuild an active mud system will be available on location during drilling operations.

#### 6. Testing, Logging, Coring

- a. Drill stem tests non anticipated
- b. Electric logs DIL/SP/GR, FDC/CNL/CAL/PE/GR, BHC sonic/GR all from TD to surface
- c. Coring possible sidewall coring in the Dakota, Cedar Mountain, Morrison and Entrada.

## 7. <u>Anticipated Bottom Hole Pressure and Temperature, and other Potential</u> Hazards

#### A. Bottom Hole Pressure:

Maximum anticipated bottom hole pressure is 4,340 psi (calculated at 0.35 psi/ft. at the 12,400' (TVD) level of the Wingate). This pressure gradient was calculated from a bottom hole pressure buildup tests conducted on four separate wells located in Section 29, T14S-R20E. These wells are the closest wells to the subject well completed in the same deep zones. Therefore the maximum anticipated surface pressure is 1,612 psi (bottom hole pressure minus the pressure of a partially evacuated hole calculated at 0.22 psi/ft.).

#### B. Bottom Hole Temperature:

The bottom hole temperature anticipated in this wellbore is approximately 230 degrees Fahrenheit at 12,400' TVD. This anticipated temperature is consistent with the temperatures encountered in the other four deep wells drilled in this area.

## C. Abnormal Pressures or Temperatures:

As demonstrated above, no abnormal pressures or temperatures are anticipated in this well.

#### D. Potential Hazards:

No hydrogen sulfide  $(H_2S)$  gas or other potential hazards have been encountered or are known to exist in any well drilled to similar depths in the general area.

## 8. Anticipated Starting Date and Duration

Spud Date: Upon governmental approval and drilling rig availability

## Duration of Operations:

- 1) Drilling: Approximately 40 days.
- 2) Completion: Approximately 30 days

#### **Drilling Notification:**

Twenty-four (24) hours prior to spudding the well, Carol Daniels at the Division of Oil, Gas and Mining for the State of Utah will be notified of our intentions to commence operations, unless otherwise instructed in the site specific conditions of approval.

### SURFACE USE PLAN MILLER, DYER & CO. LLC

## UTE TRIBAL 6-16-14-20 SENW Section 16 T14S-R20E

#### 1. Existing Roads:

- a. Topographic Map "A" shows the vicinity of the well, including a portion of the Agency Draw Road. This road is reached from Ouray, Utah, by following the Seep Ridge Road south to Buck Canyon; taking the Buck Canyon road west to the Willow Creek Road; then north on the Willow Creek Road to Santio Crossing, which is at the junction of the Willow Creek Road and the Agency Draw Road. The Flat Rock Mesa Road then continues 3.2 miles to the Flat Rock Field.
- b. Topographic Map "B" shows the point approximately 55 miles south of Ouray where the access road to the well departs from the Flat Rock Mesa Road. Beyond this point the access road consists of 0.7 mile of existing lease road leading to an existing well pad in the NENE of Section 29-R14E-R20E. Four miles of new road trending North will lead to a 4,110' access road for the Ute Tribal 6-16-14-20 location.

## 2. Planned Access Road: (refer to Topographic Map "D")

- a. Length of new road will be approximately 4110 feet.
- b. The right-of-way width is 30' (15' on either side of the centerline) with a 20-foot wide running surface.
- c. Maximum grade will be less than 2%
- d. No turn-outs are planned.
- e. The new road will be crowned, ditched and dipped to provide adequate drainage.
- f. Culverts will be used if necessary.
- g. No gates are cattle guards will be needed. Nor will any existing facilities be modified.
- h. The proposed road was flagged when the location was staked.
- i. The authorized officer will be contacted at least 24 hours in advance of commencement of construction of the access road and well pad.

## 3. Location of Existing Wells:

a. The nearest producing well is the Flat Rock #3-29-14-20, located approximately 2.5 miles southwest of the proposed well location in Section 29-T14S-R20E.

## 4. Location of Existing and/or Proposed Facilities:

a. There are no existing facilities on the proposed well pad. All proposed facilities will be contained within the proposed location site (see attached "Location Layout"). Topographic Map "D" shows the proposed route for a gas line, to be co-located in the access road right-of-way, and connected to the Miller, Dyer & Co. LLC gathering system.

b. The operator will submit information concerning proposed on and off well pad facilities once production has been established by applying for approval of subsequent operations.

## 5. Location and Type of Water Supply:

- a. Miller, Dyer & Co. existing water supply well the Ute Tribal 30-4A, located in the NENW Section 30-T14S-R20E on Indian surface has been approved by the Ute Indian Tribe. The existing BIA water permit number for the well is #14-20-H62-5069.
- b. Some produced water from existing wells may be used for drilling. Fresh water may also be taken at a point of diversion at Santio Crossing from Willow Creek in the SESE Section 29-T12S-R21E, SLB&M, if available during the drought. This water will be taken under the terms of the Ute Oilfield Water Service's state filing.
- c. Water will be transported by truck on the Agency Draw and Flat rock Mesa roads.

#### 6. Source of Construction Materials:

- a. It is anticipated that any construction materials will be needed for the drilling phase of this project. Gravel, shale or road base materials needed to upgrade access roads and well pad will be obtained from the operator's pit located on SITLA land near Chimney Rock.
- b. The entire well site and all access roads to be upgraded for built are located on lands held in trust by the federal government for the Ute Indian Tribe.
- c. All construction materials used in building the well pad and access road will be native materials accumulated during construction. In the event that additional materials are needed, they will be obtained from the operator's existing pit on SILTA land or from private sources.

### 7. Methods for Handling Waste Disposal:

- a. Methods and locations for safe containment and disposal of the following materials:
  - 1. Drill cuttings will be buried in the reserve pit.
  - 2. Garbage and trash will be contained in trash baskets and hauled to a sanitary landfill. There will be no burning of trash on the location at any time.
  - 3. Salts will be kept in proper containers and salvaged for future use or disposed of at an approved facility.
  - 4. Chemicals will be kept in proper containers and salvaged for future use or disposed of at an approved facility.
  - 5. Sewage waste will be contained in portable chemical toilets serviced by a commercial sanitary service.
- b. Drilling fluids will be contained in the reserve pit and mud tanks. To the extent possible, drilling fluids and water will be saved for use at future drilling locations. Unusable drilling fluids and water will be disposed of in an approved manner upon the completion of the well.

c. No chemicals subject to reporting under SARA Title III (hazardous materials) in an amount greater that 10,000 pounds will be used, produced, stored, transported, or disposed of annually in association with the drilling, testing, of this well. Furthermore, extremely hazardous substances, as defined in 40 CFR 355, in threshold planning quantities, will not be used, produced, stored, transported, or disposed of in association with the drilling, testing, or completing of this well.

#### d. Reserve pit and waste water disposal:

- 1. The reserve pit will be constructed so as not to lead, break, or allow the discharge of fluids.
- 2. The reserve pit will be lined with 12 mil plastic nylon reinforced liner installed over sufficient bedding material to cover any exposed rocks. The pit will be fenced on three sides with 39" net wire, topped with a minimum of one strand of barbed wire. All wire will be stretched prior to attachment to the corner posts. The fourth side will be fenced when drilling activities are completed to allow drying.
- 3. The closure of the reserve pit will follow the Guidance for Reserve Pit Closure as found in the Environmental Handbook of the State of Utah, Division of Oil, Gas & Mining.
  - a) The reserve pit will be closed within one year following drilling and completion of a well (R649-16.3).
  - b) Liquid in a pit will be allowed to either evaporate or be removed. If removed, it will be disposed of properly, some options are injection (in this well or another), hauled to a permitted disposal facility, or re-used at another well.
  - c) The pit liner may be cut off above the cuttings/mud level and hauled to a landfill, or folded in and processed along with other pit contents and covered. No remnants of liner material will be exposed at the surface when pit closure is complete. Pit area will be mounded so as not to allow ponding of water and drainage diverted around as not to allow erosion of the old pit site.
- 4. A closed drilling system will not be used as there is no irrigable land, floodplains, or lands under crop production.
- 5. In accordance with Onshore Order No. 7, a permanent disposal method and location will be applied for within 90 days of establishing production.
- 6. After first production:
  - a) Produced waste water will be confined to the reserve pit, or a storage tank for a period not to exceed 90 days.
  - b) During the 90 day period, in accordance with Onshore Order No. 7, an application for approval of a permanent disposal method and location, along with the required water analysis will be submitted to the authorized officer.

c) No produced water will be used for dust or weed control of any kind. Should spills of oil, produced water, or hazardous materials occur, the area of the spill will be re-mediated and contaminated soil and recovered oil or hazardous materials will be hauled to an approved disposal facility.

#### 8. Ancillary Facilities:

a. No airstrips will be built. Mobile living quarters and office facilities for supervisors, geologists, mud engineers, mud loggers and air compressor personnel will be confined to the drilling location as shown on the "Location Layout" diagram. The drilling crew will be housed on location.

#### 9. Well Site Layout:

- a. Refer to attached "Typical Cross Section" diagram for cuts and fills and relation to topography.
- b. Refer to "Location Layout" diagram for location of mud tanks, reserve and flare pits, pipe racks, living facilities and top soil stockpiles.
- c. Refer to "Location Layout" diagram for rig orientation, access road and parking area. Parking area will be in the northeast corner of the location.

#### 10. Plans for Restoration of the Surface:

- a. Producing well location
  - 1. Immediately upon well completion the location and surrounding area will be cleared of all tubing, equipment, debris, materials, trash and junk not required for production.
  - 2. Immediately upon well completion any hydrocarbons on the reserve pit will be removed and disposed of properly.
  - 3. The reserve pit and that portion of the location not needed for production facilities/operations will be re-contoured to the approximate natural contours. The reserve pit will be reclaimed within 90 days of the date of well completion, or as soon thereafter as is practical. Before any dirt work takes place, the reserve pit must be completely dry and all cans, barrels, pipe, etc removed. The liner will be perforated and torn prior to backfilling.
  - 4. Access roads will be graded and maintained to prevent erosion and accommodate year-round traffic.
  - 5. All disturbed areas not needed for operations will be seeded with the mixture required by the BIA in the manner specified by the BIA.

### b. Dry Hole/Abandoned Location

1. At such time as it is determined that the well is to be plugged and abandoned, the operator will submit a subsequent report of abandonment to the BLM and the BIA. The BLM will attach plugging conditions of approval, and the BIA will attach conditions of approval for the restoration of the surface.

#### 11. Surface Ownership:

a. Access roads and location are held in trust for the Ute Indian Tribe by the Unites States. The operator has obtained a right-of-way with the BIA and submitted payment for damages as specified in its Exploration and Development Agreement with the Ute Indian Tribe.

#### 12. Additional Information:

- a. The operator will inform all persons in the area who are associated with this project that they will be subject to prosecution for knowingly disturbing historic or archaeological sites, or for collecting artifacts. If historic or archaeological materials are uncovered during construction, the operator will immediately stop work that might further disturb such materials, and will inform the assigned monitor and the authorized officer (AO) at the BIA. Within five working days the AO will inform the operator as to:
  - 1. Whether the materials appear to be eligible for the National Register of Historic Places;
  - 2. The mitigation measures the operator will likely have to undertake before the site can be used (assuming in situ preservation is not necessary); and
  - 3. A time frame for the AO to complete an expedited review under 36 CFR 900.11 to confirm, through the State Historic Preservation Officer, that the findings of the AO are correct and that mitigation is appropriate.
- b. If the operator wishes at any time to relocate activities to avoid the cost of mitigation and/or the delays associated with this process, the AO will assume responsibility for whatever recordation and stabilization of the exposed materials may be required. Otherwise, the operator will be responsible for mitigation costs. The AO will provide technical and procedural guidelines for the conduct of mitigation. Upon verification from the AO that required mitigation has been completed, the operator will be allowed to resume construction.
- c. At the request of the Ute Indian Tribe, a 30'-wide fire break will be bladed around the perimeter of the location.

#### 13. Lessee's or Operator's Representative and Certification:

a. Jeff Lang, Vice President of Operations

Miller, Dyer & Co. LLC 475 17<sup>th</sup> Street, Suite 1200

Denver, CO 80202

Office: 303 292 0949 Ext 102

FAX: 303 292 3901 Cell: 303 503 3730

Email: jeff@millerdyer.com

I hereby certify that I have inspected the proposed drill site and access road; that I am familiar with the conditions which currently exist; that the statements made in this plan are true and correct to the best of my knowledge; and that the work associated with the

operations proposed here will be performed by Miller, Dyer & Co. LLC, and its contractors an subcontractors in conformity with the plan and the terms and conditions under which it is approved. This statement is subject to the provisions of 18 U.S.C. 1001 for the filing of a false statement.

Please be advised that Miller, Dyer & Co. I Tribal #8-16-14-20 well; SENE of Section Uintah County, Utah; and is responsible for lands. Bond coverage is provided by Certif	16, T14S-R20E and all prod the operations conducted up	lucing zones;
3/23/07 Date	Jeff Lang/ Vice President of Operation	hs
Γhe onsite inspection for this well was cond	lucted on	_, 2006
Participants in the onsite inspection were:		
Kolby Kay, Timberline Land Surveying		
John E. Dyer, Miller, Dyer & Co. LLC		
Ute Indian Tribe		
Ute Indian Tribe		
(contractor)		
BIA rep		
State of Utah rep		




PHOTO VIEW: FROM CORNER #5 TO LOCATION STAKE

CAMERA ANGLE: NORTHEASTERLY



PHOTO VIEW: FROM BEGINNING OF PROPOSED ROAD

CAMERA ANGLE: SOUTHWESTERLY

## MILLER, DYER & CO. LLC

Ute Tribal 6-16-14-20 SECTION 16, T14S, R20E, S.L.B.&M. 1846' FNL & 2065' FWL

#### LOCATION PHOTOS

DATE TAKEN: 07-17-06 **DATE DRAWN: 07-20-06** 

TAKEN BY: M.S.B. DRAWN BY: M.W.W.

Timberline Land Surveying, Inc.
38 West 100 North Vernal, Utah 84078
(435) 789-1365

SHEET

OF 10

# T14S, R20E, S.L.B.&M. S89°55'W - 79.60 (G.L.O.) M89'46'47"W - 5216.85' (Megs.) 1/4 Cerner 2065 (Computed) NO.03'W (G.L.O.) 16 WELL LOCATION: UTE TRIBAL 6-16-14-20 ELEV. UNGRADED GROUND = 6837.7' N00'54'10"E \$89'51'W - 79.70 (G.L.O.)

■ SECTION CORNERS LOCATED

BASIS OF ELEVATION IS BENCH MARK 60 WF 1952

LOCATED IN THE SW 1/4 OF SECTION 35, T14S,

R20E, S.L.B.&M. THE ELEVATION OF THIS BENCH

MARK IS SHOWN ON THE FLAT ROCK MESA 7.5 MIN.


QUADRANGLE AS BEING 7363'.

UTE TRIBAL 6-16-14-20 (Proposed Well Head) NAD 83 Autonomous

LATITUDE = 39' 36' 05.29" LONGITUDE = 109' 41' 06.37"

## MILLER, DYER & CO. LLC

WELL LOCATION, UTE TRIBAL 6-16-14-20, LOCATED AS SHOWN IN THE SE 1/4 NW 1/4 OF SECTION 16, T14S, R20E, S.L.B.&M. UINTAH COUNTY, UTAH.



#### NOTES:

- 1. Well footoges are measured at right engles to the Section Lines.
- 2. Bearings are based on Global Positioning Setallite observations.
- 3. The proposed well bears S47'58'40"E 2768.82' from the Northwest Corner of Section 16.


THIS IS TO CERTIFY THAT THE ABOVE PLAT WAS PREPARED FROM FIELD NOTES BRACTUAL SURVEYS MADE BY ME OR UNDER 100 SUPPERVISION AND THAT THE SAME ARE TRUE AND CORRECT OF THE BEST OF MY KNOWLEDGE AND WELLEY.


REGISTRATION NECESSARY TOR


## TIMBERLINE LAND SURVEYING, INC.


38 WEST 100 NORTH. - VERNAL, UTAH 84078 (435) 789-1365


· · · · · · · · · · · · · · · · · · ·	<b> </b>		
DATE SURVEYED: 07-17-06	SURVEYED BY: K.R.K.	SHEET	
DAYE DRAWN: 07-20-06	DRAWN BY: M.W.W.	2	
SCALE: 1" = 1000'	Date Lost Revised:	OF 10	





















## 08-06 Miller Dyer Ute Tribal 6-16-14-20rev.

Casing Schematic



Well name:

08-06 Miller Dyer Ute Tribal 6-16-14-20rev.

Operator:

Miller, Dyer & Co., LLC

String type:

Location:

Production

**Uintah County** 

Project ID:

43-047-38506

Design parameters:

Collapse

Mud weight:

9.300 ppg

Design is based on evacuated pipe.

Minimum design factors:

Collapse: Design factor

1.125

**Environment:** 

H2S considered?

Non-directional string.

Surface temperature: 75 °F 249 °F Bottom hole temperature:

1.40 °F/100ft Temperature gradient: Minimum section length: 1,500 ft

**Burst:** 

Design factor

1.00

Cement top:

3,642 ft

No

<u>Burst</u>

Max anticipated surface

pressure: Internal gradient: 3.263 psi 0.220 psi/ft

Calculated BHP

5,991 psi

No backup mud specified.

Tension:

8 Round STC: 8 Round LTC:

**Buttress:** Premium:

Body yield:

1.60 (J) 1.50 (J)

1.80 (J)

1.80 (J)

1.50 (B)

Tension is based on buoyed weight.

Neutral point:

10,651 ft

Run Seq	Segment Length (ft)	Size (in)	Nominal Weight (lbs/ft)	Grade	End Finish	True Vert Depth (ft)	Measured Depth (ft)	Drift Diameter (in)	Internal Capacity (ft³)
3	1800	5.5	17.00	N-80	Buttress	1800	18Ó0	4.767	234.9
2	8600	5.5	17.00	N-80	LT&C	10400	10400	4.767	1122.5
1	2000	5.5	17.00	P-110	LT&C	12400	12400	4.767	261.1
Run Seq	Collapse Load (psi)	Collapse Strength (psi)	Collapse Design Factor	Burst Load (psi)	Burst Strength (psi)	Burst Design Factor	Tension Load (Kips)	Tension Strength (Kips)	Tension Design Factor
3	870	5435	6.250	3659	7740	2.12	` 181 <sup>°</sup>	`3 <b>9</b> 7	2.19 B
2	5024	6273	1.249	5551	7740	1.39	150	348	2.31 J
1	5991	7480	1.249	5991	10640	1.78	4	445	99.99 J

Prepared

**Dustin K. Doucet** 

Div of Oil, Gas & Minerals

Phone: 801-538-5281

FAX: 801-359-3940

Date: March 30,2007 Salt Lake City, Utah

Remarks:

Collapse is based on a vertical depth of 12400 ft, a mud weight of 9.3 ppg. The casing is considered to be evacuated for collapse purposes. Collapse strength is based on the Westcott, Dunlop & Kemler method of blaxial correction for tension.

Burst strength is not adjusted for tension.

Well name:

08-06 Miller Dyer Ute Tribal 6-16-14-20rev.

Operator:

Miller, Dyer & Co., LLC

String type:

Surface

**Uintah County** 

Project ID:

43-047-38506

Design parameters:

Collapse

Location:

8.600 ppg

Mud weight: Design is based on evacuated pipe. Minimum design factors:

Collapse: Design factor

1.125

**Environment:** 

H2S considered? Surface temperature:

75 °F 120 °F

No

Bottom hole temperature: Temperature gradient:

1.40 °F/100ft

Minimum section length:

300 ft

**Burst:** 

Design factor

1.00

1.80 (J) 1.80 (J)

1.60 (J)

1.50 (J)

Cement top:

343 ft

Burst

Max anticipated surface

No backup mud specified.

pressure: Internal gradient: Calculated BHP

2,496 psi 0.220 psi/ft

3,200 psi

**Tension:** 

8 Round STC: 8 Round LTC: **Buttress:** 

Premium: Body yield:

1.50 (B)

Tension is based on buoyed weight. Neutral point: 2,793 ft

Non-directional string.

Re subsequent strings:

Next setting depth: Next mud weight: Next setting BHP:

12,400 ft 9.300 ppg 5,991 psi 19.250 ppg

Fracture mud wt: Fracture depth: Injection pressure:

3,200 ft 3,200 psi

Run Seq	Segment Length (ft)	Size (in)	Nominal Weight (lbs/ft)	Grade	End Finish	True Vert Depth (ft)	Measured Depth (ft)	Drift Diameter (in)	Internal Capacity (ft³)
1	3200	9.625	36.00	J-55	LT&C	3200	3200	8.796	1389
Run Seq	Collapse Load (psi)	Collapse Strength (psi)	Collapse Design Factor	Burst Load (psi)	Burst Strength (psi)	Burst Design Factor	Tension Load (Kips)	Tension Strength (Kips)	Tension Design Factor
1	1430	2020	1.413	3200	3520	1.10	101	453	4.51 J

Prepared

Dustin K. Doucet

Div of Oil, Gas & Minerals

Phone: 801-538-5281 FAX: 801-359-3940

Date: March 30,2007 Salt Lake City, Utah

Remarks:

Collapse is based on a vertical depth of 3200 ft, a mud weight of 8.6 ppg. The casing is considered to be evacuated for collapse purposes. Collapse strength is based on the Westcott, Dunlop & Kemler method of biaxial correction for tension.

Burst strength is not adjusted for tension.

#### **STATE OF UTAH**

DEPARTMENT OF NATURAL RESOURCES
DIVISION OF OIL GAS AND MINING

5.	LEA	SE DESIG	NATION A	ND SERIAL	NUMBER:	
A	Al	50724	(provid	ouely M	II _47502	•

DIVISION OF OIL, GAS AND IMINING	ML-50734 (previously ML-47502)
SUNDRY NOTICES AND REPORTS ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME:
Do not use this form for proposals to drill new wells, significantly deepen existing wells below current bottom-hole depth, reenter plugged wells, or to drill horizontal laterals. Use APPLICATION FOR PERMIT TO DRILL form for such proposals.	7. UNIT or CA AGREEMENT NAME:
1. TYPE OF WELL OIL WELL GAS WELL OTHER	8. WELL NAME and NUMBER: Ute Tribal #6-16-14-20
2. NAME OF OPERATOR: Miller, Dyer & Co. LLC	9. API NUMBER: 4304738506
3. ADDRESS OF OPERATOR: 475 17th Street, Ste 1200 CITY Denver STATE CO ZIP 80202 PHONE NUMBER: (303) 292-0949	10. FIELD AND POOL, OR WILDCAT:
4. LOCATION OF WELL FOOTAGES AT SURFACE: 1846' FNL, 2065' FWL	соинту: Uintah
QTR/QTR, SECTION, TOWNSHIP, RANGE, MERIDIAN: SENW 16 14S 20E	STATE: UTAH
11. CHECK APPROPRIATE BOXES TO INDICATE NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION TYPE OF ACTION	
NOTICE OF INTENT (Submit in Duplicate)  Approximate date work will start:  CASING REPAIR  CHANGE TO PREVIOUS PLANS  DEEPEN  PRACTURE TREAT  NEW CONSTRUCTION  OPERATOR CHANGE	REPERFORATE CURRENT FORMATION  SIDETRACK TO REPAIR WELL  TEMPORARILY ABANDON  TUBING REPAIR
CHANGE TUBING PLUG AND ABANDON  SUBSEQUENT REPORT (Submit Original Form Only) Date of work completion: PRODUCTION (START/RESUME)  COMMINGLE PRODUCING FORMATIONS RECLAMATION OF WELL SITE  CONVERT WELL TYPE RECOMPLETE - DIFFERENT FORMATION	VENT OR FLARE WATER DISPOSAL WATER SHUT-OFF OTHER:
12. DESCRIBE PROPOSED OR COMPLETED OPERATIONS. Clearly show all pertinent details including dates, depths, volum	es. etc.
Miller, Dyer & Co. LLC now plans to drill the subject well to a bottom hole location of 2450' FR20E. The surface location remains unchanged. Attached is the request for permission to request for administrative approval of our exception location. Also enclosed is a plat showing	FNL, 1660' FWL, Section 16, T14S, drill a directional well, and the
4383944 - Approved by the / Utah Division of Oll, Gas and Mining	RECEIVED JUN 1 2007
Date: 00-26-07	DIV. OF OIL, GAS & MINING
Miller, Dyer & Co. LLC requests that all well information Parain confidential	
NAME (PLEASE PRINT) Leffrey H. Lang TITLE Vice President o	f Operations
SIGNATURE	
(This space for State use only)	

475 Seventeenth Street, Suite 1200 Denver, Colorado 80202 P: 303-292-0949 F: 303-292-3901

June 20, 2007

Ms. Diana Mason Division of Oil, Gas and Mining P O Box 145801 Salt Lake City, UT 84114-5801

RE: Directional Drilling R649-3-11

Ute Tribal #6-16-14-20 1846' FNL, 2065' FWL (surface) 2450' FNL, 1660' FWL (bottom hole)

Section 16, T14S R20E Uintah County, Utah **API: 43-047-38506** 

State Lease # ML-50734 (previously ML-47502)

Dear Ms. Mason,

Pursuant to the filing of Miller, Dyer & Co. LLC's Application for Permit to Drill regarding the above referenced well on March 23, 2007, we are hereby submitting this letter in accordance the Oil & Gas Conservation rule R649-3-11 pertaining to the Exception to Location and Siting of Wells.

- The Ute Tribal #6-16-14-20 is located on State Lease #ML-50734
- Miller, Dyer & Co. LLC is permitting this well as a direction a well in order to minimize surface disturbance by utilizing our existing location. We have revised our targeted bottom hole location based on a new seismic interpretation.
- Furthermore Miller, Dyer & Co. LLC hereby certifies that it is the sole working interest owner within 460 feet of the entire directional well bore and the entirety of Section 16 (state lease #ML-50734).

Therefore, based on the above stated information, Miller, Dyer & Co. LLC requests the permit be granted pursuant to R649-3-11.

Respectfully Submitted, MILLER, DYER & CO. LLC

Jeffrey H. Lang

Vice President of Operations



475 Seventeenth Street, Suite 1200 Denver, Colorado 80202 P: 303-292-0949 F: 303-292-3901

June 20, 2007

Ms. Diana Mason Division of Oil, Gas and Mining P O Box 145801 Salt Lake City, UT 84114-5801

RE:

**Exception Location** 

Ute Tribal #6-16-14-20 Section 16, T14S R20E Uintah County, Utah API: 43-047-38506

State Lease # ML-50734 (previously ML-47502)

Dear Ms. Mason:

Miller, Dyer & Co. LLC, as Operator, is proposing to drill and has made application with the Division of Oil. Gas and Mining ("DOGM") for a permit to drill the following well:

Ute Tribal #6-16-14-20

Surface location: 1846' FNL, 2065' FWL Bottom hole location: 2450' FNL, 1660' FWL

SE/NW Section 16, T14S R20E,

Uintah County, Utah

Record Title Owner: Chicago Energy Associates, LLC

Designated Operator: Miller, Dyer & Co. LLC (Designation on file with DOGM & SITLA)

Pursuant to Rule R649-3-3, Miller, Dyer & Co. LLC is making application and seeking DOGM's administrative authority to grant an exception to the locating and siting requirements for this well.

The Ute Tribal #6-16-14-20 bottom hole location is approximately 270' to the south and 120' to the west of the 400' drilling window centered in the 40-acre drilling unit designated as the SE/NW of Section 16. The well will be directionally drilled to minimize surface disturbance by utilizing our existing location. The targeted bottom hole location represents the most optimal location to test the Entrada formation according to our recently interpreted seismic information.

Chicago Energy Associates, LLC is the owner within a 460-foot radius of the proposed well location and is the owner of directly and diagonally offsetting drilling units of the proposed well location.


Miller-Dyer and Chicago Energy Associates, LLC respectfully requests an administrative approval by the division of an exception location for the above referenced well.

Yours truly,

MILLER, DYER & CO. LLC

Jeffrey H. Lang

Vice President of Operations



## **DIVISION OF OIL, GAS AND MINING**

## **SPUDDING INFORMATION**

Name of Company:		MILL	ER, DYER	<u>&amp; CO, L</u>	LC	
Well Name:		UTE	TRIBAL 6-1	6-14-20		
Api No:	43-047-38	8506	Lease	Type:	STATE	
Section 16	_Township_	14S Range	<b>20E</b> Cou	ınty	UINTAH	
Drilling Con	tractor	PATTERS	ON	R	IG # <u>180</u>	
SPUDDE  Drilling wi	Date Time How	07/16/07 4:15 AM ROTARY				
Reported by		GARY				
		307) 212				
Date	07/17/07		Signed	CHD		

STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS AND MINING FORM 6

		ENTITY ACTIO	N FORM
Operator:	Miller, Dyer & Co. LLC		Operator Account Number: N 2580
Address:	475 17th Street, Suite 420		
	city Denver		<u> </u>
	state CO	zip 80202	Phone Number: (303) 292-0949

Action Code Current Entity New Entity Spud Date Entity Assig Effective I	API Number	Well	Name	QQ	Sec	Twp	Rrig	County
Number Number Effective I	4304738506	Ute Tribal # 6-16-14-20		SENW	16	145	20E Uintah	
2000	Action Code			Spud Date		Entity Assignment Effective Date		
A = 99999 = 16320 = 1782007 = 8/88/0	A	99999	16320	7	/16/200	7	8/0	28/07

API Number	Well	Name	QQ	Sec	Twp	Rng	County
Action Code	Current Entity Number	New Entity Number	S	pud Da	te		y Assignment fective Date
omments:				·			***

181416 7

API Number	Well t	lame	QQ	Sec	Twp	Rng	County
Action Code	Current Entity New Entity Number Number		Spud Date			Entity Assignmen	
omments:						<u></u>	


#### ACTION CODES:

- A Establish new entity for new well (single well only)
- B Add new well to existing entity (group or unit well)
- C Re-essign well from one existing entity to another existing entity
- D Re-assign well from one existing entity to a new entity
- E Other (Explain in 'comments' section)

JEFFREY	H.	Land
Harris (Please) Palett		
Signature/ VP Operations		7/26/2007
Title		Date

(5/2000)

AUG 2 3 2007



#### NOTICE

Utah Oil and Gas Conservation General Rule R649-3-21 states that,

- A well is considered completed when the well has been adequately worked to be capable of producing oil or gas or when well testing as required by the division is concluded.
- Within 30 days after the completion or plugging of a well, the following shall be filed:
  - Form 8, Well Completion or Recompletion Report and Log
  - · A copy of electric and radioactivity logs, if run
  - · A copy of drillstem test reports,
  - A copy of formation water analyses, porosity, permeability or fluid saturation determinations
  - · A copy of core analyses, and lithologic logs or sample descriptions if compiled
  - A copy of directional, deviation, and/or measurement-while-drilling survey for each horizontal well

Failure to submit reports in a timely manner will result in the issuance of a Notice of Violation by the Division of Oil, Gas and Mining, and may result in the Division pursuing enforcement action as outlined in Rule R649-10, Administrative Procedures, and Section 40-6-11 of the Utah Code.

As of the mailing of this notice, the division h	as not received the requir	red reports for
Operator: Miller, Dyer & Co, LLC	Today's I	Date:11/27/2007
Well:	API Number:	Drilling Commenced:
Ute Tribal 6-16-14-20 drlg rpts/wcr	4304738506	07/16/2007

To avoid compliance action, required reports should be mailed within 7 business days to:

Utah Division of Oil, Gas and Mining

1594 West North Temple, Suite 1210

P.O. Box 145801

Salt Lake City, Utah 84114-5801

If you have questions or concerns regarding this matter, please call (801) 538-5284.

cc: Well File Compliance File

## STATE OF UTAH

	DIVISION OF OIL, GAS AND MI		5. LEASE DESIGNATION AND SERIAL NUMBER: ML-50734 (previously ML-47502)
SUNDRY	NOTICES AND REPORTS	S ON WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME: Ute Indian Tribe
Do not use this form for proposals to drill n	new wells, significantly deepen existing wells below curn aterals. Use APPLICATION FOR PERMIT TO DRILL fo	rent bottom-hole depth, reenter plugged wells, or to	7. UNIT or CA AGREEMENT NAME:
1. TYPE OF WELL OIL WELL		omina saar proposals.	8. WELL NAME and NUMBER: Ute Tribal #6-16-14-20
2. NAME OF OPERATOR: Miller, Dyer & Co. LLC			9. API NUMBER: 4304738506
3. ADDRESS OF OPERATOR:		PHONE NUMBER:	10. FIELD AND POOL, OR WILDCAT:
475 17th Street, Ste 1200 CIT	Y Denver STATE CO ZIP		TO THE THE TOOL, ON WILLSON.
4. LOCATION OF WELL FOOTAGES AT SURFACE: 1846'			соимту: <b>Uintah</b>
QTR/QTR, SECTION, TOWNSHIP, RAN	nge, meridian: SENW 16 14S 2	0E	STATE: UTAH
11. CHECK APP	ROPRIATE BOXES TO INDICAT	E NATURE OF NOTICE, REPO	RT, OR OTHER DATA
TYPE OF SUBMISSION		TYPE OF ACTION	
NOTICE OF INTENT	ACIDIZE	DEEPEN	REPERFORATE CURRENT FORMATION
(Submit in Duplicate)	ALTER CASING	FRACTURE TREAT	SIDETRACK TO REPAIR WELL
Approximate date work will start:	CASING REPAIR	NEW CONSTRUCTION	TEMPORARILY ABANDON
	CHANGE TO PREVIOUS PLANS	OPERATOR CHANGE	TUBING REPAIR
<b>□</b>	CHANGE TUBING	PLUG AND ABANDON	VENT OR FLARE
SUBSEQUENT REPORT (Submit Original Form Only)	CHANGE WELL NAME	PLUG BACK	WATER DISPOSAL
Date of work completion:	CHANGE WELL STATUS	PRODUCTION (START/RESUME)	WATER SHUT-OFF
•	COMMINGLE PRODUCING FORMATIONS	RECLAMATION OF WELL SITE	✓ other: Drilling Report
	CONVERT WELL TYPE	RECOMPLETE - DIFFERENT FORMATION	
Please see attached drilling	ompleted operations. Clearly show all ping report for the Ute Tribal 6-16-1	4-20 well.	es, etc.
NAME (PLEASE PRINT) Jeffrey H.	Lang	TITLE Vice President of	Operations
(This space for State use only)			

**RECEIVED** 

DEC 0 5 2007

Date	Drilling Summary Ute Tribal 6-16-14-20
07/10/07	Rig down, move DP, rig down move & rig up skid houses SDFN
07/11/07	Rig down & move rig, Derrick down on stand, Trucks having trouble with road SDFN
07/12/07	Move rig, Set rig matting boards SDFN
07/13/07	MORU SDFN
07/14/07	shut down for night RU / move all equipment on location / mechnic & welder working on draworks 12:00 - 19:00 hrs shut down for night
07/15/07	Rig up / raised derrick 17:00 hrs Shut down for night / Mechnic worked on Drawworks #2 clutch until 23:00 hrs
07/16/07	Rig up floor / iron roughneck/ set pipe racks / mix mud / flange up conductor Measure up BHA Pick up BHA Air lines / had to reconnect air lines / they were all hooked up wrong / no pump clutches or throttles
07/17/07	Drl 12 1/4" 40' > 54' Drl 12 1/4" 54' >74' / Corrected depth to 90.6'
	Lubricate rig/pull dry bushing Drl 12 1/4" 90' > 249' Deviation Survey Drl 12 1/4" 249' > 372' Lubricate rig Drl 12 1/4" 372' > 529'
07/18/07	Wireline survey Drl 12 1/4" 529' > 560' Lubricate rig Drl 12 1/4" 560' > 744' Libricate rig Drl 12 1/4" 744' > 836' Rig service / grease swivel Drl 12 1/4" 836' > 1019' Wireline survey Drl 12 1/4" 1019' > 1200'
07/19/07	Drl 12 1/4" 1200' > 1261' Wireline survey Drl 12 1/4" 1261' > 1450' Lubricate rig Drl 12 1/4" 1450' > 1515' Wireline survey

Rig repair / losen swivel & grease Drl 12 1/4" 1515' > 1535' Rig repair / pull wash pipe and packing & replace Drl 12 1/4" 1535' > 1610' Rig repair / work on pump Drl 12 1/4" 1610' > 1737' 07/20/07 Drl 12 1/4" 1737' > 1865' Circ & condition for bit trip Drop survey / set kelly back Tripout hole / pulled tight after 2 jts / kelly up back ream / lay down singles Stake pockets and rub rail on casing delivery trucks were damaged while unloading surface casing 2 separate trucks/ got pictures and statements from everybody involved / at this time it looks like Patterson drilling will take care of it 07/21/07 Reaming out of hole / laying down singles stuck in hole Ream out of hole / laying down singles Dress bit / swipe jets out of old bit Pick up DC & DP and trip in hole w/bit#2 kelly up /Trip in / 1600' ream to bottom Cic & condition hole 07/22/07 Ream to bottom Circ & Condition Drop survey Drl 12 1/4" 1865' > 1958' Lubri cate rig Drl 12 1/4" 1958' > 2300' 07/23/07 Drl 12 1/4" 2300' > 2342' Rig service Wireline survey Drl 12 1/4" 2342' > 2710' 07/24/07 Drl 12 1/4" 2710' > 2722' Wireline survey Drl 12 1/4" 2722' > 2785' Rig service Drl 12 1/4" 2785' > 3008' Wireline survey Drl 12 1/4" 3008 > 3040' 07/25/07 Drl 12 1/4" 3040' > 3082' TOH f/mud motor Lay down Mud motor Wait on Mud motor TIH W/bit #3 & mud motor #2 s/n 8044 07/26/07 Trip in hole Remove elevators/ pu kelly/ fill pipe Drl 12 1/4" 3082' > 3133'

Rig service

Drl 12 1/4" 3133' > 3430'

Wiper trip

#### 07/27/07

Wiper trip / pull 5 stands

Circ & condition / drop surey

T0 for Csg

Rig up laydown machine & LD DC & Mud motor

Rig up Caliber Casing Service / pump up torgue Gage /Safety meeting/ fix Switch on power tongs

Run casing

Fix power tongs / replace pin

Run casing

Dress threads on casing jt

Drop ball

Run casing

Circ & condition / rig down casing crew / rig up BJ cementing

BJ safety meeting

Pressure test lines

Cement 9 5/8" Csg w/

woc

#### 07/28/07

W/O/C

Cut conductor & Csg, Weld on wellhead

Pressure test wellhead to 1000 psi, test held OK, Saftey meeting on nipple up procedures

Nipple up BOP stack

Pressure test BOP stack with Quick Test Inc., tested pipe & blind rams, inside BOP, choke manifold, upper & lower kelly cocks & safety valve to 250 psi low & 3000 psi high, tested choke line 250 low & 5000 psi high, tested cgs to 1200 psi. for 30 min. All other tests held 5 min low & 10 min high No leaks observed Install wear bushing

Pick up bit & mud mtr, Trip in hole with BHA

#### 07/29/07

RIH, Install rotating head rubber, PU kelly install rotating head drive bushing, Break circulation

Drlg cement, plug & shoe, Tagged cmt @ 3405, shoe @ 3420, Wash & ream to 3430'

Circulate, waiting on mud loggers to get up & running, as per Jeff Lang's instructions

Drlg 8 3/4 hole from 3430' to

#### 07/30/07

Drlg from 3854 to 3981'

Rig serv, wireline survey - missrun

Drlg from 3981 to 4013'

Wireline survey, 2.5 deg

Drlg from 4013 to 4331'

Wireline survey, 4.5 deg

Drlg from 4331 to 4395'

#### 07/31/07

Drlg from 4395 to 4455'

Wireline survey @ 4420' - missrun fouled line on survey machine

Drlg from 4455 to 4465'

Wireline survey @ 4387' - missrun

Drlg from 4465 to 4485'

Wireline survey @ 4450', 5 deg

Drlg from 4485 to 4521'

Rig serv

Drig from 4521 to 4553'

Wireline survey @ 4517', 5 deg

	Drlg from 4553 to 4617'
	Wireline survey @ 4582' 4 3/4 deg
	Drig from 4617 to 4681'
	Wireline survey @ 4646' 4.85 deg
	Drig from 4681 to 4713'
08/01/07	Drlg from 4713 to 4735'
	Circulate Btms up
	POOH
	Lay down mud mtr, pick up directioal tools
	Orentate tools, pick up first stand DC
	Wait on change over sub to go between monel and DC
	RIH
	RIH take surveys, directional surface tools not receiving signal correctly
	Trouble shoot directional tools, got them working finally
	RIH, taking surveys
08/02/07	RIH pick up rotating head, LD 5 jts DP
	Ream 3 jts to Btm
	Drlg from 4735 to 5339'
08/03/07	Drlg from 5339 to 5530'
•	Rig serv
	Drlg & slide from 5530 to 5944'
08/04/07	Drlg & slide from 5944 to 6039'
	Rig serv
	Drlg & slide from 6039 to 6101'
	Circ Btms up
	POOH, Pull EM tool & recalibrate
	Dress & make up bit
	RIH
	Slip & cut Drlg line
08/05/07	Trip in hole
	Wash & ream 150' to Btm, last 4' appeared to be out of gauge
	Drlg & slide from 6101 to 6330'
08/06/07	Drlg & slide from 6330 to 6416'
	Rig serv
	Drlg & slide from 6416 to 6636'
	Rig repair, working on #2 Dwks mtr clutch
	Drlg from 6636 to 6688'
08/07/07	Drlg & slide from 6688 to6700
	Rig serv
	Drlg & slide from 6700 to 6717'
	Circ btms up
	Rig repair, air line to #2 Dwks Mtr clutch
	POOH f/bit
	Lay down 15 6" DC & Mud Mtr
	Pick up bit & Mud Mtr
	Lay down & pick up MWD tools

	RIH w/DC's
	Pick up 15 jts HWDP
	RIH, work tight hole @ 6150'
	TAIT, WORK agric Hole @ 0150
08/08/07	Ream tight hole from 6100 to 6717'
<u> </u>	Drlg & slide from 6717 to 6830'
08/09/07	Drlg & slide from 6830 to 6841'
	POOH f/bit Pick up new bit
	Rig repair, High drum clutch quick releases & control valve
	RIH
	Drlg & slide from 6844 to 6880'
08/10/07_	Drig & slide from 6880 to
	Rig serv
	Drlg & slide from 7068 to 7288'
	Rig repair, Air to #2 Dwks mtr clutch, spear to high drum clutch, circ & move pipe while repairing rig
	Drlg from 7288 to 7300'
00/44/07	Discourse of the control of the cont
08/11/07	Drlg & slide from 7300 to 7477'
	Rig serv
	Drlg & slide from 7477 to 7700'
	work on MWD tools, not getting signal
	Drlg & slide from 7700 to 7844'
08/12/07	Drlg & slide from 7844 to 8043'
	Rig serv
	Drlg & slide from 8047 to 8130'
	Survey - MWD tools malfunction
	Drig & slide from 8130 to 8257'
	Work on MWD tool
	Drig & slide from 8257 to 8385'
	Survey - MWD tools malfunction
	Drig & slide from 8385 to 8450'
	Survey - MWD tools malfunction
	Drlg & slide from 8450 to 8514'
	Survey - MWD tools malfunction
	Drlg & slide from 8514 to 8520'
00/40/07	<b>1</b>
08/13/07	Drlg & slide from 8520 to 8797'
	Rig serv
	Drlg & slide fron 8797 to 8985'
	Change out kelly saver sub
	Drlg & slide from 8985 to 9143'
08/14/07	Drlg & slide to 9206'
	Rig repair - change pumps
	Drlg & slide from 9206 to 9363'
	Rig serv
	Drlg & slide from 9363 to 9772'
08/15/07	Drlg & slide from 9772 to 9992'
	Rig serv, change out control valve for rotary clutch

	Drlg & slide from 9992 to 10338'
00/40/07	D. C. W. C. (2000)
08/16/07	Drlg & slide from 10338 to 10652' Rig serv
	Drlg & slide from 10652 to 10972'
08/17/07	Drlg from 10972 to 11002'
	Circ Btms up f/trip
	POOH Change MWD tools, Lay down mud mtr & pick uo new mtr, change bit
	RIH
	Wash & ream from 10500 to 10600', 10650 to 10740', 10951 to 11002'
	Drlg from 11002 to 11018'
08/18/07	Drlg & slide from 11018 to 11059'
	Rig serv
	Drlg & slide from 11059 to 11190'
08/19/07	Drlg & slide from 11190 to 11246'
<del></del>	Rig serv
	Drig & slide from 11246 to 11300'
	POOH, mtr failure
	Pull MWD tools , Change out Mud mtr
08/20/07	PU new mud mtr swap out MWD tools
	RIH
	Kelly up & fill pipe RIH to 10964'
	Wash & ream froom 10964 to 11300'
	Drlg from 11300 to 11475'
08/21/07	Drill from 11475 to 11501'
	Rig serv Drill from 11501 to 11708'
	5.111 1.001 to 111.00
08/22/07	Drlg from 11708 to 11721'
	Rig serv
	Drig from 11721 to 11846'
	Slide drilling from 11846 to 11852'  Drlg from 11852 to 11878'
	5 ig itolii 11002 to 11070
08/23/07	Drlg & slide from 11878 to 11940'
	Rig serv
	Drlg & slide from 11940 to 12062'
08/24/07	Drlg from 12062 to 12072'
	Circ btms up cond mud spot beads from 12072 to 11072'
	POOH
	Lay down 35 jts grade "S 135" DP POOH
	Lay down directional tools , pick up straight Mtr,Bit, & Teledrift, Function test blind & pipe rams
	Slip & cut Drlg line
	Pick up 35 jts grade "G" DP changed out corrosion ring

, ,

	RIH
08/25/07	Test Teledrift tool
00/20/01	RIH
	Rig serv
	RIH, wash 5 its to Btm
	Rig repair - replace slip dies
	Drig from 12072 to 12124'
	Work bead sweep
	Drig from 12124 to 12127'
	Spot Luba beads, work pipe
	Drig from 12127 to 12129'
	- Ng No. 11 12 12 10 12 12 0
08/26/07	Drlg from 12127 to 12132', can not get Diff pressure to rise acts like no weight on bit
	Spot Lubra beads & work pipe, beads spotted from 11125 to 9125'
	Drlg from 12132 to 12136', try more weight on bit - loosing pump pressure, seems to be a problem downhole
	Circ & cond hole
	РООН
	Lay down mud mtr & pick up fresh mtr & bit
	RIH, break and redope all drill collars
	Fill pipe, break circ
	RIH
	Fill pipe & break circ
	Wash & ream 35' to Btm
	Drlg from 12136 to 12140'
00/07/07	D 111.5 404.40 ( 404.75)
08/27/07	Drill from 12140 to 12175'
	Rig serv
	Drig from 12175 to 12208'
08/28/07	Drig from 12208 to 12237'
	Rig serv, unplug standpipe pressure transducer
	Drlg from 12237 to 12266'
	Circ & cond mud, Teledrift survey, drop single shot survey
	POOH f/bit
	Change bit, Function test Blind & Pipe rams, Break down survey tools
	RIH w/bit # 12
09/20/07	Die sanaie Water not sieu-letter en beste flances leur en de el
08/29/07	Rig repair - Water not circulating on brake flanges, Iron roughneck RIH
	Wash & ream 30' to btm
	Drig from 12266 to 12340'
	Ding   10111   12250 to 12540
08/30/07	Drlg from 12340' to 12517'
-	Circc & cond hole
	Wiper trip f/logs
08/31/07	Wiper trip
	Circ & cond mud, raise vis to 48 sec
	Drop survey & POOH f/logs
	Run wireline logs w/ Halliburton Wireline, loggers depth 12555'
	Lay down logging tools & rig down loggers
	W/O/O, waiting on sidewall core tools

09/01/07	W/O/O
	Lay down mud mtr & Teledrift
	RIH w/ bit, SLM , Hole depth adjusted to 12534' as per pipe strap
	Circ & cond mud, unload csg, sort & put on racks, clean , rabbit & strap pipe
	Rig up lay down machine & LDDP
09/02/07	LDDP
	Rig repair - Iron roughneck blew Hyd hose
	LDDP
	Pull rotating head & break kelly
	LDDP & DC
	Pull wear bushing & rig up Caliber casing tools
	Run 5 1/2, 17#, production csg. Work on casing tongs, tongs have caused approx two hrs downtime
09/03/07	Run 5 1/2 Prod casing
	Rig down csg tools & Rig up BJ cementers
	Circulate & cond hole for cement
	Pump 345 sx PLII + adds 1st stage cement, drop plug
	Displace with 300.8 bbls mud Bump plug 558 psi over
	Drop DV opening tool & open DV tool
	Circulate with rig pumps
	Pump 1005 sx 2nd stage lead & 100 sx 2nd stg tail, Displace w/240.7 bbls H2O, bump plug W 1490 psi over
	Nipple down BOP, set casing , Clean mud pits Rig released @ 0600 hrs 9-3-07
09/04/07	Rig down / wait on trucks
	SDFN
09/05/07	Rig repair - wait on trucks
<u>-</u>	SDFN
09/06/07	Rig down, stack rig on 32-7 location, crains did not show up, backyard is gone, derrick is down on stand
	need crains to remove derrick,dwks,& unstack sub structure , blocks unstrung.
	SDFN
09/07/07	Rig down - stack rig on 32-7 location
	SDFN
09/07/07	Rig down - stack out rig

# NOTICE OF LATE REPORTING DRILLING & COMPLETION INFORMATION

Utah Oil and Gas Conservation General Rule R649-3-6 states that.

Operators shall submit monthly status reports for each drilling well (including wells where drilling operations have been suspended).

Utah Oil and Gas Conservation General Rule R649-3-21 states that.

- A well is considered completed when the well has been adequately worked to be capable of producing oil or gas or when well testing as required by the division is concluded.
- ➤ Within 30 days after the completion or plugging of a well, the following shall be filed:
  - Form 8, Well Completion or Recompletion Report and Log
  - · A copy of electric and radioactivity logs, if run
  - · A copy of drillstem test reports,
  - A copy of formation water analyses, porosity, permeability or fluid saturation determinations
  - · A copy of core analyses, and lithologic logs or sample descriptions if compiled
  - A copy of directional, deviation, and/or measurement-while-drilling survey for each horizontal well

Failure to submit reports in a timely manner will result in the issuance of a Notice of Violation by the Division of Oil, Gas and Mining, and may result in the Division pursuing enforcement action as outlined in Rule R649-10, Administrative Procedures, and Section 40-6-11 of the Utah Code.

As of the mailing of this notice, the division h	nas not received the required reports for
Operator: Miller, Dyer & Co, LLC	Today's Date:04/21/2007
Well: Ute Tribal 6-16-14-20   45 20E 16	API Number: Drilling Commenced: 4304738506 07/16/2007
List Attached	
To avoid compliance action, required reports Utah Division of Oil, Gas and Mining 1594 West North Temple, Suite 1210 P.O. Box 145801 Salt Lake City, Utah 84114-5801	s should be mailed within 7 business days to:
If you have questions or concerns regarding at (801) 538-5260	this matter, please contact Rachel Medina

cc: Well File Compliance File



Date	Drilling Summary Ute Tribal 6-16-14-20					
07/10/07	Rig down, move DP, rig down move & rig up skid houses SDFN					
07/11/07	Rig down & move rig, Derrick down on stand, Trucks having trouble with road SDFN					
07/12/07	Move rig, Set rig matting boards SDFN					
07/13/07	MORU SDFN					
07/14/07	shut down for night RU / move all equipment on location / mechnic & welder working on draworks 12:00 - 19:00 hrs shut down for night					
07/15/07	Rig up / raised derrick 17:00 hrs Shut down for night / Mechnic worked on Drawworks #2 clutch until 23:00 hrs					
07/16/07	Rig up floor / iron roughneck/ set pipe racks / mix mud /					
	flange up conductor  Measure up BHA  Pick up BHA  Air lines / had to reconnect air lines / they were all hooked up wrong / no pump clutches or throttles  Drl 12 1/4" 40' > 54'					
07/17/07	Dri 12 1/4" 54' >74' / Corrected depth to 90.6'					
	Lubricate rig/pull dry bushing Drl 12 1/4" 90' > 249'					
	Deviation Survey					
	Drl 12 1/4" 249' > 372'					
	Lubricate rig					
	Drl 12 1/4" 372' > 529'					
07/18/07	Wireline survey					
	Drl 12 1/4" 529' > 560'					
	Lubricate rig					
	Drl 12 1/4" 560' > 744'					
	Libricate rig					
	Dri 12 1/4" 744' > 836'					
	Rig service / grease swivel					
	Dri 12 1/4" 836' > 1019'					
	Wireline survey Drl 12 1/4" 1019' > 1200'					
07/19/07	Drl 12 1/4" 1200' > 1261'					
	Wireline survey					
	Dri 12 1/4" 1261' > 1450'					

Lubricate rig

RECEIVED
JUL 0 8 2008

Drl 12 1/4" 1450' > 1515' Wireline survey Rig repair / losen swivel & grease Dri 12 1/4" 1515' > 1535' Rig repair / pull wash pipe and packing & replace Drl 12 1/4" 1535' > 1610' Rig repair / work on pump Drl 12 1/4" 1610' > 1737' 07/20/07 Drl 12 1/4" 1737' > 1865' Circ & condition for bit trip Drop survey / set kelly back Tripout hole / pulled tight after 2 jts / kelly up back ream / lay down singles Stake pockets and rub rail on casing delivery trucks were damaged while unloading surface casing 2 separate trucks/ got pictures and statements from everybody involved / at this time it looks like Patterson drilling will take care of it 07/21/07 Reaming out of hole / laying down singles stuck in hole Ream out of hole / laying down singles Dress bit / swipe jets out of old bit Pick up DC & DP and trip in hole w/bit#2 kelly up /Trip in / 1600' ream to bottom Cic & condition hole 07/22/07 Ream to bottom Circ & Condition Drop survey Drl 12 1/4" 1865' > 1958' Lubri cate rig Drl 12 1/4" 1958' > 2300' 07/23/07 Drl 12 1/4" 2300' > 2342' Rig service Wireline survey Drl 12 1/4" 2342' > 2710' 07/24/07 Drl 12 1/4" 2710' > 2722' Wireline survey Drl 12 1/4" 2722' > 2785' Rig service Dri 12 1/4" 2785' > 3008' Wireline survey Drl 12 1/4" 3008 > 3040' 07/25/07 Dri 12 1/4" 3040' > 3082' TOH f/mud motor Lay down Mud motor Wait on Mud motor TIH W/bit #3 & mud motor #2 s/n 8044

	<b>L</b>
07/26/07	Trip in hole
	Remove elevators/ pu kelly/ fill pipe
	Dri 12 1/4" 3082' > 3133'
	Rig service
	Drl 12 1/4" 3133' > 3430'
	Wiper trip
07/27/07	Wiper trip / pull 5 stands
	Circ & condition / drop surey
	T0 for Csg
	Rig up laydown machine & LD DC & Mud motor
	Rig up Caliber Casing Service / pump up torgue Gage /Safety meeting/ fix Switch on power tongs
	Run casing
	Fix power tongs / replace pin
	Run casing
	Dress threads on casing it
	Drop ball
	Run casing
	Circ & condition / rig down casing crew / rig up BJ cementing
	BJ safety meeting
	Pressure test lines
	Cement 9 5/8" Csg w/
	woc
07/28/07	w/o/c
, 200000000	Cut conductor & Csg, Weld on wellhead
	Pressure test wellhead to 1000 psi, test held OK, Saftey meeting on nippie up procedures
	Nipple up BOP stack
	Pressure test BOP stack with Quick Test Inc., tested pipe & blind rams, inside BOP, choke manifold,
	upper & lower kelly cocks & safety valve to 250 psi low & 3000 psi high, tested choke line 250 low & 5000
	psi high, tested cgs to 1200 psi. for 30 min. All other tests held 5 min low & 10 min high No leaks observed
	Install wear bushing
	Pick up bit & mud mtr, Trip in hole with BHA
07/29/07	RIH, Install rotating head rubber, PU kelly install rotating head drive bushing, Break circulation
	Drig cement, plug & shoe, Tagged cmt @ 3405, shoe @ 3420, Wash & ream to 3430'
	Circulate, waiting on mud loggers to get up & running, as per Jeff Lang's instructions
	Drig 8 3/4 hole from 3430' to
07/30/07	Drlg from 3854 to 3981'
	Rig serv, wireline survey - missrun
	Drlg from 3981 to 4013'
	Wireline survey, 2.5 deg
	Drlg from 4013 to 4331'
	Wireline survey, 4.5 deg
	Drig from 4331 to 4395'
07/31/07	Drig from 4395 to 4455'
	Wireline survey @ 4420' - missrun fouled line on survey machine
	Drig from 4455 to 4465'
	Wireline survey @ 4387' - missrun
1	•

Drlg from 4465 to 4485' Wireline survey @ 4450', 5 deg Drlg from 4485 to 4521' Rig serv Drlg from 4521 to 4553' Wireline survey @ 4517', 5 deg Drlg from 4553 to 4617' Wireline survey @ 4582' 4 3/4 deg Drlg from 4617 to 4681' Wireline survey @ 4646' 4.85 deg Drlg from 4681 to 4713' 08/01/07 Drlg from 4713 to 4735' Circulate Btms up POOH Lay down mud mtr, pick up directioal tools Orentate tools, pick up first stand DC Wait on change over sub to go between monel and DC RIH RIH take surveys, directional surface tools not receiving signal correctly Trouble shoot directional tools, got them working finally RIH, taking surveys 08/02/07 RIH pick up rotating head, LD 5 jts DP Ream 3 its to Btm Drlg from 4735 to 5339' 08/03/07 Drlg from 5339 to 5530' Rig serv Drlg & slide from 5530 to 5944' 08/04/07 Drlg & slide from 5944 to 6039' Rig serv Drlg & slide from 6039 to 6101' Circ Btms up POOH, Pull EM tool & recalibrate Dress & make up bit RIH Slip & cut Drlg line 08/05/07 Trip in hole Wash & ream 150' to Btm, last 4' appeared to be out of gauge Drlg & slide from 6101 to 6330' 08/06/07 Drlg & slide from 6330 to 6416' Rig serv Drlg & slide from 6416 to 6636' Rig repair, working on #2 Dwks mtr clutch Drlg from 6636 to 6688' 08/07/07 Drlg & slide from 6688 to 6700

Rig serv Drlg & slide from 6700 to 6717' Circ btms up Rig repair, air line to #2 Dwks Mtr clutch POOH f/bit Lay down 15 6" DC & Mud Mtr Pick up bit & Mud Mtr Lay down & pick up MWD tools RIH w/DC's Pick up 15 jts HWDP RIH, work tight hole @ 6150' 08/08/07 Ream tight hole from 6100 to 6717' Drig & slide from 6717 to 6830' 08/09/07 Drig & slide from 6830 to 6841' POOH f/bit Pick up new bit Rig repair, High drum clutch quick releases & control valve RIH Drlg & slide from 6844 to 6880' 08/10/07 Drlg & slide from 6880 to Rig serv Drlg & slide from 7068 to 7288' Rig repair, Air to #2 Dwks mtr clutch, spear to high drum clutch, circ & move pipe while repairing rig Drlg from 7288 to 7300' 08/11/07 Drlg & slide from 7300 to 7477' Rig serv Drlg & slide from 7477 to 7700' work on MWD tools, not getting signal Drlg & slide from 7700 to 7844' 08/12/07 Drlg & slide from 7844 to 8043' Rig serv Drlg & slide from 8047 to 8130' Survey - MWD tools malfunction Drlg & slide from 8130 to 8257' Work on MWD tool Drlg & slide from 8257 to 8385' Survey - MWD tools malfunction Drlg & slide from 8385 to 8450' Survey - MWD tools malfunction Drlg & slide from 8450 to 8514' Survey - MWD tools malfunction Drlg & slide from 8514 to 8520' 08/13/07 Drlg & slide from 8520 to 8797' Rig serv Drlg & slide fron 8797 to 8985' Change out kelly saver sub

	Drlg & slide from 8985 to 9143'
08/14/07	Dela 9 alida la 02061
00/14/0/	Drlg & slide to 9206' Rig repair - change pumps
	Drig & slide from 9206 to 9363'
	Rig serv
	Drlg & slide from 9363 to 9772'
08/15/07	Drlg & slide from 9772 to 9992'
	Rig serv, change out control valve for rotary clutch
	Drlg & slide from 9992 to 10338'
08/16/07	Drlg & slide from 10338 to 10652'
	Rig serv
	Drlg & slide from 10652 to 10972'
08/17/07	Drlg from 10972 to 11002'
	Circ Btms up f/trip
	POOH
	Change MWD tools, Lay down mud mtr & pick uo new mtr, change bit
	RIH
	Wash & ream from 10500 to 10600', 10650 to 10740', 10951 to 11002'
	Drig from 11002 to 11018'
08/18/07	Drlg & slide from 11018 to 11059'
	Rig serv
	Drlg & slide from 11059 to 11190'
08/19/07	Drlg & slide from 11190 to 11246'
	Rig serv
	Drlg & slide from 11246 to 11300'
	POOH, mtr failure
	Pull MWD tools , Change out Mud mtr
08/20/07	PU new mud mtr swap out MWD tools
**************************************	RiH
	Kelly up & fill pipe
	RIH to 10964'
	Wash & ream froom 10964 to 11300'
	Drlg from 11300 to 11475'
08/21/07	Drill from 11475 to 11501'
	Rig serv
	Drill from 11501 to 11708'
08/22/07	Drig from 11708 to 11721'
ne mer dindmit tel d	Rig serv
	Drlg from 11721 to 11846'
	Slide drilling from 11846 to 11852'
	Drig from 11852 to 11878'
•	•

 $f_{-}$ 

	ī.
08/23/07	Drig & slide from 11878 to 11940'
	Rig serv
	Drig & slide from 11940 to 12062'
08/24/07	Drlg from 12062 to 12072'
	Circ btms up cond mud spot beads from 12072 to 11072
	POOH
	Lay down 35 jts grade "S 135" DP
	POOH ·
	Lay down directional tools , pick up straight Mtr,Bit, & Teledrift, Function test blind & pipe rams
	Slip & cut Drlg line
	Pick up 35 jts grade *G" DP changed out corrosion ring
	RIH
08/25/07	Test Televistated
00/20/07	Test Teledrift tool
	RIH
	Rig serv RIH, wash 5 jts to Btm
	Rig repair - replace slip dies
	Drig from 12072 to 12124' Work bead sweep
	Drig from 12124 to 12127' Spet Lube books work pins
	Spot Luba beads, work pipe Drig from 12127 to 12129'
	Dig 1011 12127 to 12129
08/26/07	Drlg from 12127 to 12132', can not get Diff pressure to rise acts like no weight on bit
	Spot Lubra beads & work pipe, beads spotted from 11125 to 9125'
	Drlg from 12132 to 12136', try more weight on bit - loosing pump pressure, seems to be a problem downhole
	Circ & cond hole
	РООН
	Lay down mud mtr & pick up fresh mtr & bit
	RIH, break and redope all drill collars
	Fill pipe, break circ
	RIH
	Fill pipe & break circ
	Wash & ream 35' to Btm
	Drlg from 12136 to 12140'
08/27/07	Drill from 12140 to 12175'
	Rig serv
	Drlg from 12175 to 12208'
08/28/07	Drlg from 12208 to 12237'
	Rig serv, unplug standpipe pressure transducer
	Drlg from 12237 to 12266'
	Circ & cond mud, Teledrift survey, drop single shot survey
	POOH f/bit
	Change bit, Function test Blind & Pipe rams, Break down survey tools
	RiH w/bit # 12
BB (	
08/29/07	Rig repair - Water not circulating on brake flanges, Iron roughneck

	RIH
	Wash & ream 30' to btm
	Drig from 12266 to 12340'
	51g 11011 12200 to 12040
08/30/07	Drlg from 12340' to 12517'
	Circe & cond hole
	Wiper trip f/logs
08/31/07	Wiper trip
00/01/01	Circ & cond mud, raise vis to 48 sec
	Drop survey & POOH f/logs
	Run wireline logs w/ Halliburton Wireline, loggers depth 12555'
	Lay down logging tools & rig down loggers
	W/O/O, waiting on sidewall core tools
	Watting of aldewall core tools
09/01/07	w/o/o
	Lay down mud mtr & Teledrift
	RIH w/ bit, SLM, Hole depth adjusted to 12534' as per pipe strap
	Circ & cond mud, unload csg, sort & put on racks, clean , rabbit & strap pipe
	Rig up lay down machine & LDDP
09/02/07	LDDP
03/02/01	Rig repair - Iron roughneck blew Hyd hose
	LDDP
	Pull rotating head & break kelly
	LDDP & DC
•	Pull wear bushing & rig up Caliber casing tools
	Run 5 1/2, 17#, production csg. Work on casing tongs, tongs have caused approx two hrs downtime
	The state of the s
09/03/07	Run 5 1/2 Prod casing
	Rig down csg tools & Rig up BJ cementers
	Circulate & cond hole for cement
	Pump 345 sx PLII + adds 1st stage cement, drop plug
	Displace with 300.8 bbls mud Bump plug 558 psi over
	Drop DV opening tool & open DV tool
	Circulate with rig pumps
	Pump 1005 sx 2nd stage lead & 100 sx 2nd stg tail, Displace w/240.7 bbls H2O, bump plug W 1490 psi over
	Nipple down BOP, set casing , Clean mud pits Rig released @ 0600 hrs 9-3-07
09/04/07	Rig down / wait on trucks
	SDFN
09/05/07	Rig repair - wait on trucks
	SDFN
09/06/07	Rig down, stack rig on 32-7 location, crains did not show up, backyard is gone, derrick is down on stand
08/00/07	need crains to remove derrick,dwks,& unstack sub structure, blocks unstrung.
	SDFN
09/07/07	Rig down - stack rig on 32-7 location
	SDFN
i	•

09/07/07 Rig down - stack out rig

### WELL COMPLETION REPORT MILLER DYER & CO, LLC UTE TRIBAL 6-16-14-20 SE/NW SEC 16, T 14S -R 20E UNITAH COUNTY, UTAH

#### September 11, 2007

Move on and spot Leed rig 677. Scrape mud off location into pit. Spot pipe racks and catwalk. Cameron made final cut and installed tbg head on wellhead. Test to 5000 psi. Held. SWIFN

In A.M. Install dead men. Rig up. Unload 2 7/8" tbg on racks, pick up bit and tbg.

#### **September 12, 2007**

175 psi on surface. Set dead men. Rig up Leed rig 677. Unload 381 jts N-80 @ 7/8" EUE tbg onto pipe racks. Remove thread protectors and tally tbg. NU BOP. Rig up tbg equipment and floor. Pick up (used) 4 ¾" Varel L2 Ser# 990027 bit with Nabors bit sub. Pick up tbg. RIH Pick up 210 jts. 6900' +-. SWIFN In A.M. Finish picking up tbg. Drill DV tool.

#### September 13, 2007

Psi on surface csg. Tbg and csg dead. Finish picking up tbg. Tag cement above DV tool @ 10358' KB on jt# 315. Install Washington rubber. Rig up pump, tank and swivel. Start drilling cement. 3 bpm @ 800 psi. 6000 lbs slackoff, 75 rpm @ 1600 psi torque. Find the DV tool @ 10381' KB on jt# 316. Drill DV tool and wiper plug. Took 31 minutes. Circulate clean. Set back swivel and remove Washington rubber. Pick up tbg. Tag bottom @ 12495' Kb on jt# 380. 205' below projected perfs. Roll hole. Roll 50 bbls mud to pit. Lay down 2 jts. SWIFN In A.M. POOH. Trip casing scraper.

#### **September 14, 2007**

175# on surface csg. 0 psi on csg and tbg. Finish POOH. Pick up 5 ½" csg scraper with 4 ¾" bit. RIH Tag bottom @ 12495' KB on jt# 380. Circulate bottoms up. Little bit of mud and aluminum in returns. Lay down 8 jts. POOH with 372 jts and csg scraper. Pull 140 jts. SWIFN

In A.M. Finish pulling tbg. Bond log and perforate.

#### **September 15, 2007**

175 psi on surface. 0 psi on csg and tbg. Finish POOH. Stand 372 jts in derrick. Lay down bit and csg scraper. Rig up JW Wireline. Bond log well holding 1000 psi pressure on csg with rig pump. Coorolate to HES open hole log dated 8/31/07. Logger's TD 12512' KB. Run Cement Bond CCL, Gamma Ray VDL from TD(12512') to surface. Top of cement was surface. Excellent cement bond from 12512' to 5980'. Good cement bond from 5980' to surface. Lay down logging tools. Pick up perforating gun. RIH Perforate from 12282-12290' using 3 3/8" slick guns, 23 gram charges, 37" PEN, 0.42"

EHD, 120 deg phasing, 4 SPF-32 total. POOH. All shots fired. Rig down wireline. Well dead. SWIFN

In A.M. Run tbg and packer. Swab

#### **September 16, 2007**

Well on slight vacuum. Pick up Nabors 10K 2 7/8" AE-1 Fullbore Arrowset packer with 2 7/8" SN. RIH. Fluid level about 80'. Set packer @ 10240' KB with 372 jts. 42' above perforations. Rig up to swab. Swab. SFL was surface. Made 9 swab runs. 65 bbls total. Volume to top of perfs is 71.8 bbls. 6.8 bbls short of load. Well swabbed right down. Ending fluid level was 11800'. Swabbed 100% water first 6 swabs. Last 3 swabs swabbed gas cut fluid, but no blow between runs. SWIFN In A.M. Check pressures and swab.

#### **September 17, 2007**

Slight blow on csg. 300 psi on tbg. Blow well down. Blew right down to slight blow. Swab. SFL was 7500'. Swab well down. 2 runs. 15.50 bbls. 80.5 bbls total. 9 bbls over tbg volume. Swab gas cut water with a little bit of LCM on top of first swab. No blow on tbg between runs. 3<sup>rd</sup> run was dry. Have trouble getting down with sinker bar. Remove swab cups. Run sinker bar to SN. Did not have any trouble getting down. Made 4<sup>th</sup> swab run. Recovered 2.6 bbls. 83.1 total. 11.5 bbls over load. Gas cut water. Made 3 more swab runs. 1 per hr. All dry runs. Lay down swab. SWIFN

In A.M. Check pressures. Pull swab. Release packer. Pull tbg. Perforate.

#### **September 18, 2007**

Slight blow on casing. 310 psi on tbg. Blow well down. Swab. SFL was 8500'. Pull 1 swab. 7 bbls gas cut water. 90 bbls total. 18.2 bbls over load. Blow on tbg after swab. Lay down swab. Pump 25 water bbls down tbg. Try to release packer. Would not, no mandril travel. Still too far out of balance. Pump another 20 bbls down tbg. Able to release packer. Lay down 2 jts. Jts are slightly bent. Notice that the elevators on the bales on Rig's blocks are not hanging level. Bales appear to be very worn. Order new bails and elevators. Swab well down while waiting for bales. Swab 43 bbls out of well. Put on new bales. Elevators hanging level. Finish pulling tbg. Lay down packer. Stand 370 jts in derrick.

In A.M. Perforate upper bench of bottom zone. Run packer. Swab. Acidize Thursday morning.

#### September 19, 2007

0 psi on well. Rig up JW Wireline. Pick up perforating gun. RIH. Fluid level was 4360' from surface. Perforate upper bench of lower zone from 12256-12261' using 3 3/8" slick guns, 23 gran charges, 120 deg phasing, 37" Pen, 0.41" EHD, 4 spf, 20 shots total. POOH. Still no pressure on well. Rig down wireline. Pick up Nabors 5 ½" 10K fullbore Arrowset AE1 packer with 2 7/8" SN. RIH with tbg. Set packer @ 12208'KB with 371 jts. Rig up to swab. SFL was 3000'. 2<sup>nd</sup> run- 4500'. 3<sup>rd</sup> run- 5700'. 4<sup>th</sup> run-5700'. Fluid level then stayed between 5000 and 6000'. Started swabbing gas cut water after 3<sup>rd</sup> run. No blow on tbg between runs. Very warm fluid. Made 9 swab runs. Swab back 86 bbls. Checked csg after last run. Csg on vacuum. Check weight on packer. Have 25,000 lbs on

packer. Put 40,000 lbs on packer. Try to load the csg. Pump 120 bbls water down csg. Tbg starting to blow. Csg on vacuum. Packer gave up quit holding. SWIFN In A.M. Release packer. Round trip for new packer. (BJ could not do acid job until Friday)

#### September 20, 2007

20 psi on tbg. Csg on vacuum. Blow down tbg. Release packer. Lay down 1 jt. POOH with 370 jts and packer. Lay down packer. Packer rubbers are gone. Pick up Nabors 5 ½" 10K Arrowset fullbore AE-1 packer. RIH with tbg. Set packer @ 12208' KB with 371 jts. 48' above top perfs. Load csg with 45 bbls water. Test packer to 500 psi. Held. Rig up to swab. Swab. SFL was 2000'. Rubber from packer elements in the tbg. Have trouble getting down. Make 8 swab runs. Ending fluid level was 9000'. Well swabbed right down. Very gassy but no blow between runs. Swab 52.5 bbls. 100% water. Load is 60.1 bbls SWIFN

In A.M. Check pressures, Swab, acidize with BJ.

#### September 21, 2007

175 psi on tbg. Slight blow on csg. Blow tbg down. Pick up swab. Swab, SFL was 6700'. Made 3 runs. Swab well dry. Swab 12.5 bbls. 65 bbls total. 4.9 bbls over load. Gassy fluid. 100% water. Slight blow on the between runs. Lay down swab. Rig up BJ. Acidize perfs from 12256-12261' and 12282-12290'. Test lines to 6000 psi. Pump 10 bbls water with biocide, 300 gals 7 1/2% HCL acid with 15 gal Ferrotrol 300L, 2 gal NE-940, 3 gal CI-25, 2 gal Claytreat 3C, 900 gals acid with 100 7/8" 1.3 sg spaced out evenly, 300 gals acid, flush with 73.6 bbls water. Took 74.4 bbls to catch pressure. 1.8 bbls over capacity. Pressure up to 4260 psi. Broke back to 3640 psi @ 4.0 bpm. Slowly climbed up to 3900 psi. No reaction or break with the acid. Did see some ball action but did not ball out completely. Increased rate to 5.1 bpm and pressure climbed to 4250 psi. Flushed acid to bottom perf @ 12290' plus 1 bbl. Total pumped 124 bbls. ISIP was 3053 psi. 5 min-2004. 10 min-1720. 15 min-1332. 30 min -864. 60 min-190 psi. Well on vacuum in 75 min. Leave shut in for 90 min. Pick up swab. Start swabbing. Leed operator went too deep on 1st swab. Tried to pull 4000' of fluid with swab. Took 3 hrs to get swab out of hole. Finally got a cup to roll over and were able to pull out of the hole. Continue swabbing. Make 10 runs. Swab 74 ½ bbls. 49.5 bbls left to recover. Starting to get acid back on last swab. Ending fluid level was 7000'. Lay down swab. SWIFN In A.M. Check pressures, swab.

#### September 22, 2007

300 psi on tbg. Slight blow on csg. Blow tbg down swab. SFL was 4800'. Made 6 swab runs. Ending fluid level was 9000'. Swab 44.5 bbls. 119 bbls total. 5 bbls of load left to recover. Gassy acid water. Blow between swab runs on last 3 runs. Lay down swab. SWIFW Travel back to Roosevelt.

#### **September 24, 2007**

Slight blow on csg. 2525 psi on tbg. Blow tbg down. Took 45 min to blow down tbg. Blew down to strong blow. ND Washington head. NU tree onto BOP. Rig down and

move off Leed rig 677. Very muddy at top of hill. Wait for roads to dry. Leave well shut in.

9/25/07 Tubing pressure-1950 psi. 9/26/07 Tubing pressure – 2950 psi 9/27/07 Tubing pressure-3300 psi 9/28/07 Tubing pressure 3350 psi.

#### October 2, 2007

3375 psi on tbg. Slight blow on csg. MORU Leed rig 677. Spot pipe racks and cat walk. Open tbg to pit on 16/64" choke. Flow test well. Spot flowback tank. Move 3 RNI tanks from 15-25 to location. Fill with water.

12:50 hrs---3375 psi 13:30 hrs---800 psi 14:50 hrs---275 psi 15:50 hrs---110 psi 16:50 hrs---55 psi 15:20 hrs---48 psi

Leave well open to pit on 16/64" choke

In A.M. Check pressure, swab, release packer, POOH laying down tbg.

#### October 3, 2007

FTP was 38 psi on 16/64" choke. Slight blow on csg. Finish blowing well down. ND tree. RU to swab. Starting fluid level was 2000'. 100% gas cut water. Swab well down in 5 runs. Swab down was 21 bbls. 140 bbls total(includes swabbing after acid job). 18 bbls over load. Strong blow on well. Wait 1 hr. Make swab run. Dry run. Wait 2 hrs. make swab run. 500' of fluid. 2.75 bbls. 23.75 total today. 142.75 total. 20.75 bbls over load. Lay down swab. Pump 60 bbls water down tbg. Release packer. Pick up 3 jts tbg. Run packer thru perfs to ensure all frac balls off perfs. POOH with 374 jts and packer. Lay tbg down on pipe racks. Lay down 31 jts. SWIFN In A.M. finish laying down tbg

#### October 4, 2007

Tbg and csg on slight vacuum. Remat rig(one pad sinking). Load out pump and tank. Haul to Roosevelt yard. Finish laying down tbg. Lay down packer. SWIFN In A.M. Load out tbg equip. ND BOP, NU frac valve, RDMO

#### October 5, 2007

15 psi on well. Blow well down. Load out the equipment and floor. ND BOP. NU Stinger 7 1/16" 5000 psi frac valve. RDMO Leed rig 677. Move pipe, racks and catwalk to side of location. Move Premier's flowback manifold from 15-25 to location. Ready to frac on 10/6/07

#### October 6, 2007

Rained and snowed last night. HES not on Location until 10:30 A.M. Rig up Stinger 10K wellhead isolation tool. Rig up HES and Praxair(CO2). Test lines to 7000 psi. Frac

Navajo zone 12256-12261' and 12282-12292' with 22219 gal(529 bbls) pHaser Frac fluid system and 143 ton CO2 containing 5000 lbs of 100 mesh and 67,800 lbs of 20/40 ceramic frac sand. Pump job as follows. Loaded the hole and broke formation with 1000 gals water. Initial break was 3666 psi @ 7.8 bpm. Initial ISIP was 3350. Frac grad-.706. Went ahead and pumped stages 2-8 as per design(dated10/06/07) From 0.5 lb thru 4 # sand. Flush frac to top of perfs with Co2 and water then pumped 500 gal of straight water. Avg rate was 4602 psi. Slurry rate-10.61 bpm. CO2-16.27 bpm. ISIP was 5604 psi. 5 min-3645 psi. 10 min-3472 psi. 15 min-3256 psi. Frac grad-0.89. Had problems with HC-2 LA pump during 100 mesh stage. Changed pumps-worked better. No other problems. Increase in surface pressure during flush due to change in hydrostatic pressure. Max pressure was 5700 psi. Rig down HES. Rig down Stinger. Rig up flowback manifold and line to tank. Initial pressure 1975 psi.

Time	Ducaguma	Cl1	וזמת	ממיזי	DI TO	
18:15	Pressure	Choke	BPH	TBR	BLTR	
	1975	12/64	0	0	529	
19:00	1500	T 1 A	6	6	523	
		Line to tank fr				
20:00	1100	14/64	10	16	513	
21:00	900	14/64	10	26	503	
No sand, fi	rac gell and CC	02			*	
23:00	750	14/64	15	41	488	
24:00	675		6	47	482	
October 7	, 2007					
Flowing N	avajo frac bacl	k. 481 bbls left	to recover.			
_	_					
24:00	675	14/64	0	47	482	
01:00	600		4	51	478	
Not as m	uch water and	still losing pre	ssure. Go to 16	5/64 choke		
02:00	650	16/64	8	59	470	
04:00	1000		16	75	454	
05:00	1225		6	81	448	
	Line froze off-went to 14/64 while fixing 16/64 side					
06:00	1450	16/64	10	91	438	
					,	
Building	pressure, no sa	nd, less gel, me	ore water, very	wet gas		
09:00	1500	16/64	15	106	423	
Not bringing much fluid now, no sand, increase choke to 18/64						
10:00	1525	18/64	5	111	418	
Still building pressure change choke to 20/64						
11:00	1510	20/64	4	115	414	
			•	113	414	
Well is just not making as much fluid. Drying up!						
12:00	1525	20/64	2	117	412	
13:00	1525	20/64	0	117	412	
14:00	1525	20/64	0	117	412	

2

119

410

17:00

1550

20/64

Choke freezing up. Went to 22/64. froze up in 5 sec. try 24/64- same results Went to 36/64- same open well on 1" unloaded 10 bbls sewer smelling nasty Black hydrates-no sand in it. Started making water again. Open well back on 20/64 choke.

18:00	1500	20/64	15	134	395
21:00	1525	20/64	15	149	380

#### October 8, 2007

Time	Pressure	Choke	BPH	Tbbls	BLTR
07:00	1975	20/64	235	384	145

Well was blowing dry CO2 when I got there. Started unloading clear water again.

Figure well made 235 bbls overnight. Pressure is increasing.

15:00 1975 20/64 30 414 115

Less CO2 and less water

#### October 9, 2007

Time	Pressure	Choke	BPH	Tbbls	BLTR
05:00	1900	20/64	mist	414	115
12 noon	1100	20/64	mist	414	115

The well was flowing at 1900 psi as of 5 am. When a different field foreman checked the well at noon, the pressure was reported as 1100 psi on the 20 choke. There may be some discrepancy resulting from the change in personnel or gauges. The well was then blown to atmosphere wide open on a 2" line due to suspected liquid loading and made a few slugs of water. After 10 minutes on the 2", the wellhead pressure had decreased to 600 psi. The well was then put on a 16/64 choke and had built to 1050 psi within a few minutes. A wellhead gas sample taken today indicated 10.1 % CO2.

#### October 10, 2007

Time	Pressure	Choke	BPH	Tbbls	BLTR
12 noon	1400	16/64	mist	414	115

#### October 11, 2007

Time	Pressure	Choke	BPH	Tbbls	BLTR
12 noon	1375	16/64	mist	414	115
A wellhea	d gas sample	taken todav	indicated (	5.1 % CO2.	

#### October 12, 2007

Time	Pressure	Choke	BPH	Tbbls	BLTR
12 noon	1350	16/64	mist	414	115

#### October 13, 2007

Time	Pressure	Choke	BPH	Tbbls	BLTR
12 noon	1375	16/64	mist	414	115

The well was shut-in today. The rig will be moved back on location on Monday to run the tubing and packer and enable a better Navajo test.

#### October 15, 2007

MORU Leed rig 677. Open well to pit on 16/64" choke. Leave well flowing to pit overnight. Move and spot pipe racks and cat walk. Load 381 jts 2 7/8" tbg onto racks. In A.M. Kill well, run tbg and packer

#### October 16, 2007

Well flowing 800 psi on 16/64 choke. Open up on 36/64" choke. Rig up D&M hotoil service. Control well with 180 bbls water. Still had 200 psi on it. Blow down to pit. Well died. ND frac valve. NU BOP. Rig up tbg equipment and floor. Pick up Nabors 10K Arrowset AE1 Fullbore packer, 2 7/8" XN nipple, 1 jt 2 7/8" EUE Tbg, X nipple, 2 7/8 N-80 EUE Tbg. Pick up tbg. Run 34 jts. Well flowed again. Control well with 70 bbls water. Run 1 jt. Well un loaded. Flow well to pit. Would not die. Leave well flowing to pit on 36/64" tbg. Ran total of 34 jts. 1100' approx In A.M. Kill well. Finish running tbg and packer, flowtest.

#### October 17, 2007

50 psi on tbg flowing to pit on 36/64" choke. 150 psi on csg. Rig up Adler Hot Oil Service. Pump 120 bbls water down tbg. Well went on vacuum after 20 bbls. Continue picking up tbg. 191 jts in tbg started flowing. Spot kill tbg with 30 bbls water. Install washington rubber. Csg satrted flowing. Continue running tbg. 300 jts in tbg flowed. Spot kill tbg with 25 bbls water. Continue running tbg. 329 jts in @ 10828' KB. 1328' above top Navajo perf. Tbg started flowing again. 5 pm time. We would not have time enough to kill tbg, finish running tbg, set packer and swab well in tonight for flow test. So set packer. Shut in csg. Hook up tbg to flowback manifold. Unload water out of tbg to pit. Leave well open to pit flowing on 12/64" choke. Started at 400 psi at 17:00 hrs. 18:00 hrs- 1225 psi 995 MCFD rate

Do flow rate test.

#### October 18, 2007

Tbg had 1950 psi flowing on 12/64" choke. 1576 MCFD. 100 psi on csg. Same as last night. 06:30 hrs Change choke to 16/64" choke. 07:00 hrs-1750 psi- 2599 MCFD rate.

Time	Choke	Pressure	Rate(MCFD)	Comments
06:30	12/64	1950	1576	Dry gas
07:00	16	1750	2599	Dry gas
07:30	16	1650	2452	
08:00	16	1600	2378	Water mist(part time)
08:30	16	1500	2231	
09:00	16	1400	2084	Mist of water(part time)
09:30	16	1350	2010	Light water
10:00	16	1300	1937	dry gas
10:30	16	1250	1863	
11:00	16	1200	1789	watermist(occasionaly)
11:30	16	1200	1789	
12:00	16	1200	1789	
12:30	16	1200	1789	
13:00	16	1200	1789	
14:00	16	1200	1789	
15:00	16	1200	1789	

Blow well down. Rig up Adler Hot Oil Service. Kill the with 40 bbls water. Pump 40 bbls water down csg. Release packer. Finish running the Run 41 more jts. Set packer @ 12178' KB with 370 jts. Rig up the to flowback manifold. Unload the to pit. Flow the on 16/64" choke to pit. 19:00 hrs- 1400 psi-2061 MCFD. Flow well to pit all night. In A.M. Set pressure bombs with slickline.

#### October 19, 2007

06:30 hrs. 1050 psi on tbg flowing on 16/64" choke. 950 psi on csg. Very wet gas. Flow well to pit until 10 A.M. Pressure still @ 1050 psi. Still wet. SWI. Rig up Production Logging Services. Pick up pressure bombs. RIH. Get gradient pressure every 2000' on way in. Set guages in X nipple @ 12143' KB. Shear off. POOH. Rig down slickline. Hook tbg up to manifold. 1230 hrs- Flow tbg on 16/64" choke to pit. Starting pressures was 1800 psi. 18:00 hrs. SWI 1100 psi on tbg. Catch 2 gas samples and water sample. Leave well shut in until 8A.M. Monday Oct 22. Check pressures throughout weekend.

#### October 20, 2007

Check pressures on pressure buildup.

Time	Tbg pressure	Csg pressure
07:00	2300	950
12:00	2350	950
18:00	2375	950

#### October 21, 2007

Check pressures on pressure buildup. 07:00-Tbg- 2475 Csg -950

12:00 Tbg- 2500 Csg-950

18:00 Tbg- 2525 Csg-950

In A.M. Check Pressure, fish pressure guages, kill well, Pull tbg and packer.

#### October 22, 2007

950 psi on csg. 2625 psi on tbg. Rig up Production Logging Services Inc. Fish pressure guages. Take gradient pressure readings every 2000' on way out of the hole. Rig down slickline. Blow well down. Kill csg with 50 bbls water. Kill tbg with 60 bbls water. Release packer. Lay down 8 jts. POOH with 362 jts and packer. Well stayed dead the whole trip out of the hole. Lay down packer. SWIFN. In A.M. Set bridge plug and perforate Entrada

#### October 23, 2007

750 psi on well. Rig up J W Wireline. Pick up HES 8K EZ Drill composite frac plug. RIH Corolate to JW Wireline log dated 9/15/07 Set Bridge Plug @ 12150' KB. 106' above Navajo perfs. 92' below Entrada perfs. Perforate Lower Entrada zone from 12037-12042', 12024-12029', 12014-12019', 12003-12008', 11994-11999', 11983-11988', 11952-11957' using 3 1/8" slick guns, 23 gram charges, 0.42" EHD, 60 deg phasing, 4 SPF, 120 shots total. POOH. All shots fired. Rig down wireline. Perforated bottom 3 zones with pressure on wellhead. No change in pressure after perforating. Bled well off for last 4 zones. Slight blow on well before we perforated. No change after perforating. Pick up Nabors 5 ½" 10K Arrowset AE-1 Fullbore packer. RIH with tbg. Had to work on rig slips and tongs. Set packer @ 11913' KB with 362 jts. 39' above top Entrada perf. Rig up to swab. SFL was 5000'. Pull one swab. Swab 10 bbls. Gassy water. No blow after run. SWIFN.

In A.M. Swab well down. Acidize with Superior.

#### October 24, 2007

1025 psi on tbg. 450 psi on csg. Blow down tbg. Dry gas. Blew down to slight blow. Swab. Hit fluid @ 4000' but it was scattered up and down tbg. Pretty solid @ 7000'. Where we left it last night. Swab well dry. 19 bbls. Slight blow after every run. Make another swab run. Dry. Rig up Superior. (they were lost, had to find them). Acidize Lower Entrada perfs(12042-11957') with 1500 gallons 7.5% HCL acid. Pump 10 bbls water ahead. 300 gallons 7.5% HCL acid, 900 gallons acid with 200 7/8" 1.3 spec.grav. balls spaced evenly throughout the 900 gallons, 300 gallons acid. Then displace with 73 bbls water. To bottom perf @ 12042' plus one bbl. Caught pressure @ 67 bbls. 2 bbls short of tbg volume. Pressured up to 3100 psi. Lost all pressure(packer failure or bridge plug gave out.) Went ahead and pumped flush water volume. Caught pressure again @ 105 bbls pumped. Pressure increased to 5.2BPM @ 1720 psi. Finished job. Total fluid pumped 118.5 bbls. ISIP was 65 psi. Well went on vacuum in 25 seconds. When pressure went to zero csg pressure was 150 psi. Down from 450. I blew csg down. Steady blow on csg. As soon as quit pumping. Blow quit. Packer or bridge plug failure. Release packer. All the weight was still on packer. Run 7 jts back in well Tag plug@ 12150' KB. Bridge plug had not moved. Lay down 1 jt. Set packer@ 12125' KB. 25' above bridge plug and 83' below perfs. Pump down thg. The loaded with 8 bbls. Able to pump 3.0 BPM @ 850 psi. Steady blow on csg while pumping. Quit pumping blow on csg quits. Release packer.

Lay down 6 jts. Set packer@ 11913'KB. 44' above top perf. Pump down csg. Took ½ bbl to load csg. Able to pump down csg at 3 BPM @ 850 psi. Same rate and pressure as when pumping down tbg. Blow on tbg while pumping down csg. Release packer. Run 5 jts in hole. Packer @ 12078' KB. 36' below perfs. Roll hole with 300 bbls water. Acid was partially spent with some acid gas. Lay down 5 jts. Try to do breakdown. Pump down tbg. Hole was loaded. Pump 30 bbls total. Start @ 4.2 BPM @ 2540 psi. Increased rate to 5.3 BPM @ 3025 psi. No break but was able to pump into formation. Shut down ISIP was 1700 psi. 5 min-1360 psi. 10 min-1120 psi. 15 min-950 psi. Bleed well down 4 bbls. Rig down Superior. Rig up to swab. Start swabbing. SFL was surface. Swab well down to 4200'. Csg on vacuum. Slight blow on tbg after every run. Swab gas cut water. Slight trace of acid. Swab 114 bbls. Set back swab. SWIFN In A.M. Check pressures. Swab

#### October 25, 2007

1275 psi on tbg. 800 psi on csg. Blow tbg down. Blew down in 3 minutes. Rig up to swab. Swab. Starting fluid level was 2700'. Very gas cut water. Made 5 swab runs. 24 bbls. 138 bbls total. Strong blow on well after every run. Continous blow. Rig crew missed flag on 5th run. Ran the sinker bar into the oil saver. Parted sand line @ the tbg board. Sand line came over the crown. Nobody got hurt!! Sinker bar got stuck in lubricator. Did not drop anything down hole. Lay down lubricator and sinker bar. Enough swabbing with this crew!! Too many miscues!! Bled off casing. It was down to 600 psi. Took 15 min. Lot of gas volume. POOH laying down tbg on pipe racks. Lay down 362 jts(381 total) and packer. No rubbers on packer. Load out tbg equipment and floor. ND BOP. NU frac valve. SWIFN In A.M. RDMO Leed rig Move pipe and racks

#### October 26, 2007

1075 psi on well. RDMO Leed rig 677. Move rig up to top of hill. Move tbg, pipe racks and cat walk to side of location. Finish filling frac tanks. Ready to frac on 10/27/07 In A.M. Set another composite bridge plug. Frac Entrada zones.

#### October 27, 2007

1500 psi on well. Rig up Stinger wellhead isolation tool. Rig up Haliburton. Lone Wolf had flat tire. 3 hrs late. Hang lubricator and sheive off of their crane. Lone Wolf crane broke down. PTO went out. Cannot get to lubricator or sheive safely. 65' in the air. Stinger would not let us use their crane. HES crane too small. Order new crane. Rig up new Lone Wolf crane. Pick up HES 8K 5 ½" FAS DRIL composite bridge plug. Set bridge plug @ 12140' KB. 10' above 1st plug and 98' below Lower Entrada perfs. POOH. SWIFN

In A.M. Frac Entrada, set plug, perforate, frac Upper Entrada.

#### October 28, 2007

1740 psi on well. HES, Stinger and Lone Wolf startup. Test lines to 6600 psi. Frac lower Entrada(11952-12042) using pHaser fluid system. Pump stages 1-9 as per frac design. Pump 5100 lbs 100 mesh frac sand and 92600 lbs 20/40 ceramic frac sand. Average rate was 30.8 BPM. Sluury rate- 13.3 CO2 rate – 18.0 Avg. Treating pressure was 4413 psi.

Had trouble with keeping blender tub levels during 3 lb stage. Trouble with valve. Repair valve. Lost sand concentration. Regained level, continued job. ISIP was 3010 psi . 0.68 frac gradient. 5min-2650 10 min-2446 15 min-2297 psi. Shut well in. Rig up Lone Wolf. HES CO2 valve leaking. Froze off wellhead. Dig out ice and dump methanol. Pick up HES 8K EZ Dril Flowthru composite frac plug with 10' perforating gun. RIH. Cannot get thru wellhead. Ice. Pump 10 bbl water. Still cannot. Set weight on ice plug and have HES pump perforating gun thru plug. Went thru. RIH Set plug @ 11940' KB. Plug did not set. Lost 50 lbs of weight(norm 60-80 lbs). POOH. Order new plug. Plug rubbers were swelled out. Wait on new plug. Pick up new composite plug. RIH Set plug @ 11940' KB. 12' above Lower Entrada perfs and 20' below upper Entrada perfs. Perforate Upper Entrada from 11910-11920' KB using 3 1/8" slick guns, 0.42" EHD, 23 gram charges, 120 deg phasing, 27" PEN. Prior to shooting perforating gun have HES pump 1/2 BPM water. Shoot gun. POOH All shots fired. Rig down Lone Wolf. Hook HES up to wellhead. Frac Upper Entrada zone(11910-11920') using pHaser fluid system with CO2. Pump stages 1-9 as per frac design. Pump 2900 lbs of 100 mesh and 31,500 lbs of ceramic frac sand. Average Rate was 18.9 BPM(11.8 CO2, 7.1 fluid). Avg pressure was 3930 psi. Formation broke @ 5023 psi. ISIP was 3320 psi. 0.711 frac gradient. 5 min-2836. 10 min-2555. 15 min-2584. Had trouble maintaining correct CO2 rate. Pumps would not cooperate. Job went real smooth. Shut frac valve. RD HES. Rig down Stinger. Rig up flow back manifold. Fluid to recover. 1st stage-645 bbls. 2nd stage-356 bbls. 1001 total. Start flow back 19:15 hrs. 1775 psi on 14/64" choke. 100 % water to start with.

October 29, Flow Back	2007	•			
10:00 am	24ck	700 psi	no fluid	2.4 mmcfd	
11:00 am	24ck	750 psi	no fliud	2.5 mmcfd	
12:00 pm	24ck	850 psi	no fluid	2.9 mmcfd	
1		•			
Flow Back (c	ont)				
1:00 pm	24ck	1050 psi	21bbls	3.6 mmcfd	
2:00 pm	24 ck	1150 psi	42bbls	3.9 mmcfd	
3:00 pm	24ck	1450 psi	63bbls	4.9 mmcfd	
4:00 pm	24ck	1700 psi	42bbls	5.8 mmcfd	
5:00 pm	24ck	1750 psi	47bbls	5.9 mmcfd	
702 Bbls to b	e recove	ered			
October 30,	2007				
1:00 am	24ck	2100 psi	no fluid	7.1 mmcfd	
6:00 am	24ck	2175 psi	no fluid	7.4 mmcfd	
10:00 am	24ck	2300 psi	no fluid	7.8 mmcfd	
4:00 pm	24ck	2225 psi	no fluid	7.6 mmcfd	14% CO2
9:00 nm	24ck	2225 psi	no fluid	7.6 mmcfd	

October 31, 2	2007				
1:00 am	24ck	2200 psi	no fluid	7.5 mmcfd	
6:00 am	24ck	2200 psi	no fluid	7.5 mmcfd	
10:00 am	24ck	2150 psi	no fluid	7.3 mmcfd	
5:00 pm	24ck	2150 psi	no fluid	7.3 mmcfd	
9:00 pm	24ck	2125 psi	no fluid	7.2 mmcfd	
November 1,	2007				
1:00 am	24ck	2100 psi	no fluid	7.1 mmcfd	
6:00 am	24ck	2050 psi	no fluid	7.0 mmcfd	
10:00 am	24ck	2040 psi	no fluid	6.9 mmcfd	Gas sample
5:00 pm	24ck	2040 psi	no fluid	6.9 mmcfd	
9:00 pm	24ck	2000 psi	slight mist	6.8 mmcfd	
November 2,	2007				
1:00 am	24ck	1950 psi	slight mist	6.6 mmcfd	
6:00 am	24ck	1900 psi	slight mist	6.5 mmcfd	
10:00 am	24ck	1900 psi	slight mist	6.5 mmcfd	
4:00 pm		•			Gas sample, SI well

Work Over Report Miller Dyer & Co, LLC UTE Tribal 6-16-14-20 SENW Sec 16, T14S-R20E Uintah County, Utah

## December 17, 2007

SICP 3100 psi. RU Wireline truck and lubricator with grease injection . Attempt to make gauge ring run. Couldn't get frac valve open all the way—appear to have some ice behind gate. RD lubricator, crane and wireline truck. Move in, spot rig. SDFN @ 5:30 pm.

## **December 18, 2007**

SICP 3075 psi. Repaired rig governor hose. RU Stone Well Service Rig 3. RU Well head heater. Dumped methanol down master valve, onto frac valve. Heated well head. Was able to get 38 full turns on frac valve – should be fully open. Remove snow from cat walk, tubing & flow back manifold. SDFN @ 4:30 pm.

## December 19, 2007

SICP 3150 psi. Open Frac Valve – leaking badly at packing. Closed valve – still leaking. Worked valve – still leaking. Opened well on 17 choke for 30 min. Pressure

down to 3050 psi. Leak stopped. MU Stinger isolation tool & run thru frac valve. Repack valve stem. Leak stopped. RU Cased Hole Solutions – RIH with Halliburton 10 K CBP. Set plug @ 11,800'. Casing pressure 3185 psi on gauge in logging truck. POH, bleed off pressure to 2270 psi. Monitored pressure for 15 min. – 2278 psi – plug holding. Closed frac valve & RD Cased Hole Solutions. MU Master Valve above frac valve. SDFN @ 10:30 pm.

## December 20, 2007

SICP 2200 psi. Bleed off casing pressure. Pump 120 bbl water down csg. and monitor pressure for 30 min. – dead. Remove Stinger Frac Valve, NU Spool, Pipe & Blind Rams and Hydril BOP, RU Floor. MU 4 ¾" Blade Bit (.33"), Conventional Bit Sub (1.04"), 1 jt. 2 7/8" 6.5#, N-80, LTC tbg (32.90"), 1 - 2.313" XN Nipple w/PXN flow thru plug installed – nipple no-go ID 2.05" (1.30"), 1 jt 2 7/8" tbg (32.91"), 1 - 2.312" X Nipple (1.25") & 28 jts 2 7/8" tbg (918.73"). MU tbg valve, close BOP & csg valve. SDFN @ 7:00 pm.

## December 21, 2007

SICP 50 psi – blow down to pit. Snowed over night – cleared pipe rack and rig. Had to get the road into location plowed. Tally, PU & RIH with 2 7/8" tubing – LD 1 crimped jt (32.92'). Have 358 jts tbg in hole – bit @ 11772'. Install tbg valve, close csg valves and close BOP. SDFN @ 7:00 pm.

## December 22, 2007

SICP 40 psi – blow down to pit. – 7 degrees with light wind. Thaw water tank valve, RU Weatherford foam unit, MU Washington Head Rubber, RU Power Swivel. Pump air and water down tbg. Blow water from well. Run in to Kill Plug @ 11,800°. Drill plug, RIH, tagged up @ 11913°, about the top of Upper Entrada perfs. Clean out to composite BP @ 11940°. Drill plug & circ down to 11971° (19° below top of lower Entrada perfs). Flow back manifold froze off. Cleared manifold – unable to drill below 11971° – dragging slightly pulling up – stacking out trying to get back to 11971°. Can't rotate, Power Swivel torquing – stalling out. Attempted to pull above top perfs for the night. Pulled 1 jt, Washington Rubber washed out. Closed pipe rams – not holding. Tried to close hydril – hydraulic hose nipple cracked – changed hoses with gas blowing thru Washington head. Closed Hydril and manually locked pipe rams – well not leaking. Have 363 jts. tbg. in well – bit @ 11936. SDFN@ 7:00 pm.

## **December 23, 2007**

3000 psi SICP. Only have 2 of the rig hands and the TP. Temperature about 15 degrees. RU well heater and get heat on the BOP's & valves. Attempted to PU on the BOP's & pull slips to remove Washington Head – stuck – no stretch. Finally warmed up enough, able to pull slips. Remove Nabors Washington Head and MU Weatherford Head and Spool. Pulled 2 jts the. Closed Hydril, removed Washington Head Rubber, MU landing donut RI, and attempt to land the — could not get the donut thru the Hydril. Measurement indicates we are stacking out 6" above the bottom of the Hydril. Worked Hydril & Pipe Rams and made several attempts to run thru Hydril —not successful. Close Hydril, close

and lock Pipe Rams. TIW valve in tbg, Well secure. SD until Thursday 12/27/07. Going to try to pump methanol thru BOP's to clear ice blockage.

## **December 27, 2007**

Temperature 7 degrees below zero. SICP 2700 psi, SITP about 40 psi – blew down tbg pressure. Started WH heater. Opened casing to pit to blow down pressure – have to change Washington Head Rubber – Producing a ½" to 1½" stream of water. Pulled Rubber and landing donut. The packoff rubber on the donut is torn into 2 pieces. MU new Washington rubber and tried to run thru Hydril with the donut (without packoff) to see if hydril is relaxing. Could not run thru hydril. Going to have BOP hand out in the morning and also a hot oil truck to pump 5-10 bbl. 200 degree water thru BOP's. Leaving the well head heater going over night. Flowing Casing Pressure down to 200 psi and water production had stopped. Closed & Locked Pipe Rams, Closed Hydril, SI casing.

## **December 28, 2007**

Temperature 4 degrees below zero. SICP 2400 psi; SITP about 40 psi – blew down tbg. pressure. Opened well to pit & blew down pressure. Hook up Adler Hot Oiler & pump 25 bbl hot water thru port below Washington head & across BOP's. Broke lines – well on slight vacuum. Removed Pipe Ram rubbers – on one of the rubbers, the metal plate was bent and the bolt holding the rubber in place was pulled & bent. Replace rubbers. Pulled landing donut. There are dings on the bottom of the donut where we were setting down on something. Removed Washington Head, spool and Nabors Hydril. NU stack with the spool on top of the pipe rams, Weatherford Hydril and Washington head. Still can't go down with tbg. Able to get about 4 ft. below the floor. Stab Washington Rubber on jt tbg and ran into head and locked. MU Power Swivel. Tbg. torquing – ran about 2300, tbg turning very slow, torquing. Acts like there is something along side the tbg string. Closed and locked Pipe Rams, Closed Hydril, well secure. SDFN @ 5:30 pm.

## December 29, 2007

SICP 1750 psi. Blow down to pit Pull 17 jts tbg, pulled free – able to go down. Tbg. was packed off and had pressure trapped below. Flowing pressure increased to 3000 psi within minutes. Open up to pits on 1 to 3 parallel chokes – kept plugging chokes with rubber, sand, general trash. Blew pressure down to about 1100 psi. RI with 21 jts. Back to where we had cleaned out to previously. RIH to 12,102' – didn't tag anything, didn't have to clean out any sand. Continued down 2 jts to 12168'- did not tag CBP that were supposed to be at 12,140' and 12,150' – plugs no longer there. Pull and LD 9 jts tbg. Tubing String In Hole: 359 jts 2 7/8" 6.5#, N-80, LTC Tbg (11,793.24'), 2.313" X Nipple (1.25'), 1 jt 2 7/8" 6.5# N-80, LTC Tbg (32.91'), 2.313" XN Nipple with PXN Flow Thru Plug installed (1.30'), 1 jt 2 7/8" 6.5#, N-80, LTC Tbg (32.90'), Bit Sub- 3 ¾" OD x 1.75" ID (1.04'), 4 ¾" Blade Bit (.33'). X Nipple @ 11,811.24' to 11,812.49'; XN Nipple @ 11845.40' to 11846.70'; Bottom of Bit @ 11880.97' – All KB Depths. MU landing donut and strip in thru BOP's. Land tubing, tighten lock down lugs. Bled down pressure – hanger is sealing.. Installed TIW valve in tbg, closed pipe rams, secured well. SDFN @ 5:00 pm.

## December 30, 2007

SICP 2900 psi; SITP 2200 psi. Blew down tubing pressure. RD floor, ND BOP, MU Well Head. RD Stone Well Service Rig 3. Load out BOPE. Have 20 jts 2 7/8" 6.5#, N-80, LTC tbg left on location – 19 good jts (624.81') and 1 crimped jt (32.92'). Rig off location at 2:30 pm 12/30/07. Delsco Wireline lined up to pull flow thru plug out of XN Nipple, Wednesday 1/2/08 – They plan to be on location about 10:00 am. Final Report

WORKOVER REPORT MILLER DYER & Co, LLC UTE TRIBAL 6-16 SENW Sec 16, T15S-R20E UINTAH COUNTY, UTAH

#### March 17, 2008

Snowed 4"-6" over night – lease roads bad. Got PLS slickline truck down hill to location but couldn't rig or snub unit down to location – had to wait for motor grader to clear snow off the lease road. RU PLS – SICP 2000 psi. RIH with XN plug – couldn't get thru X nipple. Got plug to 10810' KB – wireline depth. X nipple at 10811' KB – tubing tally. POH, had slight flare on 2 of the seals on the plug. Change seals on plug (and caliper). Made 2<sup>nd</sup> run. Plug hung up @ 10810' – hung up and pulled off running tool. POH, MU retrieving tool, RIH. Latched onto the plug, drug up hole 40', sheared off. Made 4 more runs, sheared off each time. RD PLS. Got rig & snub unit down to location. Attempted to RU rig – stuck in mud on location. Wait for dozer. Lay line to pit, open tbg. on 8/64 choke – SICP 2060 psi & SITP 2100 psi. RU Leed Rig 732 while flowing tubing. Tubing pulled down to about 1600 psi, CP stayed about 2060 psi. Then the TP started increasing to 1800 psi and the CP dropped to 1980 psi – plug apparently came free and coming up hole. SI flow line – pumped 50 bbl water down tbg. SI well and SDFN @ 7:00 pm.

**Estimated Costs** 

Leed Rig 732	\$ 5,375
Mtn. States Pressure Control	8,995
PLS - Slick Line	5,320
Chapman - Dozer & Grader	700
Supervision – PEMI	1,250
Daily Cost	\$21,640

## March 18, 2008

7:00 am SITP 600 psi; SICP 2100 psi. Pumped 49 bbl water down tbg – pressured up to 1000 psi. Appears XN plug may be in either the X or XN nipples. Bled tubing pressure down to 10 psi – SI, removed TIW valve and RU JW Wireline. RI with GR/CCL – correlate to GR on CBL. X nipple @ 11802', (wireline depth) – set down @ 11830'. POH, PU CIBP & RIH, correlate to CCL. Set CIBP in tubing @ 11825' – between X & XN nipples. POH, RD JW Wireline. NU rig BOP. RU Mountain States Pressure Control equipment. Pull and LD tubing hanger, MU tubing collar and install TIW valve. Close TIW valve, close & lock BOP's. SDFN @ 7:15 pm. Estimated Costs

Rig - Eegd 732	\$ 5,385
Wireline JW	15,030
Snub Unit - Mnt. States Pressure Control	6,300
Supervision – PEMI	1,250
Daily Cost	\$27,965
Cum Cost	\$49,605

Page 2

# WORKOVER REPORT MILLER DYER & Co, LLC UTE TRIBAL 6-16 SENW Sec 16, T14S-R20E UINTAH COUNTY, UTAH

#### March 19, 2008

SICP 2200 psi; Tbg. dead. Held safety meeting, check equipment. PU & RIH with 10 jts 2 7/8" tubing to 12183'. Pull & LD 10 jts tbg. Pull & stand back 36 stands tbg dry & 115 stands wet. Wireline truck stuck in mud on location — need dozer to pull out. Snub out with 28 stands. Ran sash cord with wt. down single — CIBP is set above X nipple. Snub out triple with X nipple, XN nipple, Bit Sub & Bit. Closed and locked blind rams & bled off pressure. Laid triple on ground. RD snub equipment & SDFN @ 6:30 pm.

**Estimated Costs** 

Rig – Leed	\$ 5,475
Dozer - Chapman	750
Snubbers - Mtn. States Press. Control	6,800
Vac Truck – R.N. Inductries	1,835
Supervision – PEMI	1,250
Daily Cost	\$16,110
Cum Cost	\$65,715

#### March 20, 2008

SICP 2300 psi, RU JW Wireline, RI with 4.75" OD gauge ring to 12,200°. POH, LD gauge ring & PU 4.68" OD CIBP. RI & set BP @ 12, 175°. POH, RD JW Wireline, RU Mtn. States Pressure Control equipment. MU Weatherford Pump Off Sub (.50°) on bottom of jt of 2 7/8" tbg. (32.82°), snub in. MU 2.312" ID XN nipple (1.28°), MU jt of 2 7/8" tbg (32.86°), snub in. MU 2.31" ID X nipple (1.22°). PU & snub in 3 more singles (98.65°). Start snubbing stands. Snub in with 18 stands tubing and run in with 69 stands. Close and lock BOP's, SDFN @ 7:00 pm. Estimated Costs

Rig-Leed	\$ 4,555
Snub Unit - Mtn. States Press. Control	6,600
Subs & Nipples - Weatherford	2,400
Wireline – JW	17.825
Supervision - PEMI	1,250
Daily Cost	\$32,630
Cum Cost	\$98,345

Page 3

## WORKOVER REPORT MILLER, DYER & Co, LLC UTE TRIBAL 6-16 SENW Sec 16, T14S-R20E UINTAH COUNTY, UTAH

## March 21, 2006

SICP 2300 psi. Open rig BOP & equalize across snub stack. RIH with 70 stands tbg. PU landing jt. with tbg hanger. MU new seal on hanger. RI and land tbg. Tubing landed with 359 jts 2 7/8" 6.5#, N-80 tubing (11794.18'), 2.31" ID X Nipple (1.22'), 1 jt. 2 7/8" 6.5#, N-80 tbg (32.86'), 2.31" ID XN Nipple (1.28'), 1 jt 2 7/8" 6.5#, N-80 tbg (32.82'), Weatherford Pump Out Plug (50'). Pump out plug will convert to a wireline reentry guide after plug is pumped out. X Nipple (11813" KB; XN Nipple (11846" KB; EOT (11881" KB. RD Mtn. States Pressure Service and ND rig BOP & NU Tree. Pump 30 bbl water down tubing. Rig down Leed Rig 732 while waiting for Cudd Nitrogen pump truck. RU Cudd, cool down and PT to 5000 psi. Pump 85,525 cf N2 down tubing. Pump out plug (24200 psi. RD Cudd, tighten well head studs. Open to well with gas.

Trenumien Costs	
Rig-Leed 732	*
Smit Unit - Men Chatan Day	\$ 4,300
Snub Unit - Mtn. States Pressure Service Nitrogen Pumper - Cudd	7,694
Outback Rental - Trucking	13,190
Supervision - PEMI	1,400
Daily Cost	1,250
Cum Cost	\$ 27,834
	\$126,179

			DEDAE		TATE (			NIBCEI								ORT [	] F	ORM 8
					FOIL,										chang ESIGNAT		SERIAL NUN	IBER:
	, , , , , , , , , , , , , , , , , , , ,													ML-47				
	L COM	PLET	ION	OR I	RECC	MPI	.ETIC	ON R	EPO	RT ANI	LOG				, ALLOTT Idian		RIBE NAME	
1a, TYPE OF WELL		OI W		]	GAS WELL	Z	DRY		OTI	IER			- 1	NIT or C	A AGREE	MENT NA	ME	
b. TYPE OF WORL NEW WELL	K: HORIZ, LATS.	DI	EP-	]	RE- ENTRY		DIFF. RESVR,		OT	ER					ME and N ribal 6	UMBER: 5-16-14	4-20	
2. NAME OF OPER. Miller, Dye		LLC									•			PI NUME 4304	3ER: 73850	6	····	
3. ADDRESS OF OF 475 17th St		200 с	ıтү De	nver		STATE	СО	ZIP 802	202		NUMBER: 03) 292-0	949		TELD AN		OR WILD	CAT	
4. LOCATION OF W										- A. whey			11.	QTR/QT	R, SECTION	ON, TOW	NSHIP, RANG	GE,
AT SURFACE:	1846 FN	IL 206	5 FWL	_ SEN	W Sec	: 16 1	4S-20	5						ENW	16		20E :	
AT TOP PRODU	CING INTERV	AL REPOR	RTED BEL	.ow: 2	397 F	NL 16	92 FV	VL SEI	NW Se	ec 16 14	S-20E		10	001110	<u>.</u>			
AT TOTAL DEPT								20E			•		1	county Jintah	1		13. STATE	UTAH
7/16/2007		7/5/20	07		4/1	E COMPL 1/2008	3		ABANDON	ED 🗌	READY TO P	RODUC	E 🔽		858 K		3, RT, GL):	
18. TOTAL DEPTH:	MD 12, TVD 12,	517 474	1	9. PLUG	BACK T.	TVD	1249	95 152	20. IF	MULTIPLE CO	OMPLETIONS	, HOW I	ANY? *		TH BRIC		12,18 12,19	
22. TYPE ELECTRIC	C AND OTHER	RMECHAN	ICAL LO	SS RUN (	Submit co	y of each	) Ds	r DK	< D	23.				F1				* *********
ACRt, DSN/	SDL, WS	ST, GR	s, SP,	CBL						WAS WELL	L CORED?		NO NO		YES YES		omit analysis	)
											NAL SURVEY	?	NO		YES 7		omit report) omit copy)	
24. CASING AND L	NER RECORD	) (Report :	all strings	set in w	ell)	*								h				
HOLE SIZE	SIZE/GRA	DE	WEIGHT	{#/ft_}	TOP	MD)	вотто	IM (MD)		CEMENTER PTH	CEMENT TY NO. OF SA		SLUM		CEME	NT TOP	AMOUN	T PULLED
26"	20"					)	4	0					····		Sı	ırface		
12-1/4"	9-5/8"	J-55	36	)		)	3,4	420	· · · · · · · · · · · · · · · · · · ·			750			Sı	rface		
8-7/8"	5-1/2" N	1-80	17		C	)	12,	510	10	,392		1,450			Su	rface		
										:								
	V41132 W. ST. 141																	
-															<u> </u>	************		
25. TUBING RECOR			1												·······		,,	
2-7/8"	DEPTH S		PACKE	R SET (I	MD)	SIZE		DEPTH	SET (MD	PACKE	R SET (MD)		SIZE		DEPTH SI	ET (MD)	PACKER	SET (MD)
26. PRODUCING IN			V 5)	~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~~	I					27 PERFO	RATION RECO	IRD		<u>l</u>		······································		
FORMATION		ر 2ا <i>یا</i>	ED)	, <b>.</b> .	A (MD)	TOP	(TVD)	вотто	M (TVD)		L (Top/Bot - M		SIZE	NO. HO	LES	PERFO	RATION STA	ATUS
(A) Navajo		12,	256	12,	290	12,	213	12,	247	12,256	12,2	90	0.42	52	Ор	en 💰	Squeezed	I
(B) Entrada		11,	910	12,	042	11,	840	11,	378	11,910	12,0	42	0.42	180	) Op		Squeezed	
(C)										**************************************	·····				Ор	en 🗍	Squeezed	
(D)										····					Ор	en 🗌	Squeezed	
28. ACID, FRACTUR	RE, TREATME	NT, CEME	NT SQUE	EZE, ETC	<b>3.</b>							<del></del>			•			
DEPTHI	NTERVAL								АМ	T DIA TAUC	YPE OF MATE	RIAL			******	<del>(************************************</del>	<del>L.i</del>	
12,256-12,29	<b>3</b> 0	*****	Acidi	ze wil	th 150	gal,	7.5%	HCI, F	rac wi	th 73000	# 20/40	and 1	00 m	esh s	and w	ith 143	3 tons C	O2
11,910-12,04	12										00# 20/40							
29. ENCLOSED ATT	ACHMENTS:							······································			<del>, , , , , , , , , , , , , , , , , , , </del>					30. WEI	L STATUS:	
=	RICAL/MECHA Y NOTICE FO			CEMENT	VERIFICA	TION	=	GEOLOGI			DST REPORT OTHER: CB		DIRECT		SURVEY	Р	roduc	ing
(5/2000)							(00)	NTINIIE	יא ח	NCK)				R	ECI	EIVE	ΞD	

JUL 08 2008

#### 31. INITIAL PRODUCTION

#### INTERVAL A (As shown in item #26)

DATE FIRST PR	ODUCED:	TEST DATE: 10/16/20	07	HOURS TESTED	): '2	TEST PRODUCTION RATES: →	OIL – BBL:	GAS - MCF:	WATER - BBL:	PROD. METHOD: Flow up Tbg
CHOKE SIZE: 16	TBG. PRESS. 1,200	CSG. PRESS.	API GRAVITY	1,030	GAS/OIL RATIO	24 HR PRODUCTION RATES: →	OIL - BBL:	GAS MCF: 1,789	WATER - BBL:	INTERVAL STATUS: Below CIBP
			,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	INT	ERVAL B (As show	wn In item #26)	, , , , , , , , , , , , , , , , , , ,	.,		
DATE FIRST PR 2/8/2008	ODUCED:	TEST DATE: 10/29/20	07	HOURS TESTED	): 20	TEST PRODUCTION RATES: →	OIL – BBL:	GAS – MCF:	WATER - BBL:	PROD. METHOD: Flow up Tbg
CHOKE SIZE: <b>24</b>	TBG. PRESS. 1,900	CSG, PRESS.	API GRAVITY	BTU - GAS 1,030	GAS/OIL RATIO	24 HR PRODUCTION RATES: →	OIL – BBL:	GAS – MCF: 6,500	WATER - BBL:	INTERVAL STATUS: Open
	, , , , , , , , , , , , , , , , , , , ,			INT	ERVAL C (As show	wn in Item #26)				.,
DATE FIRST PR	ODUCED:	TEST DATE:		HOURS TESTED	);	TEST PRODUCTION RATES: →	OIL BBL:	GAS MCF:	WATER - BBL:	PROD. METHOD:
CHOKE SIZE:	TBG. PRESS.	CSG, PRESS.	API GRAVITY	BTU – GAS	GAS/OIL RATIO	24 HR PRODUCTION RATES: →	OfL B&L:	GAS – MCF:	WATER - BBL:	INTERVAL STATUS:
				INTI	ERVAL D (As show	wn in ilem #26)				
DATE FIRST PR	ODUCED:	TEST DATE:		HOURS TESTED	);	TEST PRODUCTION RATES: →	OIL - B8L:	GAS - MCF:	WATER - BBL:	PROD. METHOD:
CHOKE SIZE:	TBG. PRESS.	CSG. PRESS.	API GRAVITY	BTU – GAS	GAS/OIL FIATIO	24 HR PRODUCTION RATES: →	OIL - BBL:	GAS – MCF:	WATER - BBL:	INTERVAL STATUS:

#### 33. SUMMARY OF POROUS ZONES (Include Aquifers):

Show all important zones of porosity and contents thereof: Cored intervals and all drill-stem tests, including depth interval tested, cushlon used, time tool open, flowing and shut-in pressures and recoveries.

34. FORMATION (Log) MARKERS:

Formation	Top (MD)	Bottom (MD)	Descriptions, Contents, etc.	Name	Top (Measured Depth)
Wasatch	3,442	4,614	Gas / water sand	Green River	0
Mesaverde	4,614	6,634	Gas / water sand	Wasatch	3,442
Castlegate	6,634	6,832	Sandstone	Mesaverde	4,614
Mancos	6,832	10,893	Sand / shale	Castlegate	6,634
Dakota Group	10,893	11,280	Sand / shale	Dakota	10,893
Morrison	11,280	11,883	Sand / shale	Morrison	11,280
Entrada	11,883	12,168	Gas sand	Entrada	11,883
Carmel	12,168	12,240	Shale	Wingate	12,433
Kayenta	12,240	12,433	Gas / water sand		
Wingate	12,433		Gas / water sand		

35. ADDITIONAL REMARKS (Include plugging procedure)

^ ^		
NAME (PLEASE PRINT) John E. Dyer	TITLE Manager	
SIGNATURE	PATE 7/8/2008	

This report must be submitted within 30 days of

- · completing or plugging a new well
- drilling horizontal laterals from an existing well bore
- · recompleting to a different producing formation
- reentering a previously plugged and abandoned well

- · significantly deepening an existing well bore below the previous bottom-hole depth
- · drilling hydrocarbon exploratory holes, such as core samples and stratigraphic tests

\* ITEM 20: Show the number of completions if production is measured separately from two or more formations.

36. I hereby certify that the foregoing and attached information is complete and correct as determined from all available records.

\*\* ITEM 24: Cement Top - Show how reported top(s) of cement were determined (circulated (CIR), calculated (CAL), cement bond log (CBL), temperature survey (TS)).

Send to:

Utah Division of Oil, Gas and Mining

1594 West North Temple, Suite 1210

Box 145801

Salt Lake City, Utah 84114-5801

Phone: 801-538-5340

801-359-3940 Fax:

Ute Tribal 6-16-14-20 Perforation Record API: 43-047-38506

					ı
Formation	Interval	Size	No. Holes	Perforation Status	
Navajo	12,282-12,290	23 gm, 0.42" entry holes, 120 degree phasing, 4 spf	32	Below CIBPs @ 12182' &12192'	т—
Navajo	12,256-12,261	23 gm, 0.41" entry holes, 120 degree phasing, 4 spf	20	Below CIBPs @ 12182' &12192'	
Lower Entrada	12,037-12,042	23 gm, 0.42" entry holes, 120 degree phasing, 4 spf	20	Open	
Lower Entrada	12,024-12,029	23 gm, 0.42" entry holes, 120 degree phasing, 4 spf	20	Open	
Lower Entrada	12,014-12,019	23 gm, 0.42" entry holes, 120 degree phasing, 4 spf	20	Open	
Lower Entrada	12,003-12,008	23 gm, 0.42" entry holes, 120 degree phasing, 4 spf	20	Open	1
Lower Entrada	11,994-11,999	23 gm, 0.42" entry holes, 120 degree phasing, 4 spf	20	Open	
Lower Entrada	11,983-11,998	23 gm, 0.42" entry holes, 120 degree phasing, 4 spf	20	Open	_
Lower Entrada	11,952-11,957	23 gm, 0.42" entry holes, 120 degree phasing, 4 spf	20	Open	
Upper Entrada	11,910-11,920	23 am, 0,42" entry holes, 120 degree phasing, 4 spf	40	Open	1



# **Drilling Services**

## **FINAL SURVEYS**

## MILLER, DYER & COMPANY, LLC

UTE TRIBAL 6-16-14-20

**UINTAH COUNTY, UTAH** 

WELL FILE: FINAL

**OCTOBER 18, 2007** 

## MILLER, DYER & CO, LLC

UTE TRIBAL 6-16-14-20 SHL SEC 16-T14S-R20E 1846' FNL, 2065' FWL UINTAH COUNTY, UTAH



Azimuths to True North Magnetic North: 11,61°

Magnetic Field Strength: 52516nT Dip Angle: 65.63° Date: 7/26/2007 Model; bggm2006

TOTAL CORRECTION TO TRUE NORTH: 11.61°

FIELD DETAILS UINTAH COUNTY, UTAH

Geodetic System: US State Plane Coordinate System 1983 Ellipsoid: GRS 1980 Zone: Utah, Central Zone Magnetic Model: bggm2006

System Datum: Mean Sea Level Local North: True North

SITE DETAILS

UTE TRIBAL 6-16-14-20 1846' FNL 2065' FWL SECT 16-T14S-R20E

Site Centre Latitude: 39°36'05,290N Longitude: 109°41'06,370W

Ground Level: 6838.00 Positional Uncertainty: 0,00 Convergence: 1.16

CASING DETAILS

No. TVD MD Size 20" CONDUCTOR 9 5/8" CSG PT. 60.00 3400.00 60,00 3400.21 20.000 9.625

SECTION DETAILS												
Sec.	MD	Inc	Azi	TVD	+N/-S	+E/-W	DLeg	TFace	VSec	Target		
1 2 3 4 5 6	0.00 6914.67 7831.34 9687.06 10603.73 12470.73	0.00 0.00 13.75 13.75 0.00 0.00	218.09 218.09 218.09 218.09 218.09 218.09	0,00 6914.67 7822.56 9625.11 10533.00 12400.00	0,00 0,00 -86.15 -433.29 -519.44 -519.44	0.00 0,00 -67.53 -339.65 -407.18 -407,18	0,00 0,00 1,59 0,00 1,50 0,00	0,00 0,00 218.09 0,00 180.60 0,00	0.00 0.00 109.47 550.54 660.01 660.01	KOP HOLD DROP DAKOT/ PBHL	A SILT/HOLD	
					WEL	L DETAIL	S					
	Name		+N/-S	+E/-W	Northing	Eas	ting	Latitude		Longitude	Slot	
	UT 6-16-	14-20	0.00	9,00	7028765.78	215174	9.04	39°36'05.290N	10 <del>9</del> °41	'06.370W	N/A	
					TARG	ET DETAI	LS					
		Name	T	VD +N/-	S +E/-W	North	ring	Easting S	Shape			


PBHL 12400,00 -519.44 -407.18 7028238.19 2151352.48 Circle (Radius; 100) KB ELEVATION: 6858' GR ELEVATION: 6838' 3000 3750 4500 True Vertical Depth [1500ft/in] 7500 8250 9000 10500 LAST MWD SVY 12000

1500

Vertical Section at 214.15° [1500ft/in]

3000

Survey: Survey #2 (UT 6-16-14-20/1) MD TVD +N/-S +E/-W TFace VSec Inc Λz DLeg 12444.00 2.50 197,00 -548.99 -372.41 12414,42 0.00 0.00 663.38



Survey: Survey #2 (UT 6-16-14-20/1)

Created By: ROBERT SCOTT

Date: 10/18/2007

## Weatherford International, Ltd. **Survey Report**

Company: Field; Site: Well: Wellpath;	MILLER, DY UINTAH CO UTE TRIBA UT 6-16-14- 1	UNTY, UT. L 6-16-14-2			C V S	ate: 10/18/20 Co-ordinate(NE) Certical (TVD) R ection (VS) Refe urvey Calculatio	Reference eference: rence:	: Site SIT We	E 6858.0	Pag AL 6-16-14-20, 0E,214.15Azi) ture Db;	
Field:	UINTAH C	OUNTY, U	TAH				-				
Geo Datur	m:US State I n: GRS 1980 n: Mean Sea	1	dinate Systen	າ 1983		Map Zone: Coordinate S Geomagnetic		Utah, Site C bggm	T	3	
Site:	UTE TRIB	AL 6-16-14	-20								
Site Positi From: Position U Ground L	on: Geograph nccrtainty:	ic	L SECT 16-7 North Eastin Oft	ing: 702876	5.78 ft 9.04 ft	Latitude: Longitude: North Refere Grid Converg			5.290 N 6.370 W True 1.16 deg		
Well:	UT 6-16-1	4-20	*			Slot Name:			······································	· · · · · · · · · · · · · · · · · · ·	
Well Posit		/-W 0.0	O ft North O ft Eastin		5.78 ft 9.04 ft	Latitude: Longitude:	3 10		5.290 N 6.370 W		
Wellpath:						Drilled From:		Surfac			
Current D Magnetic Field Street Vertical S	atum: SIT Data: ngth:	7/26/200	6 nT	Height 685 +N/-S ft	8.00 ft	Tie-on Depth Above System Declination: Mag Dip Ang +E/-W	: 1 Datum:		0.00 ft Sea Level 11.61 deg 65.63 deg		
		0.00	·····	0.00		0.00		214.15			
Date: 10 Actual Front	om To ft	finitive Wel Validate Survey				Version: 3 Toolcode		ool Name			
3520.00 12230.00	12034.00 12444.00		#1 (3520.00-1 #2 (12230.00			MWD SS SURVEYS		WD - Sta CWSA	ındard		
Survey											
MD ft	Incl deg	Azim deg	TVD ft	+N/-S ft	+E/-W ft	VS ft	DLS deg/100fi	Build deg/100	Turn ft deg/100ft	Tool/Commer	ıt
0.00	0.00	218.09	0.00	0.00	0.00	0.00	0.00	0.00	0.00	TIE LINE	
3520.00 3611.00	1.13 1.11	174.99 176.76	3519.77 3610.75	-34.58 -36.35	3.03 3.16	26.91 28.31	0.03 0.04	0.03 -0.02	0.00 1.95	MWD MWD	
3703.00	1.31	180.99	3702.73	-38.29	3.19	29.90	0.24	0.22	4.60 0.83	MWD MWD	
3793.00	1.94	181.74	3/92.70	-40.84	3.13	32.04	0.70	0.70			
3883.00 3973.00	2.06 3.13	207.24 182.36	3882.64 3972.55	-43.80 -47.70	2.34 1.50	34.94 38.63	0.99 1.70	0.13 1.19	28.33 -27.64	MWD MWD	
4063.00	3.63	178.49	4062.40	-53.00	1.47	43.03	0.61	0.56	-4.30	MWD	
4154.00	4.31	177.36	4153.18	-59.30	1.71	48.11	0.75	0.75	-1.24	MWD	
4244.00	5.00	175.74	4242.88	-66.59	2.15	53.90	0.78	0.77	-1.80	MWD	
4335.00 4396.00	5.19 5.25	174.61 175.49	4333.52 4394.27	-74.64 -80.17	2.83 3.31	60.18 64.48	0.24 0.16	0.21 0.10	-1.24 1.44	MWD MWD	
4456.00	4.94	175.45	4454.03	-85.48	3.73	68.65	0.52	-0.52	0.20	MWD	
4484.00 4514.00	4.94 4.88	174.74 173.24	4481.93	-87.88 -90.44	3.93 4.20	70.52 72.48	0.27 0.47	0.00 -0.20	-3.11 -5.00	MWD MWD	
4014.00			4511.82								
4544.00	4.75	174.36	4541.71	-92.94	4.47	74.40	0.53	-0.43	3.73	MWD	}
4685.00 4718.00	4.44 4.25	172.36 174.61	4682.26 4715.16	-104.16 -106.64	5.77 6.05	82.96 84.85	0.25 0.77	-0.22 -0.58	-1.42 6.82	MWD MWD	
4748.00	4.23	174.36	4745.08	-108.82	6.27	86.54	0.40	-0.40	-0.83	MWD	
4778.00	4.19	175.36	4775.00	-110.99	6.46	88.23	0.31	0.20	3.33	MWD	

0.65

0.27

6.72

7.23

90.15

93.80

0.35 -0.09

-7.35 3.33

MWD

MWD

4812.00

4876.00

4.31

4.25

172.86 174.99

4808.91

4872.73

-113.50

-118.25

## Weatherford International, Ltd. **Survey Report**

MILLER, DYER & CO. UINTAH COUNTY, UTAH UTE TRIBAL 6-16-14-20 Company: Field: UT 6-16-14-20 1 Well:

Date: 10/18/2007 Co-ordinate(NE) Reference: Vertical (TVD) Reference: Section (VS) Reference: Survey Calculation Method:

Time: 10:04:57 Page: 2

Et Site: UTE TRIBAL 6-16-14-20, True North
SITE 6858.0
Well (0.00N,0.00E,214.15Azi)

B. Minimum Curvature Db: Sybase

Wellpath	12
Survey	

MD										
ft ft	Incl deg	Azim deg	TVD ft	+N/-S ft	+E/-W ft	VS ft	DLS deg/100ft	Baild t deg/100	Turn ft deg/100ft	Tool/Comment
4940.00	4.44	181.99	4936.55	-123.08	7.35	97.73	0.88	0.30	10.94	MWD
5003.00	4.69	184.11	4999.35	-128.09	7.08	102.03	0.48	0.40	3.37	MWD
5067.00	4.31	189.36	5063.15	-133.07	6.50	106.48	0.88	-0.59	8.20	MWD
131.00	3.94	199.24	5126.99	-137.52	5.38	110.79	1.25	-0.58	15.44	MWD
3194.00	3.94	199.99	5189.84	-141.60	3.93	114.98	0.08	0.00	1.19	MWD
267.00	3.95	198.44	5262.66	-146.34	2.28	119,83	0.15	0.01	-2.12	MWD
321.00	3.75	196.86	531 <del>6</del> .54	-149.80	1.18	123.30	0.42	-0.37	-2.93	MWD
384.00	3.75	201.36	5379.41	-153.69	-0.17	127.28	0.47	0.00	7.14	MWD
448.00	3.81	205.11	5443.27	-157.56	-1.84	131.42	0.40	0.09	5.86	MWD
512.00	4.13	211.24	5507.11	-161.46	<i>-</i> 3,93	135.82	0.83	0.50	9.58	MWD
576.00	4.63	208.49	5570.93	-165.70	-6.36	140.70	0.85	0.78	-4.30	MWD
639.00	4.69	210.36	5633.72	-170.15	-8.88	145.80	0.26	0.10	2.97	MWD
703.00	4.38	217.74	5697.52	-174.34	-11.69	150.85	1.03	-0.48	11.53	MWD
766.00	4.75	222.74	5760.32	-178.16	-14.94	155.83	0.86	0.59	7.94	MWD
6830.00	4.56	223.74	5824.11	-181.95	-18.49	160.95	0.32	-0.30	1.56	MWD
5894.00	4.38	223.74	5887.91	-185.55	-21.94	165.87	0.28	-0.28	0.00	MWD
5958.00	4.13	221.61	5951.74	-189.04	-25.16	170.57	0.46	-0.39	-3.33	MWD
3021.0 <b>0</b>	3.94	219.49	6014.58	-192.41	-28.05	174.97	0.38	-0.30	-3.37	MWD
6076.00	4.19	220.49	6069.44	-195.39	-30.55	178.85	0.47	0.45	1.82	MWD
3146.00	4.31	221.86	6139.25	-199.30	-33.97	184.00	0.22	0.17	1.96	MWD
3209.00	4.31	224.36	6202.07	-202.75	-37.20	188.67	0.30	0.00	3.97	MWD
6272.00	4.25	227.11	6264.90	-206.03	-40.57	193.28	0.34	-0.10	4.37	MWD
335.00	3.88	227.86	6327.74	-209.05	-43.86	197.62	0.59	-0.59	1.19	MWD
397.00	3.88	225.49	6389.60	-211.93	-46.91	201.72	0.26	0.00	-3.82	MWD
3461.00	4.25	221.24	6453.44	-215.23	-50.02	206.20	0.75	0.58	-6.64	MWD
6523.00	4.13	216.99	6515.27	-218.74	-52.88	210.71	0.54	-0.19	-6.85	MWD
6586.00	4.56	217.22	6578.09	-222.55	-55.76	215.47	0.68	0.68	0.37	MWD
6650.00	4.81	216.36	6641.87	-226.73	-58.88	220.69	0.41	0.39	-1.34	MWD
6702.00	4.88	218.24	6693.69	-230.23	-61.55	225.08	0.33	0.13	3.62	MWD
6765.00	4.75	220.11	6756.47	-234.33	-64.89	230.35	0.32	-0.21	2.97	MWD
6797.00	4.81	220.24	6788.36	-236.36	-66.61	233.00	0.19	0.19	0.41	MWD
6829.00	5.00	223.36	6820.24	-238.40	-68.43	235.71	1.02	0.59	9.75	MWD
6861.00	5.00	226.99	6852.12	-240.37	-70.41	238.44	0.99	0.00	11.34	MWD
6892.00	4.88	227.36	6883.00	-242.18	-72.36	241.04	0.40	-0.39	1.19	MWD
6955.00	5.06	232.11	6945.76	-245.70	-76.53	246.30	0.71	0.29	7.54	MWD
7018.00	5.81	236.74	7008.48	-249.16	-81.39	251.88	1.38	1.19	7.35	MWD
7081.00	5.94	236.86	7071.15	-252.69	-86.78	257.84	0.21	0.21	0.19	MWD
7112.00	5.88	236.74	7101.99	-254.44	-89.45	260.78	0.20	-0.19	-0.39	MWD
7144.00	5.75	235.11	7133.82	-256.25	-92.14	263.79	0.66	-0.41	-5.09	MWD
7206.00	6.13	235.61	7195.49	-259.90	-97.42	269.77	0.62	0.61	0.81	MWD
7269.00	6.38	234.74	7258.11	-263.82	-103.05	276.18	0.42	0.40	-1.38	MWD
7332.00	6.13	232.74	7320.74	-267.88	-108.59	282.64	0.53	-0.40	-3.17	MWD
7395.00	6.75	236.61	7383.34	-271.95	-114.36	289.25	1.20	0.98	6.14	MWD
7458.00	6.81	239.24	7445.90	-275.90	-120.66	296.06	0.50	0.10	4.17	MWD
7521.00	6.75	239.36	7508.46	-279.70	-127.05	302.79	0.10	-0.10	0.19	MWD
7584.00	6.63	238.86	7571.03	-283.47	-133.35	309.45	0.21	-0.19	-0.79	MWD
7656.00	6.50	238.99	7642.56	-287.71	-140.40	316.92	0.18	-0.18	0.18	MWD
7710.00	6.19	236.86	7696.23	-290.88	-145.46	322.38	0.72	-0.57	-3.94	MWD
7772.00	5.63	234.61	7757.90	-294.47	-150.74	328.31	0.98	-0.90	-3.63	MWD
7835.00	5.13	229.61	7820.62	-298.08	-155.40	333.92	1.09	-0.79	-7.94	MWD
	5.38	235.86	7883.36	-301.57	-159.99	339.38	0.99	0.40	9.92	MWD
7898.00		m-0-0-0-0								
7898.00 7961.00	5.94	241.99	7946.05	-304.76	-165.32	345.01	1.31	0.89	9.73	MWD

# Weatherford International, Ltd.

## **Survey Report**

Company: MILLER, DYER & CO.
Field: UINTAH COUNTY, UTAH
Site: UTE TRIBAL 6-16-14-20
Well: UT 6-16-14-20 Well;

Date: 10/18/2007 Time: 10:04:57 Page: 3
Co-ordinate(NE) Reference: Site: UTE TRIBAL 6-16-14-20, True North
Vertical (TV) Reference: SITE 6858.0
Section (VS) Reference: William (CON), 0.00E, 214, 15Azj)

	1	4+ZU				ection (VS) R irvey Calcula			iii (U.DUN,U. iimum Curv	∪0E,214,15Azi) ature Dba	Sybase
Survey											
MD ft	Incl deg	Azim deg	TVD ft	+N/-S ft	+E/-W ft	VS ft	DLS deg/100f	Build t deg/100	Turn Ift deg/100f	Tool/Commer L	ot
8087.00	6.26	239.41	8071.38	-310.97	-176.66	356.52	1.00	0.90	-4.10	MWD	
8150.00	6.38	237.11	8134.00	-314.62	-182.56	362.85	0.44	0.19	-3.65	MWD	
8213.00	6.19	234.74	8196.62	-318.48	-188.27	369.25	0.51	-0.30	-3.76	MWD	
8275.00	6.25	237.49	8258.26	-322.22	-193.85	375.48	0.49	0.10	4.44	MWD	
8338.00	5.81	236.36	8320.91	-325.83	-199.40	381.58	0.72	-0.70	-1.79	MWD	
8401.00	5.94	236.86	8383.58	-329.38	-204.78	387.54	0.22	0.21	0.79	MWD	
8464.00 8527.00	5.94	245.61	8446.24	-332.51	-210.48	393.33	1.44	0.00	13.89	MWD	
8590.00	6.25 6.94	249.24 250.36	8508.88 8571.47	-335.07 -337.56	-216.65 -223.45	398.91 404.79	0.78 1.11	0.49 1.10	5.76 1.78	MWD MWD	
8653.00	6.81	247.61	8634.01	-340.27	-230.48	410.98	0.56	-0.21	-4.37	MWD	
8715.00	6.37	245.37	8695.60	-343.10	-237.01	416,99	0.82	-0.71	-3.61	MWD	
8778.00	6.06	245.11	8758.23	-345.96	-243.20	422.83	0.49	-0.49	-0.41	MWD	
8841.00	6.31	244.24	8820.87	-348.86	-249.34	428.67	0.42	0.40	-1.38	MWD	
8904.00	6.50	241.49	8883.47	-352.07	-255.59	434.84	0.57	0.30	-4.37	MWD	
8967.00	6.50	239.36	8946.07	-355.59	-261.79	441.23	0.38	0.00	-3.38	MWD	
9030.00	6.38	242.49	9008.67	-359.02	-267.96	447.54	0.59	-0.19	4.97	MWD	
9093.00	6.38	241.99	9071.28	-362.28	-274.16	453.72	0.09	0.00	-0.79	MWD	
9156.00	6.06	237.45	9133.91	-365.71	-280.05	459.86	0.93	-0.51	-7.21	MWD	
9218.00 9281.00	5.25 5.31	232.49 230.36	9195.61 9258.34	-369.20 -372.82	-285.06 -289.59	465.56 471.10	1.52 0.33	-1.31 0.10	-8.00 -3.38	MWD MWD	
9345.00	5.25	226.74	9322.07	-376.71	-294.00	476.80	0.53	-0.09	-5.66	MWD	
9408.00	5.00	222.49	9384.82	-380.71	-297.96	482.33	0.72	-0.40	-6.75	MWD	
9470.00	4.81	220.49	9446.59	-384.68	-301.47	487.59	0.41	-0.31	-3.23	MWD	
9533.00	4.81	223.24	9509.37	-388.61	-304.99	492.82	0.37	0.00	4.37	MWD	
9628.00	4.56	230.86	9604.05	-393.90	-310.65	500.37	0.71	-0.26	8.02	MWD	
9691.00	4.75	229.74	9666.85	-397.17	-314.59	505.28	0.33	0.30	-1.78	MWD	
9753.00	4.50	225.49	9728.64	-400.53	-318.28	510.14	0.68	-0.40	-6.85	MWD	
9816.00 9879.00	4.44	223,99 225,49	9791.45	-404.02	-321.74	514.96	0.21	-0.10	-2.38	MWD	
9942.00	4.75 4.56	225.49 222.74	9854.25 9917.04	-407.60 -411.27	-325.29 -328.85	519.92 524.96	0.53 0.47	0.49 -0.30	2.38 -4.37	MWD MWD	
10036.00	4.56	218.86	10010.74	-416.92	-333.73	532.38	0.33	0.00	-4.13	MWD	
10099.00	4.31	214.49	10073.56	-420.82	-336.64	537.24	0.67	-0.40	-6.94	MWD	
10162.00	3.69	211.36	10136.40	-424.51	-339.04	541.63	1.04	-0.98	-4.97	MWD	
10225.00	3.32	213.14	10199.28	-427.77	-341.09	545.48	0.61	-0.59	2.83	MWD	
10278.00	3.50	219.49	10252.19	-430.30	-342.96	548.63	0.79	0.34	11.98	MWD	
10351.00	3.69	220.11	10325.05	-433.81	-345.89	553.18	0.27	0.26	0.85	MWD	
10414.00	3.44	209.99	10387.93	-437.00	-348.14	557.08	1.07	-0.40	-16.06	MWD	
10476.00 10539.00	3.38 3.39	196.49 186.86	10449.82 10512.71	-440.37 -444.00	-349.59 -350.34	560.68 564.10	1.30 0.90	-0.10 0.02	-21.77 -15.29	MWD MWD	
10602.00	3.44	180.74	10575.60	-447.74	-350.58	567.34	0.58	0.02	-13.25	MWD	
10665.00	3.13	174.99	10638.49	-451.34	-350.46	570.25	0.72	-0.49	-9.13	MWD	
10728.00	3.00	168.36	10701.40	-454.67	-349.97	572.73	0.60	-0.21	-10.52	MWD	
10759.00	2.88	164.86	10732.36	-456.21	-349.61	573.81	0.70	-0.39	-11.29	MWD	
10791.00	2.69	161.36	10764.32	-457.70	-349.16	574.78	0.80	-0.59	-10.94	MWD	
10853.00	2.89	164.96	10826.25	-460.59	-348.29	576.69	0.43	0.32	5.81	MWD	
10906.00	2.73	161.36	10879.19	-463.08	-347.54	578.32	0.45	-0.30	-6.79	MWD	
10980.00	2.36	160.61	10953.11	-466.18	-346.47	580.29	0.50	-0.50	-1.01	MWD	
11042.00 11104.00	3.00 3.38	180.86 198.61	11015.05 11076.95	-469.01 -472.36	-346.07 -346.68	582.41 585.52	1.83 1.70	1.03	32.66 28.63	MWD MWD	
11135.00	3.63	210.99	11107.89	-472.36 -474.07	-346.68 -347.47	587.38	1.70 2.57	0.61 0.81	28.63 39.94	MWD	
11230.00	2.94	211.74	11202.74	-478.72	-350.30	592.82	0.73	-0.73	0.79	MWD	
11264.00	2.75	209.24	11236.70	-480.17	-351.16	594.51	0.67	-0.56	-7.35	MWD	
11359.00	2.69	203.99	11331.59	-484.20	-353.18	598.97	0.27	-0.06	-5.53	MWD	
11421.00	2.94	199.03	11393.51	-487.03	-354.29	601.94	0.56	0.40	-8.00	MWD	

# Weatherford International, Ltd.

**Survey Report** 

Company: MILLER DYER & CO.
Field: UINTAH COUNTY, UTAH
Site: UTE TRIBAL 6-16-14-20
Well: UT 6-16-14-20 Wellpath: 1

Date: 10/18/2007 Co-ordinate(NE) Reference: Vertical (TVD) Reference; Section (VS) Reference; Survey Calculation Method:

Time: 10:04:57 Page: 4
:: Site: UTE TRIBAL 6-16-14-20, True North
 SITE 6858.0
 Well (0.00N,0.00E,214.15Azi)
:: Minimum Curvature Db; Sybase

Survey

~~~~										
MD ft	Incl deg	Azim deg	TVD ft	+N/-S ft	+E/-W ft	VS ft	DLS deg/100f	Bulld t deg/100i	Turn It deg/100ft	Tool/Comment
11484.00	3.06	196.74	11456.43	-490.17	-355.30	605.10	0.27	0.19	-3.63	MWD
11547.00	3.25	195.99	11519.33	-493.50	-356.28	608.40	0.31	0.30	-1.19	MWD
11610.00	3.38	196.61	11582.23	-496.99	-357.30	611.87	0.21	0.21	0.98	MWD
11673.00	3.63	193.86	11645.11	-500.71	<i>-</i> 358.31	615.51	0.48	0.40	-4.37	MWD
11736.00	3.75	192.61	11707.98	-504.66	-359.24	619.30	0.23	0.19	-1.98	MWD
11799.00	4.06	191.86	11770.83	-508.85	-360.14	623.28	0.50	0.49	-1.19	MWD
11861.00	4.13	196.86	11832.67	-513.13	-361.24	627.44	0.59	0.11	8.06	MWD
11924.00	4.18	197.85	11895.51	-517.49	-362.60	631.81	0.14	0.08	1.57	MWD
11987.00	4.25	197.49	11958.34	-521.90	-364.01	636.25	0.12	0.11	-0.57	MWD
12034.00	4.19	197.61	12005.21	-525.20	-365.05	639.57	0.13	-0.13	0.26	MWD
12230.00	4.00	197.00	12200.71	-538.56	-369.22	652.96	0.10	-0.10	-0.31	SS SURVEYS
12350.00	2.50	197.00	12320.51	-545.07	-371.21	659.46	1.25	-1.25	0.00	SS SURVEYS
12444.00	2.50	197.00	12414.42	-548.99	-372.41	663.38	0.00	0.00	0.00	SS SURVEYS
12484.25	2,50	197.00	12454.64	-550.67	-372.92	665.06	0.00	0.00	0.00	PROJECTED to TD

## Division of Oil, Gas and Mining

## **OPERATOR CHANGE WORKSHEET**

R	OUTING
1.	DJJ

X - Change of Operator (Well Sold)		Operator Name Change/Merger									
The operator of the well(s) listed below has changed, effective	e:	6/1/2008									
FROM: (Old Operator):		TO: ( New Operator):									
N2580-Miller, Dyer & Co, LLC		N2680-Whiting	•	Company							
475 17th St, Suite 1200		_	roadway, S								
Denver, CO 80202			, CO 80290								
Phone: 1 (303) 292-0949		Phone: 1 (303)	837-1661								
CA No.		Unit:									
WELL NAME SEC TWN	RNG	API NO		LEASE TYPE		WELL					
			NO		TYPE	STATUS					
SEE ATTACHED LIST			<u> </u>		<u> </u>						
OPERATOR CHANGES DOCUMENTATION											
Enter date after each listed item is completed											
1. (R649-8-10) Sundry or legal documentation was received from	om the	FORMER ope	rator on:	6/5/2008							
2. (R649-8-10) Sundry or legal documentation was received from	om the	NEW operator	on:	6/5/2008	=						
3. The new company was checked on the <b>Department of Com</b>		_		s Database on:	-	7/16/2008					
4a. Is the new operator registered in the State of Utah:		Business Numb	=	5890476-0143							
4b. If <b>NO</b> , the operator was contacted contacted on:		•			•						
5a. (R649-9-2)Waste Management Plan has been received on:		REQUESTED	7/16/2008								
5b. Inspections of LA PA state/fee well sites complete on:		done	. 1710/2000								
5c. Reports current for Production/Disposition & Sundries on:		ok	-								
<del>-</del>	DIA 1		-	1							
6. Federal and Indian Lease Wells: The BLM and or the					DIA						
or operator change for all wells listed on Federal or Indian le	eases o	n:	BLM	not yet	BIA	not yet					
7. Federal and Indian Units:		41 11 . 1		,							
The BLM or BIA has approved the successor of unit opera				n/a	-						
8. Federal and Indian Communization Agreements (				,							
The BLM or BIA has approved the operator for all wells l			and IIIC E	n/a	of Auth	ovity to					
8 '				orm 5, <b>Transfer</b>		ority to					
Inject, for the enhanced/secondary recovery unit/project for	the wa	iter disposai wei	ii(s) iistea c	on:	n/a	-					
DATA ENTRY:		7/16/2009									
<ol> <li>Changes entered in the Oil and Gas Database on:</li> <li>Changes have been entered on the Monthly Operator Changes</li> </ol>	ngo Sn	7/16/2008	-	7/16/2008							
<ol> <li>Changes have been entered on the Monthly Operator Changes.</li> <li>Bond information entered in RBDMS on:</li> </ol>	nge op	7/16/2008		7/10/2008	-						
4. Fee/State wells attached to bond in RBDMS on:		7/16/2008	•								
5. Injection Projects to new operator in RBDMS on:		n/a	-								
6. Receipt of Acceptance of Drilling Procedures for APD/New	on:		7/16/2008								
BOND VERIFICATION:				-							
Federal well(s) covered by Bond Number:		UTB000148									
2. Indian well(s) covered by Bond Number:		RLB0011681	-								
3a. (R649-3-1) The NEW operator of any state/fee well(s) liste	ed cove	ered by Bond N	umber	RLB0004585							
3b. The <b>FORMER</b> operator has requested a release of liability	not yet		-								
LEASE INTEREST OWNER NOTIFICATION:				_							
4. (R649-2-10) The <b>NEW</b> operator of the fee wells has been con	ntacted	and informed b	y a letter fr	om the Division							
of their responsibility to notify all interest owners of this cha			n/a								
COMMENTS:											

STATE OF UTAH

Effective 6/1/2008, pleas Whiting Oil and Gas Corp See attached well list.  Whiting Oil and Gas Corp 1700 Broadway, Suite 23 Denver, CO 80290 (303) 837-1661  Miller, Dyer & Co., LLC 475 17th Street, Suite 12 Denver, CO 80202  Miller, Dyer & Co., LLC	00 N 250	eor Utah BLM Bond #UTB-0 4585 A RLB DO114	ng Oil and Gas Corporation. 000148.
Effective 6/1/2008, pleas Whiting Oil and Gas Corp See attached well list.  Whiting Oil and Gas Corp 1700 Broadway, Suite 23 Denver, CO 80290 (303) 837-1661  Miller, Dyer & Co., LLC 475 17th Street, Suite 12 Denver, CO 80202  Miller, Dyer & Co., LLC	poration Utah State bond is #RLB00167 RLB0000 Poration B / 000 N 3580	eor Utah BLM Bond #UTB-0 4585 A RLB DO114	RECEIVED JUN 0 5 2008 DIV. OF OIL, GAS & MINING
Effective 6/1/2008, pleas Whiting Oil and Gas Corp See attached well list.  Whiting Oil and Gas Corp 1700 Broadway, Suite 23 Denver, CO 80290 (303) 837-1661  Miller, Dyer & Co., LLC 475 17th Street, Suite 12 Denver, CO 80202	poration Utah State bond is #RLB081167  RLB080  poration  00	£.or Utah BLM Bond #UTB-0	RECEIVED JUN 0 5 2008
Effective 6/1/2008, pleas Whiting Oil and Gas Corp See attached well list.  Whiting Oil and Gas Corp 1700 Broadway, Suite 23 Denver, CO 80290 (303) 837-1661  Miller, Dyer & Co., LLC 475 17th Street, Suite 12	poration Utah State bond is #RLB081167  RLB080  poration  00	£.or Utah BLM Bond #UTB-0	RECEIVED JUN 0 5 2008
Effective 6/1/2008, pleas Whiting Oil and Gas Corp See attached well list.  Whiting Oil and Gas Corp 1700 Broadway, Suite 23 Denver, CO 80290 (303) 837-1661  Miller, Dyer & Co., LLC	poration Utah State bond is #RLB081167  RLB080  poration  00	£.or Utah BLM Bond #UTB-0	ng Oil and Gas Corporation. 000148.  RECEIVED
Effective 6/1/2008, pleas Whiting Oil and Gas Corp See attached well list. Whiting Oil and Gas Corp 1700 Broadway, Suite 23 Denver, CO 80290	ooration Utah State bond is # <del>RLB001167</del> RLB000 Doration	£.or Utah BLM Bond #UTB-0	ng Oil and Gas Corporation. 000148.
Effective 6/1/2008, pleas Whiting Oil and Gas Corp See attached well list.	oration Utah State bond is <del>#RI-R004467</del>	£.or Utah BLM Bond #UTB-0	ng Oil and Gas Corporation. 000148.
Effective 6/1/2008, pleas Whiting Oil and Gas Corp	oration Utah State bond is <del>#RI-R004467</del>	£.or Utah BLM Bond #UTB-0	ng Oil and Gas Corporation. 000148.
12. DESCRIBE PROPOSED OR C			
	OMPLETED OPERATIONS. Clearly show all pertinent d		etc.
		CLAMATION OF WELL SITE  COMPLETE - DIFFERENT FORMATION	OTHER:
(Submit Original Form Ority)  Date of work completion:		ODUCTION (START/RESUME)	WATER SHUT-OFF
SUBSEQUENT REPORT (Submit Original Form Only)	CHANGE WELL NAME PLI	JG BACK	WATER DISPOSAL
Law.		JG AND ABANDON	VENT OR FLARE
Approximate date work will start:		N CONSTRUCTION  ERATOR CHANGE	TUBING REPAIR
(Submit in Duplicate)		ACTURE TREAT	SIDETRACK TO REPAIR WELL  TEMPORARILY ABANDON
NOTICE OF INTENT	ACIDIZE DE	EPEN	REPERFORATE CURRENT FORMATION
TYPE OF SUBMISSION		TYPE OF ACTION	
11. CHECK APP	ROPRIATE BOXES TO INDICATE NAT	JRE OF NOTICE, REPORT	, OR OTHER DATA
QTR/QTR, SECTION, TOWNSHIP, RAI	IGE, MERIDIAN:	ST	TATE:
FOOTAGES AT SURFACE:		co	DUNTY:
1700 Broadway, Ste 2300 CIT	Denver STATE CO ZIP 80290	(303) 837-1661	
3. ADDRESS OF OPERATOR:			FIELD AND POOL, OR WILDCAT:
2. NAME OF OPERATOR: Whiting Oil And Gas Com	pany N2680	9.	API NUMBER:
OIL WELL	GAS WELL OTHER		See Attached List
drill horizontal le	terals. Use APPLICATION FOR PERMIT TO DRILL form for such	proposals.	WELL NAME and NUMBER:
Secretary 41 feet as a second to diffe	ew wells, significantly deepen existing wells below current bottom-r	7.	UNIT or CA AGREEMENT NAME:
	NOTICES AND REPORTS ON V	VELLS 6.	IF INDIAN, ALLOTTEE OR TRIBE NAME:
SUNDRY		1 *-	See Attached List
	DIVISION OF OIL, GAS AND MINING		LEASE DESIGNATION AND SERIAL NUMBER:

Carlene Russell
Division of Oil, Gas and Mining
Earlene Russell, Engineering Technician

		T.	1	<del></del>	T	T-1		T	<u> </u>
well_name	sec	twp	rng	api		lease	_	stat 2	flag
UTE TRIBAL 32-5A	32	140S	200E	4304710577	12655		GW	S	
UTE TRIBAL 30-3A	30	140S	200E	4304710913		Federal			
UTE TRIBAL 30-5A	30	140S	200E	4304720502	<u> </u>	Federal	GW	S	
UTE TRIBAL 30-2A	30	140S	200E	4304730641	<del> </del>	Federal	<u> </u>	P	
UTE TRIBAL 29-1A	29	140S	200E	4304730981		Federal			
UTE TRIBAL 32-1A	32	140S	200E	4304732758	12064	State	OW		
UTE TRIBAL 29-2A	29	140S	200E	4304732945	8118	Federal	OW	P	
UTE TRIBAL 32-2A	32	140S	200E	4304733333	12658	State	GW	P	
UTE TRIBAL 32-3A	32	140S	200E	4304733334	12657	State	GW	S	
UTE TRIBAL 32-4A	32	140S	200E	4304733335	12656	State	GW	P	
UTE TRIBAL 32-6A	32	140S	200E	4304733337	12662	State	GW	P	
CHIMNEY ROCK 32-11	32	130S	210E	4304733445	12984	State	GW	S	
CHIMNEY ROCK 32-13	32	130S	210E	4304733447	12985	State	GW	P	
CHIMNEY ROCK 32-14	32	130S	210E	4304733448	12983	State	GW	P	
UTE TRIBAL 32-8A	32	140S	200E	4304733557	13066	State	GW	P	
UTE TRIBAL 32-12A	32	140S	200E	4304733558	13064	State	GW	P	
UTE TRIBAL 28-1A	28	140S	200E	4304733595	13059	Federal	GW	S	
UTE TRIBAL 30-6A	30	140S	200E	4304733596	13062	Federal	GW	P	
UTE TRIBAL 29-4A	29	140S	200E	4304733616	13060	Federal	GW	P	
UTE TRIBAL 29-5A	29	140S	200E	4304733617	13061	Federal	GW	P	
UTE TRIBAL 32-7A	32	140S	200E	4304733618	13065	State	GW	S	
UTE TRIBAL 32-9A	32	140S	200E	4304733619	13067	State	GW	P	
UTE TRIBAL 32-10A	32	140S	200E	4304733620	13054	State	GW	P	
UTE TRIBAL 32-11A	32	140S	200E	4304733621	13058	State	GW	S	
UTE TRIBAL 32-16A	32	140S	200E	4304734098	13449	State	GW	P	
UTE TRIBAL 29-6A	29	140S	200E	4304734102	13443	Federal	GW	P	
UTE TRIBAL 29-7A	29	140S	200E	4304734103	13444	Federal	GW	P	
UTE TRIBAL 10-2-15-20	02	150S	200E	4304735625	14167	State	GW	P	
FLAT ROCK 13-29-14-20	29	140S	200E	4304736778	15065	Federal	GW	P	
FLAT ROCK 3-29-14-20	29	140S	200E	4304736795	15099	Federal	GW	P	
UTE TRIBAL 6-16-14-20	16	140S	200E	4304738506	16320	State	GW	P	
UTE TRIBAL 15-25-14-19	30	140S	200E	4304739052	16169	Indian	GW	P	C
UTE TRIBAL 1-25-14-19	30	140S	200E	4304739053		Indian	GW	APD	
UTE TRIBAL 1-30-14-20	30	140S	200E	4304739665		Federal	GW	APD	
UTE TRIBAL 9-30-14-20	30	140S	200E	4304739666		Federal	GW	APD	
UTE TRIBAL 7-30-14-20	30	140S	200E	4304739667		Federal	GW	APD	
UTE TRIBAL 7-29-14-20	29	140S	200E	4304739668		Federal	GW	APD	
UTE TRIBAL 9-29-14-20	29	140S	200E	4304739669	_	Federal	-	APD	
UTE TRIBAL 12-28-14-20	28	140S	200E	4304739736		Federal		APD	
UTE TRIBAL 1-29-14-20	29	140S	200E	4304739737		Federal	GW	APD	
UTE TRIBAL 15-29-14-20	29	140S	200E	4304739738		Federal		APD	
UTE TRIBAL 3-30-14-20	30	140S	200E	4304739739		Federal	+	APD	
UTE TRIBAL 11-30-14-20	30	140S	200E	4304739740		Federal	_	APD	
UTE TRIBAL 3-32-14-20	32	140S	200E	4304739741		State	GW	APD	
UTE TRIBAL 15-30-14-20	30	140S	200E	4304739942		Federal	GW	APD	

## Earlene Russell - PEN 16320

From:

Sue Stewart

To:

Russell, Earlene

Date:

5/10/2010 10:35 AM

Subject: PEN 16320

4304738506 Ute Tribal 6-16-14-20 T145 R 20E Sec 16

## Earlene.

I was looking at PEN 16320 and noticed that DOGM shows the lease on that PEN as being ML 47502 and SITLA shows it as ML 50734. ML 47502 was replaced by ML 50734 on 3/2/2007.

**Thanks** 

Sue Stewart Trust Lands Administration Royalty Auditor SueStewart@utah.gov Wk 801-538-5133 Fax 801-538-5118 Wk Hrs M-TH, 5:30am to 4:00pm

changed 5/18/10 5/18/10

Sundry Number: 59750 API Well Number: 43047385060000

	STATE OF UTAH		FORM 9					
	DEPARTMENT OF NATURAL RESOURCES DIVISION OF OIL, GAS, AND MININ		5.LEASE DESIGNATION AND SERIAL NUMBER:					
	DIVISION OF OIL, GAS, AND MININ		ML-50734					
SUNDR	RY NOTICES AND REPORTS ON	I WELLS	6. IF INDIAN, ALLOTTEE OR TRIBE NAME: UTE					
	oposals to drill new wells, significantly dee reenter plugged wells, or to drill horizonta n for such proposals.		7.UNIT or CA AGREEMENT NAME:					
1. TYPE OF WELL Gas Well			8. WELL NAME and NUMBER: UTE TRIBAL 6-16-14-20					
2. NAME OF OPERATOR: WHITING OIL & GAS CORPO	DRATION		<b>9. API NUMBER:</b> 43047385060000					
3. ADDRESS OF OPERATOR: 1700 Broadway, Suite 2300	9. FIELD and POOL or WILDCAT: FLAT ROCK							
4. LOCATION OF WELL FOOTAGES AT SURFACE: 1846 FNL 2065 FWL			COUNTY: UINTAH					
QTR/QTR, SECTION, TOWNSI Qtr/Qtr: SENW Section:	STATE: UTAH							
11. CHEC	K APPROPRIATE BOXES TO INDICATE I	NATURE OF NOTICE, REPOF	RT, OR OTHER DATA					
TYPE OF SUBMISSION		TYPE OF ACTION						
	ACIDIZE	ALTER CASING	CASING REPAIR					
NOTICE OF INTENT Approximate date work will start:	CHANGE TO PREVIOUS PLANS	CHANGE TUBING	CHANGE WELL NAME					
	☐ CHANGE WELL STATUS	COMMINGLE PRODUCING FORMATIONS	CONVERT WELL TYPE					
SUBSEQUENT REPORT Date of Work Completion:	DEEPEN	FRACTURE TREAT	☐ NEW CONSTRUCTION					
12/7/2014	OPERATOR CHANGE	PLUG AND ABANDON	PLUG BACK					
SPUD REPORT	PRODUCTION START OR RESUME	RECLAMATION OF WELL SITE	RECOMPLETE DIFFERENT FORMATION					
Date of Spud:	REPERFORATE CURRENT FORMATION	SIDETRACK TO REPAIR WELL	TEMPORARY ABANDON					
_	TUBING REPAIR	VENT OR FLARE	WATER DISPOSAL					
DRILLING REPORT Report Date:	WATER SHUTOFF	SI TA STATUS EXTENSION	APD EXTENSION					
	☐ WILDCAT WELL DETERMINATION ✓	OTHER	OTHER: Isolate Navajo					
	COMPLETED OPERATIONS. Clearly show all p 2 12,113' and dumped 1.5 sack w/ production tbg to 11,985	s of sand on top. RIH	·					
NAME (PLEASE PRINT) Cara Mezydlo	<b>PHONE NUMBER</b> 303 876-7091	TITLE Engineering Technician						
SIGNATURE N/A		DATE 1/9/2015						

Whiting Oil & Gas Corp 1700 Broadway, Suite 2300 Denver, CO 80290 (303) 837-1661

4.0 12/6/2014

5.0 12/7/2014

4.0

5.0

12/7/2014

12/8/2014

## **Job Summary**

Well Name: UTE TRIBAL 6-16-14-20

Isolate Zone Job Started on 12/3/2014

API Number ield Name Operator Gr Elev (ft) County 1UT026830 4304738506 Uintah UT WOGC 6,838.50 6,858.00 Flat Rock Total AFE Amount (Cost) AFF Number Supp Amt (Cost) Total AFE + Supp Amount (Cost) AFE-Field Estimate (Cost) Job Category Job Type Working Interest (%) Total Fld Est (Cost) Start Date End Date Workover Isolate Zone 38.42 45,657.00 12/3/2014 Daily Operation Reports (6am to 6am) Job Day (days) Rpt# Start Date End Date Summary 1.0 1 0 12/3/2014 12/4/2014 SICP = 240 psi, SITP = 240 psi. RU Delsco Northwest Inc slick line truck, RIH with Xline Plug 1.790" OD, 1 3/8" FN. Tagged XN Nipple @ 12,190'. Tried to latch plug into profile nipple, no luck. POOH with slick line, sealing cups were torn off plug and found scale built up around tool. Notified Jared Huckabee, RIH with slick line scratching tool on slick line to try clean out ID of XN Nipple tagged @ 12187'. Worked down to 12196' and stacked out, worked thru XN Nipple to try clean out scale. POOH with slick line, RIH with another Xline plug (1.790 OD 1 3/8" FN) worked thru x nipple @ 12,143', stacked out in XN nipple @ 12187', tried to latch plug into XN nipple no luck, and released wireline truck, POOH with slick line and found sealing cups torn off and some markings on bottom of plug possibly from tagging on obstructions down hole, released slick line unit, shut in well and SDFN. 2.0 12/4/2014 SICP = 385 psi, SITP = 390 psi. Spot in and rigged up Red Rock Well Service rig # 2. Bled off well to 12/5/2014 20 production tanks, removed production tree and installed Weatherford 7 1/16" 5K BOP. Stung out of packer 30k over string weight, tallied out of hole with production TBG detail as follows: KB - 19.5 2 3/8" 4.7# N-80 Pup JT- 2.20 375 JTS 2 3/8" 4.7# N-80 TBG - 12059.29' 2 3/8" Xnipple - 1.10 1 JT 2 3/8" 4.7# N-80 TBG - 31.93 2 3/8" Sliding Sleave - 2.75 2 3/8" 4.7# N-80 Pup JT- 8.08 2 3/8" XN Nipple - 1.25 Cross Over - .50 Baker GBH-22 Locator Seal - 2.53 Stinger - 11.85 according to TBG tally Packer should be set @ 12,130'+/-Sliding sleeve appears to be only partially opened, TBG and BHA look good. Secured wellhead valves and SDFN 3.0 3.0 12/5/2014 12/6/2014 SICP =180 psi. Bled off well to production tanks, RU Rocky Mountain Wireline. RIH with 5-1/2" CICR, tagged pkr @ 12133' WL depth, correlated back to TBG tally depth of 12128', logged up hole found CSG collar @ 12122', and set CICR @ 12113'. Sat down on retainer to verify set depth good set, POOH with wireline. PU 4" Dump Bailer and filled with 1.5 sx (100 LB/sack, 40/60 mesh, .35mm) sand. Top of sand calculated to 12106'. RIH with wireline, tagged CICR @ 12113', PU hole 25' and dumped sand. Wait 5 minutes, tagged up sand to make sure glass broke on bailer. POOH RD and released wireline. RIH with Production TBG, land TBG Hanger. Floor up rig and rack out handling equipment, removed Weatherford BOPE and install production tree. Secured wellhead valves shut in well and SDFN. TBG detail: KB - 19.5' 370 JTS 2 3/8" 4.7# N-80 TBG - 11897.80 2 3/8" X Nipple 1.875 profile - 1.10 w/ bumper spring in place 27.2" long 1 3/8" FN and 1.900" OD NG 1 JT 2 3/8" 4.7# N-80 TBG - 32.37 2 3/8" XN Nipple 1.875 profile - 1.25 w/ 1.790" NG

1 JT 2 3/8" 4.7# N-80 TBG - 32.37 2 3/8" Wireline reentry guide - .33 TBG landed @ - 11984.72'

moved off location.

Page 1/1 Report Printed: 1/9/2015

SICP = 10 psi, SITP = 10 psi. Bled off TBG to rig tank, dry gas no fluid, rigged up swab lubricator and

SICP = 470 psi, SITP = 15 psi. RD Red Rock Well Service rig #2, racked out support equipment and

started swabbing operations. Initial fluid level 8900' +/-. Made 14 swab runs and recovered 62 bbl, ending fluid level 9700' and SICP 280 psi. See swab report for details. Shut in and secured wellhead

Note: Had slight foam on first couple of runs then fluid cleaned up.

RECEIVED: Jan. 09, 2015

v	VHITING					V	Le Vell Nan	ase F ne: U					4-20												
	umber		WPC ID	`		Well	Permit Numb	er			ield Name						County	<u> </u>				State			
Well (	1738506 Configuration Type		1UT026830		B Elv (ft)			levation (ft		C	Flat Roc asing Flar		vation (ft)	Tub	ing He	ad Elevat	Uintal		Depth (	ftKB)		UT			
Origin	ated/Direction al Spud Date		npletion Date	Ass	6,8 set Group	58.0	0		6,838. esponsib		jineer			N/S	Dist (ft		N/S F		/W Dist	(ft)		12,517.0 E/W Ref			
Lot	7/16/2007 IQI	uarter 1	4/11/2008		entral Rockies    Quarter 4   Sec		Section	Ja on Suffix	ared H			wnship	Іто	wnship	N/S Di	,	1,846.0 FNL Range		E/W Di		5.0 eridiar	FWL			
L	S	E	NW				16			.,,,-			14 S					20 E							
MD	Deviated/Directi	ional -	Original Hole,	1/9/201	5 2:13:12 PM		Wellbore	Section De					e Name		5	Start Date		Size (in)	Act To	op (ftKB)	Ac	ct Btm (ftKB)			
(ftKB)		Ve	ertical schemati	,	,		Conduct	or		- 1	Origina				1	6/2007		26		19.5		40.0			
- 19.4 -			19.	124; 19.	y Joints; 20; 5; 19.00 Shoe; 20; 38.5;	MINIM	Surface Production	on			Origina Origina					7/2007		12 1/4 8 7/8	3	40.0 3,430.0		3,430.0 12,517.0			
. 38.4 .			1.50	0			Conduc		, 40.0										0,400.0 12,017.0						
- 40.0 -			<b>√</b> 4.89	92; 19.5	Joints; 5 1/2; ; 1,999.59		OD (in) 20	ID (in) 19.124	_	(lb/ft) 4.00	Gra J-55	ade	Тор	(ftKB) 19.5	_	m (ftKB) 38.5	_	en (ft) 19.00							
_ 2,019.0 -					Joints; 9 5/8; ; 3,399.00		20				38.5	1	40.0	1			e Shoe								
3,418.6	88	_2 2, Salas Silos, S 6/6,		Surface OD (in)	Csg, 3,		ftKB (lb/ft)	Gra	ado	Ton	(ftKB)	I D+	m (ftKB)		en (ft)		Ito	n Des	`						
3,419.9		3,418.5; 1.50 7-1; Tubing; 2 3/8; 1.995; \$\int 19.5; 11,897.80\$		9 5/8	8.921			J-55	auc	ТОР	19.5		3,418.5	_	,399.00	Casii	ng Join		•						
- 3,430.1 -			3-2;	; Casing	Joints; 5 1/2; 9.1; 8,335.50	^~	9 5/8		40.5	10.0	fu/D		3,	418.5		3,420.0	)	1.50	Guid	e Shoe	)				
- 10,354.7 -			3-3;		Tool; 5 1/2;		OD (in)	ID (in)	,, ,	(lb/ft)		ade	Тор	(ftKB)	Bt	m (ftKB)	L	en (ft)		Ite	m Des	3			
. 10,356.6			_ 3-4;	; Casing	Joints; 5 1/2;		5 1/2	4.892			P-110			19.5	1	2,019.1	1 '	,999.59		ng Join					
- 11,032.2 -	······		_ 3-5;	; Casing	56.7; 675.54 Joints; 5 1/2;		5 1/2 5 1/2	4.892	2 1	7.00	N-80		· · · · · ·	019.1 354.6		0,354.6 0,356.7		,335.50		ng Join e Tool	เร				
- 11,570.2 -			3-6;	; Entrad	32.3; 537.95 a Marker Joint;		5 1/2	4.892	2 17	7.00	N-80		10,	356.7	1	1,032.3	1	675.54	"		ts				
- 11,588.3 -			1/2;	; 4.892;	11,570.2; 17.95		5 1/2	4.892			P-110		1	032.3	1	1,570.2	1	537.95		•		la in t			
. 11,910.1					11,910.0- 0/28/2007		5 1/2 5 1/2	4.892 4.892			P-110 P-110			570.2 588.2		1,588.2 2,468.0		879.85		ada Ma ng Join		Joint			
- 11,917.3 -			7-2;	; X-Nipp	le w/ bumper 8; 1.875;		5 1/2						1	468.0	1	2,469.3	1			Collar					
- 11,918.3 -				917.3; 1			5 1/2	4.892	2 17	7.00	P-110		1	469.3	1	2,508.7	1			ng Join	ts				
. 11,919.9 .	<u>  281</u> 			; Tubing 918.4; 3	; 2 3/8; 1.995; 2 39		5 1/2 Cement	Stages					12,	508.7	1	2,510.0	)	1.35	Float	Shoe					
- 11,950.8 -			7-4;	,	ople; 2 3/8; 1.87	5;	Conduct	Des			mp Start I 7/2007	Date	Drill	Out Dat	te	Top (	ftKB) 19.5		(ftKB) 40.0		ор Ме	eas Meth			
- 11,952.1 -			Per	forated;	11,952.0- 0/23/2007		Surface		#IIL	l	7/2007						19.5	1	,420.0						
- 11,957.0 -	8		7-5;	,	; 2 3/8; 1.995;		Cement			0 /0 //							40.5	10	= 40.4						
. 11,982.9	<u>88</u>		11,3	952.0, 3	2.37		Production Cement	on Casır	ng	9/3/2	2007						19.5	12	,510.0	'					
- 11,984.3 -				; Wirelir 984.4; 0	ne Guide; 2 3/8;		Cement		hoe	9/3/2	2007					12,	510.0	12	,517.0	ו					
- 11,984.6 -					11,983.0- 0/23/2007			71					Itm (ftKB)				Zone								
. 11,987.9 .							Perforate			28/20			,	10.0				ntrada,	•		Hole				
- 11,994.1 -					11,994.0- 0/23/2007		Perforate					ntrada, ntrada,	_												
- 11,999.0 -			11,,	333.0, 1	0/20/2007		Perforate			23/20				94.0			- 1	ntrada,	U						
- 12,003.0 -					12,003.0- 0/23/2007		Perforate			23/20			12,0				- 1	ntrada,	U						
12,007.9			12,0	000.0, 1	0.20.2001		Perforate Perforate			23/20 23/20			12,0	14.0 24.0				ntrada, ntrada,	•						
- 12,014.1 -					12,014.0- 0/23/2007		Perforate			23/20				37.0				ntrada,	_		;				
- 12,019.0 -	8		Per	forated;	12,024.0-		Perforate Perforate			9/200 5/200			12,256.0 12,282.0				- 1	0 Navajo, Original Hole 0 Navajo, Original Hole							
12,023.9			3-7;	; Casing	0/23/2007 Joints; 5 1/2;		Stim/Tre			<i>7200</i>	· I		12,2	02.0		12,29	0.0   14	avajo, C	Jilgille	ai i ioie					
12,028.9			4.89	92; 11,5	88.2; 879.85		Stage	Туре	Sta	art Date	e	Top (ftK	(B)	Btm (ft	KB)		5	Stim/Treat F	Fluid			Vol Clean Pump (bbl)			
- 12,037.1 - - 12,042.0 -					12,037.0- 0/23/2007		Acidization	on	9/21/2			12,2		,		7 1/2%	,	•	20004	20/40		124.00			
12,106.0							Frac		10/6/2	2007		12,2	36.0	12,2	.92.0			Mesh, 62 tns, CO2		20/40		529.00			
12.112.9		8	12,	113.0	l; 12,106.0-		Acidization	on	10/24			11,9		,		7 1/2%			2000	. 00/40	Ι	118.50			
- 12,112.9 -				CR; 4 3/4 115.0	1; 12,113.0-		Frac		10/28	1200	/	11,9	02.0	12,0	42.0	5100#  wh sd		Mesh, 92	∠000#	- ∠0/40		645.00			
12,191.6							Frac		10/28	/200	7	11,9	10.0	11,9	20.0	2900# snd, C		Mesh, 3	1500#	wh		356.00			
12,196.2							Tubing -	Produc	ction	set a	t 11,98	4.7ftK	 (B on 1	2/5/20	014 0	· ·	.02								
- 12,204.4 -							Set Depth (		Commer		-						F	Run Date 12/5/	2014	Pull	Date				
- 12,205.4 -								Item I	Des			OD (in)	ID (in)			Grade	Jts	Len (f	ft)	Top (ftKE	_	Btm (ftKB)			
12,205.7							Tubing					2 3/8	1.995	9 4	.70   I	80	370	11,89	0	19	.5	11,917.3			
- 12,255.9 -					40.050		X-Nipple	w/ bum	per sp	oring		2 3/8								11,917		11,918.4			
- 12,261.2 -					12,256.0- /19/2007		Tubing XN-Nipp	le				2 3/8 2 3/8	1.995		.70   I	80	1	1	- 1	11,918 11,950		11,950.8 11,952.0			
_ 12,282.2 _			Don	forsted.	12,282.0-		Tubing					2 3/8	1.995		.70 L	80	1			11,952		11,932.0			
. 12,290.0					12,282.0- /15/2007		Wireline					2 3/8						0	.33	11,984	.4	11,984.7			
- 12,292.0 -			<u></u>				Rod Stri	•	run>																
_ 12,349.1 _		Sand fill; 4 3/4; 12,349.0-					Rod Descrip								Run D	ate			Pull Da	ate					
- 12,467.8 -		11 8	12,5	510.0	3/4; 12,349.0- Collar; 5 1/2;				Item De	:S			OD (in)		Grad	ie	Jts	Len (f	ft)	Top (ftKE	3)	Btm (ftKB)			
- 12,469.2 -		11 8	12,4	468.0; 1	.25		Other St	ringe																	
- 12,508.5 -		11 88	4.89	92; 12,4	Joints; 5 1/2; 69.3; 39.40		Set Depth (	ftKB)	Commer		te co	okr oc	t @ 104	150' -	ut c	ıbsca	nt th-	Run Da	ate 10/20		ull Da	te			
_ 12,509.8 _				0; Float 508.7; 1	Shoe; 5 1/2; .35		12		runs s	how						ibseque epth to			10/20	10					
_ 12,517.1 _		<b>**</b>						[1	tbg tal	ıy.															
1																									

W	HITING				V	Lease Vell Name:				-20					
API No 4304	umber 1738506		WPC ID 1UT026830	)	Well	Permit Number		Field N					County Uintah		State UT
	Configuration Ty ated/Direct		•	Orig KB Elv (ft)	3,858.0	Ground Elevation	(ft) 6,838.5		Flange Elevat	tion (ft)	Tubin	ig Head Eleva	tion (ft)	otal Depth (ftKB)	12,517.0
	al Spud Date 7/16/2007	Cor	npletion Date 4/11/2008	Asset Group Central Rock	ies		Responsible				N/S D		N/S Ref .0 FNL	E/W Dist (ft) 2,06	E/W Ref 65.0 FWL
Lot		Quarter SE	1 Quarter 2 Q NW	uarter 3 Quarter 4	Section	Section Suffix	Section 1	Гуре	Township	Tow 14 S	nship N	/S Dir Rang	ge Ra 20 E		leridian
MD	Deviated/Dire	ectional -	- Original Hole,	1/9/2015 2:13:12 PM	1	Baker F-1 Per	Item De		5-30		(in) 9/16	ID (in) 2.668	Len (ft) 4.50	Top (ftKB) 12,191.7	Btm (ftKB) 12,196.2
(ftKB)		V	ertical schemati	·		Tubing Sub					2 7/8	2.441	8.00	12,196.2	12,204.2
- 19.4 - - 38.4 -			19.1 1-2; \sum_1.50	; Guide Shoe; 20; 38 )		Baker BXN Pr WL Guide; Pu 11/17/10			oved		.662 .662	2.310 2.441	1.10 0.30	12,204.2 12,205.4	12,205.4 12,205.7
- 40.0 -			<b>4.8</b> 9	; Casing Joints; 5 1/2 92; 19.5; 1,999.59		Other In Hole		1 6	DD (in)	ID (in)		Run Date	Pull D	Acto Ton (#W	D) Dtm (#I/D)
_ 2,019.0 _				; Casing Joints; 9 5/8 21; 19.5; 3,399.00	3;	Sand	8		4 3/4	ID (in)	12/	5/2014	Pull L	Pate Top (ftK 12,106	
- 3,418.6 -				; Guide Shoe; 9 5/8;		CICR Sand fill			4 3/4			5/2014 /2007		12,113 12,349	
. 3,419.9			7-1;	18.5; 1.50 ; Tubing; 2 3/8; 1.99 5; 11,897.80	5;	Bottom Hole	Cores		4 3/4		9/2/	2007		12,343	9.0 12,310.0
- 3,430.1 -		88	<b>-</b> 3-2;	; Casing Joints; 5 1/2 92; 2,019.1; 8,335.50	<u>;</u> ~~	Date		Cor	e#		Top (ftl	(B)	Btm (ftl	(B)	Recov (ft)
- 10,354.7 -			3-3;	; Stage Tool; 5 1/2; 354.6; 2.12											
. 10,356.6			_ 3-4;	; Casing Joints; 5 1/2 92; 10,356.7; 675.54											
- 11,032.2 -		8 (8888)	_ 3-5;	; Casing Joints; 5 1/2 92; 11,032.3; 537.95	<u>2;</u>										
- 11,570.2 -			3-6;	; Entrada Marker Joi	nt; 5										
- 11,588.3 -				4.892; 11,570.2; 17	.ฮง	1									
. 11,910.1				forated; 11,910.0- 920.0; 10/28/2007											
- 11,917.3 -			7-2; spri	; X-Nipple w/ bumpe ing; 2 3/8; 1.875;		1									
- 11,918.3 -			11,9	917.3; 1.10		1									
. 11,919.9		100 100 100 100 100 100 100 100 100 100		; Tubing; 2 3/8; 1.99 918.4; 32.39	5;	1									
- 11,950.8 -	······································			; XN-Nipple; 2 3/8; 1 950.8; 1.25	.875;										
- 11,952.1 -	Ĭ.	1 888		forated; 11,952.0- 957.0; 10/23/2007											
- 11,957.0 -		8		; Tubing; 2 3/8; 1.99 952.0; 32.37	5;										
_ 11,982.9 _															
- 11,984.3 -			7-6; \int 11,9	; Wireline Guide; 2 3 984.4; 0.33	/8;										
- 11,984.6 -			Per	forated; 11,983.0- 988.0; 10/23/2007											
_ 11,987.9 _		2000													
- 11,994.1 -		*	Per 11.9	forated; 11,994.0-											
- 11,999.0 -															
- 12,003.0 -		200000	Per 12,0	forated; 12,003.0- 008.0; 10/23/2007											
_ 12,007.9 _			H			Ì									
- 12,014.1 - - 12,019.0 -		8000	Peri 12,0	forated; 12,014.0- 019.0; 10/23/2007											
12,019.0		888	_Per	forated; 12,024.0-											
12,028.9		(888)		029.0; 10/23/2007 ; Casing Joints; 5 1/2											
- 12,026.9 -		S988 ( S888	4.89	92; 11,588.2; 879.85											
12,037.1			Per	forated; 12,037.0- 042.0; 10/23/2007											
12,106.0															
12,112.9	<b></b>	<u> </u>	12,1	nd; 4 3/4; 12,106.0- 113.0											
- 12,115.2 -				CR; 4 3/4; 12,113.0- 115.0											
. 12,191.6															
- 12,196.2 -															
- 12,204.4 -															
- 12,205.4 -															
. 12,205.7															
- 12,255.9 -				ft-d, 40 050 0											
- 12,261.2 -	1000 1000 1000 1000 1000 1000 1000 100			forated; 12,256.0- 261.0; 9/19/2007											
- 12,282.2 -			Dor	forated; 12,282.0-											
- 12,290.0 -			12,2	290.0; 9/15/2007											
- 12,292.0 -															
- 12,349.1 -			C	nd fill; 4 3/4; 12,349.0											
- 12,467.8 -			12,5	510.0	<del>-</del>										
12,469.2		111	3-8; 12,4	; Float Collar; 5 1/2; 468.0; 1.25											
12,508.5		<mark>     </mark>	4.89	; Casing Joints; 5 1/2 92; 12,469.3; 39.40	<u>'</u> ;										
. 12,509.8		III &		0; Float Shoe; 5 1/2; 508.7; 1.35											
. 12,517.1															

Page 2/2

Report Printed: 1/9/2015

Division of Oil, Gas and Mining

Operator Change/Name Change Worksheet-for State use only

Effective Date:

8/1/2015

FORMER OPERATOR:	NEW OPERATOR:	
WHITING OIL & GAS CORPORATION N2680	COBRA OIL & GAS CORPORATION N4270	
1700 BROADWAY SUITE 2300	PO BOX 8206	
DENVER CO 80290	WICHITA FALS TX 76307-8206	
CA Number(s):	Unit Name: None	

#### **WELL INFORMATION:**

Well Name	Sec	TWN	RNG	API	Entity	Mineral	Surface	Туре	Status
See Attached List									

## **OPERATOR CHANGES DOCUMENTATION:**

1. Sundry or legal documentation was received from the **FORMER** operator on:

8/4/2015

2. Sundry or legal documentation was received from the **NEW** operator on:

8/4/2015

3. New operator Division of Corporations Business Number:

9442951-0143

## **REVIEW:**

1. Surface Agreement Sundry from **NEW** operator on Fee Surface wells received on:

N/A

2. Receipt of Acceptance of Drilling Procedures for APD on:

N/A

3. Reports current for Production/Disposition & Sundries:

10/5/2015

4. OPS/SI/TA well(s) reviewed for full cost bonding:

10/2/2015

5. UIC5 on all disposal/injection/storage well(s) approved on:

N/A

6. Surface Facility(s) included in operator change:

Chimney Rock Compressor Flat Rock Compressor

\_ ----**\_**----**\_**----**\_**----**\_**-----**\_**-----**\_**-----

7. Inspections of PA state/fee well sites complete on (only upon operators request):

10/15/2015

## **NEW OPERATOR BOND VERIFICATION:**

1. Federal well(s) covered by Bond Number:

B009425

2. Indian well(s) covered by Bond Number:

B009425

3.State/fee well(s) covered by Bond Number(s):

B009455

B009568-FCB

B009567-FCB

B009566-FCB

## **DATA ENTRY:**

1. Well(s) update in the **OGIS** on:

10/14/2015

2. Entity Number(s) updated in **OGIS** on:

10/14/2015

3. Unit(s) operator number update in **OGIS** on:

N/A

4. Surface Facilities update in **OGIS** on:

N/A 10/14/2015

5. State/Fee well(s) attached to bond(s) in RBDMS on:6. Surface Facilities update in RBDMS on:

10/14/2015

## LEASE INTEREST OWNER NOTIFICATION:

1. The NEW operator of the Fee (Mineral) wells has been contacted and informed by a letter from the Division

of their responsibility to notify all interest owners of this change on:

N/A

## **COMMENTS:**

From: Whiting Oi Gas Corporation To: Cobra Oil Gas Corporation Effective:8/1/2015

LITECTIVE.OF ITZU IS									
Well Name	Section	TWN	RNG	API Number	Entity	Mineral	Surface	Туре	Status
UTE TRIBAL 32-5A	32	140S	200E	4304710577	12655	State	Indian	GW	P
UTE TRIBAL 30-3A	30	140S	200E	4304710913	12395	Federal	Indian	OW	P
UTE TRIBAL 29-1A	29	140S	200E	4304730981	8118	Federal	Indian	GW	P
UTE TRIBAL 32-2A	32	140S	200E	4304733333	12658	State	Indian	GW	P
UTE TRIBAL 32-6A	32	140S	200E	4304733337	12662	State	Indian	GW	P
CHIMNEY ROCK 32-13	32	130S	210E	4304733447	12985	State	State	GW	P
CHIMNEY ROCK 32-14	32	130S	210E	4304733448	12983	State	State	GW	P
UTE TRIBAL 32-8A	32	140S	200E	4304733557	13066	State	Indian	GW	P
UTE TRIBAL 32-12A	32	140S	200E	4304733558	13064	State	Indian	GW	P
UTE TRIBAL 30-6A	30	140S	<del></del>	4304733596	+	Federal	Indian	GW	P
UTE TRIBAL 29-5A	29	140S		4304733617	13061	Federal	Indian	GW	P
UTE TRIBAL 32-7A	32	140S		4304733618	13065	<del></del>	Indian	GW	P
UTE TRIBAL 32-9A	32	140S		4304733619	13067		Indian	GW	P
UTE TRIBAL 32-10A	32	140S		4304733620	13054		Indian	GW	P
UTE TRIBAL 32-16A	32	140S		4304734098	13449		Indian	GW	P
UTE TRIBAL 29-6A	29	140S		4304734102		Federal	Indian	GW	P
UTE TRIBAL 29-7A	29	140S		4304734103		Federal	Indian	GW	P
	2	150S		4304735625			Indian	GW	P
FLAT ROCK 13-29-14-20	1	140S	+	4304736778		Federal	Indian	GW	P
FLAT ROCK 3-29-14-20	29	140S	<del> </del>	4304736795		Federal	Indian	GW	P
UTE TRIBAL 6-16-14-20	16	140S		4304738506	16320		Indian	GW	P
UTE TRIBAL 15-25-14-19	<del></del>	140S	+		16169		Indian	GW	P
UTE TRIBAL 1-30-14-20	30	140S	<del></del>			Federal	Indian	GW	P
UTE TRIBAL 3-30-14-20	30	140S		4304739739		Federal	Indian	GW	P
UTE TRIBAL 11-30-14-20		140S				Federal	Indian	GW	P
UTE TRIBAL 5-32-14-20	32	140S		4304739741	17406		Indian	GW	P
UTE TRIBAL 15-30-14-20		140S		4304739942		Federal	Indian	GW	P
	30	140S		4304750654	17454		Indian	GW	P
UTE TRIBAL 13-25-14-19	17.	140S	+	4304750689	17808		Indian	GW	P
	26	140S		4304750690	17760		Indian	GW	P
UTE TRIBAL 3-25-14-19	30	140S		4304751030	17759		Indian	GW	P
CHIMNEY ROCK 32-11	32	130S		4304733445	12984	State	State	GW	PA
UTE TRIBAL 32-11A	32	140S		4304733621	13058	State	Indian	GW	PA
FLAT ROCK 13-32-14-20		140S		4304736992	17354	·	Indian	D	PA
FLAT ROCK 14-32-14-20		140S		4304736993			Indian	D	PA
FLAT ROCK 14-32-14-20		140S			17356		Indian	D	PA
UTE TRIBAL 8-25-14-19	30	140S		4304739953	17353		Indian	D	PA
UTE TRIBAL 30-5A	30	140S		4304739033		Federal	Indian	GW	S
UTE TRIBAL 30-3A	30	140S		4304720302	8112		Indian	GW	S
UTE TRIBAL 32-1A				4304730641		Federal State		OW	S
	32	140S			12064		Indian		
UTE TRIBAL 29-2A	29	1405		4304732945	8118	Federal	Indian	OW	S
UTE TRIBAL 32-3A	32	140S		4304733334	12657		Indian	GW	S
UTE TRIBAL 32-4A	32	1405		4304733335	12656		Indian	GW	S
UTE TRIBAL 28-1A	28	140S		4304733595		Federal	Indian	GW	S
UTE TRIBAL 29-4A	29	140S	200E	4304733616	13060	Federal	Indian	GW	S

# STATE OF UTAH DEPARTMENT OF NATURAL RESOURCES

			SE DESIGNATION AND SERIAL NUMBER: attached exhibit									
	SUNDRY	1 .	DIAN, ALLOTTEE OR TRIBE NAME: attached exhibit									
Do	not use this form for proposals to drill n drill horizontal k		or CA AGREEMENT NAME:									
	drill horizontal k		8, WELL NAME and NUMBER:									
	OIL WELL	See attached exhibit										
	IAME OF OPERATOR:	9. API NUMBER: See attach										
	OBRA OIL & GAS CORI	10. FIELD AND POOL, OR WILDCAT:										
3. ADDRESS OF OPERATOR: PO Box 8206 Wichita Falls STATE TX 76307-8206 (940) 716-5100  10. FIELD AND POOL, OR WILDCAT: See attached exhibit												
4. L	4. LOCATION OF WELL											
F	COOTAGES AT SURFACE: See at	Itached exhibit			COUNT	y: Uintah						
q	TRACTR, SECTION, TOWNSHIP, RAN	IGE, MERIDIAN:		,	STATE							
						UTAH						
11.	CHECK APP	ROPRIATE BOXES TO INDICA	TE N	ATURE OF NOTICE, REPO	RT, O	R OTHER DATA						
	TYPE OF SUBMISSION	<u></u>		TYPE OF ACTION								
	NOTICE OF INTENT	ACIDIZE		DEEPEN		REPERFORATE CURRENT FORMATION						
	(Submit in Duplicate)	ALTER CASING		FRACTURE TREAT	ᆜ	SIDETRACK TO REPAIR WELL						
	Approximate date work will start:	CASING REPAIR		NEW CONSTRUCTION	닏	TEMPORARILY ABANDON						
		CHANGE TO PREVIOUS PLANS	M	OPERATOR CHANGE	닏	TUBING REPAIR						
		CHANGE TUBING	닏	PLUG AND ABANDON	닏	VENT OR FLARE						
Z	SUBSEQUENT REPORT (Submit Original Form Only)	CHANGE WELL NAME	닏	PLUG BACK	닐	WATER DISPOSAL						
	Date of work completion:	CHANGE WELL STATUS	닏	PRODUCTION (START/RESUME)	닏	WATER SHUT-OFF						
	8/1/2015	COMMINGLE PRODUCING FORMATIONS	"  -	RECLAMATION OF WELL SITE	Ц	OTHER:						
		CONVERT WELL TYPE	<u> </u>	RECOMPLETE - DIFFERENT FORMATION		<del></del>						
12.	DESCRIBE PROPOSED OR CO	OMPLETED OPERATIONS. Clearly show at	il pertine	ent details including dates, depths, volum	es, etc.							
		Whiting Oil & Gas Corporation			isted o	n the attached Exhibit, and						
Co	obra Oil & Gas Corporat	tion has been designated as suc	ccess	or Operator.								
Co	bra Oil & Gas Corporat	ion Whiting Oil 8	k Gas	Corporation N2680								
PC	D Box 8206	1700 Bloadw	ray, S	une 2300								
	ichita Falls, TX 76307-8											
רח	ione: (940) 716-5100	Phone: (303)	) 837-	1001								
		11										
		Nich !	Con									
		Rick Ross, S	Senior	Vice President - Operations								
Во	onds through U.S. Speci	ialty Insurance Company										
Ut	ah State Bond: B00945	5										
BL	.M Nationwide Bond: B0	109425										
		•										
	<u></u>											
	D-L4144	Ochomo		Mac President								
NAM	Robert W.	Ospome / O		TITLE Vice President								
SIGN	NATURE KALAT	· WOJ		DATE 7/14/19	<							
GIGI	The state of the s		د مید دست		=							
This s	pace for State use only)											

**APPROVED** 

(See Instructions on Reverse Side)

OCT 1 4 2015

# **Well Exhibit for Utah DOGM**

								LOCATION:
LEASE/UNIT	Lease #	Tribe Name	API#	FIELD	COUNTY	STATE	RESERVOIR	SEC - TWP - RNG
CHIMNEY ROCK 32-11	ML-47437		4304733445	SEEP RIDGE B	UINTAH	UT	DAKOTA	32-T13S-R21E
CHIMNEY ROCK 32-13	ML-47437		4304733447	SEEP RIDGE B	UINTAH	UT	DAKOTA-CEDAR MOUNTAIN	32-T13S-R21E
CHIMNEY ROCK 32-14	ML-47437		4304733448	SEEP RIDGE B	UINTAH	UT	DAKOTA-CEDAR MOUNTAIN	32-T13S-R21E
FLAT ROCK 13-29-14-20	UTU10166		4304736778	FLAT ROCK	UINTAH	UT	ENTRADA	29-T14S-R20E
FLAT ROCK 13-32-14-20	ML-44317		4304736992	FLAT ROCK	UINTAH	UT	WINGT	32-T14S-R20E
FLAT ROCK 14-32-14-20	ML-44317		4304736993	FLAT ROCK	UINTAH	UT	MESA VERDE	32-T14S-R20E
FLAT ROCK 15-32-14-20	ML-44317		4304736994	FLAT ROCK	UINTAH	UT	MESA VERDE	32-T14S-R20E
FLAT ROCK 30-3A	UTU019837		4304730729	-FLAT ROCK	UINTAH	UT	N/A	30-T14S-R20E
FLAT ROCK 3-29-14-20	UTU10166		4304736795	FLAT ROCK	UINTAH	UT	ENTRADA	29-T14S-R20E
UTE TRIBAL 10-2-15-20	ML-46842		4304735625	FLAT ROCK	UINTAH	UT	WASATCH	2-T15S-R20E
UTE TRIBAL 11-30-14-20	UTU019837		4304739740	FLAT ROCK	UINTAH	UT	DAKOTA-BUCKHORN	30-T14S-R20E
UTE TRIBAL 1-25-14-19	1420H625581	Ute Tribe	4304750654	FLAT ROCK	UINTAH	UT	ENTRADA	30-T14S-R20E
UTE TRIBAL 1-30-14-20	UTU019837		4304739665	FLAT ROCK	UINTAH	UT	ENTRADA	30-T14S-R20E
UTE TRIBAL 13-25-14-19	1420H625581	Ute Tribe	4304750689	FLAT ROCK	UINTAH	UT	ENTRADA	26-T14S-R19E
UTE TRIBAL 15-25-14-19	1420H625581	Ute Tribe	4304739052	FLAT ROCK	UINTAH	UT	ENTRADA	30-T14S-R20E
UTE TRIBAL 15-30-14-20	UTU019837		4304739942	FLAT ROCK	UINTAH	UT	ENTRADA	30-T14S-R20E
UTE TRIBAL 28-1A	UTU10166		4304733595	FLAT ROCK	UINTAH	UT	DAKOTA	28-T14S-R20E
UTE TRIBAL 29-1A	UTU10166		4304730981	FLAT ROCK	UINTAH	UT	WASATCH	29-T14S-R20E
UTE TRIBAL 29-2A	UTU10166		4304732945	FLAT ROCK	UINTAH	UT	WASATCH	29-T14S-R20E
UTE TRIBAL 29-3A	UTU10166		4304732946	FLAT ROCK	UINTAH	UT	WASATCH	29-T14S-R20E
UTE TRIBAL 29-4A	UTU10166		4304733616	FLAT ROCK	UINTAH	UT	DAKOTA	29-T14S-R20E
UTE TRIBAL 29-5A	UTU10166		4304733617	FLAT ROCK	UINTAH	UT	CEDAR MOUNTAIN	29-T14S-R20E
UTE TRIBAL 29-6A	UTU10166		4304734102	FLAT ROCK	UINTAH	UT	CURTIS-ENTRADA	29-T14S-R20E
UTE TRIBAL 29-7A	UTU10166		4304734103	FLAT ROCK	UINTAH	UT	CURTIS-ENTRADA	29-T14S-R20E
UTE TRIBAL 30-1	UTU019837		4 <del>304715764</del>	FLAT ROCK	UINTAH	UT	WASATCH	30-T14S-R20E
UTE TRIBAL 30-2A	UTU019837		4304730641	FLAT ROCK	UINTAH	UT	WASATCH	30-T14S-R20E
UTE TRIBAL 30-3A	UTU019837		4304710913	FLAT ROCK	UINTAH	UT	WASATCH	30-T14S-R20E
UTE TRIBAL 30-4A	UŤU019837		4304716520	FLAT ROCK	UINTAH	UT	TW	30-T14S-R20E
UTE TRIBAL 30-5A	UTU019837		4304720502	FLAT ROCK	UINTAH	UT	WASATCH	30-T14S-R20E
UTE TRIBAL 30-6A	UTU019837		4304733596	FLAT ROCK	UINTAH	UT	DAKOTA	30-T14S-R20E
UTE TRIBAL 32-10A	ML-44317		4304733620	FLAT ROCK	UINTAH	UT	WASATCH	32-T14S-R20E
UTE TRIBAL 32-11A	ML-44317		4304733621	FLAT ROCK	UINTAH	UT	WASATCH	32-T14S-R20E
UTE TRIBAL 32-12A	ML-44317		4304733558	FLAT ROCK	UINTAH	UT	CEDAR MOUNTAIN	32-T14S-R20E
UTE TRIBAL 32-16A	ML-44317		4304734098	FLAT ROCK	UINTAH	UT	DAKOTA-CEDAR MOUNTAIN	32-T14S-R20E
UTE TRIBAL 32-1A	ML-44317		4304732758	FLAT ROCK	UINTAH	UT	WASATCH	32-T14S-R20E
UTE TRIBAL 32-2A	ML-44317		4304733333	FLAT ROCK	UINTAH	UT	WASATCH	32-T14S-R20E
UTE TRIBAL 32-3A	ML-44317		4304733334	FLAT ROCK	UINTAH	UT	WASATCH-MESAVERDE	32-T14S-R20E
UTE TRIBAL 32-4A	ML-44317		4304733335		UINTAH	UT	WASATCH	32-T14S-R20E
UTE TRIBAL 3-25-14-19	1420H625581	Ute Tribe	4304751030		UINTAH	UT	ENTRADA	30-T14S-R20E

# Well Exhibit for Utah DOGM

LEASE/UNIT	Lease # T	ribe Name	API#	FIELD	COUNTY	STATE	RESERVOIR	LOCATION: SEC - TWP - RNG
UTE TRIBAL 32-5A	ML-44317		4304710577	FLAT ROCK	UINTAH	UT	WASATCH	32-T14S-R20E
UTE TRIBAL 32-6A	ML-44317		4304733337	FLAT ROCK	UINTAH	UT	WASATCH	32-T14S-R20E
UTE TRIBAL 32-7A	ML-44317		4304733618	FLAT ROCK	UINTAH	UT	WASATCH	32-T14S-R20E
UTE TRIBAL 32-8A	ML-44317		4304733557	FLAT ROCK	UINTAH	UT	DAKOTA	32-T14S-R20E
UTE TRIBAL 32-9A	ML-44317		4304733619	FLAT ROCK	UINTAH	UT	DAKOTA-CEDAR MOUNTAIN	32-T14S-R20E
UTE TRIBAL 3-30-14-20	UTU019837		4304739739	FLAT ROCK	UINTAH	UT	ENTRADA	30-T14S-R20E
UTE TRIBAL 5-25-14-19	1420H625581 Uto	e Tribe	4304750690	FLAT ROCK	UINTAH	UT	ENTRADA	26-T14S-R19E
UTE TRIBAL 5-32-14-20	ML-44317		4304739741	FLAT ROCK	UINTAH	UT	DAKOTA ENTRADA	32-T14S-R20E
UTE TRIBAL 6-16-14-20	ML-47502		4304738506	FLAT ROCK	UINTAH	UT	ENTRADA	16-T14S-R20E
UTE TRIBAL 8-25-14-19	1420H625581 Uto	e Tribe	4304739053	FLAT ROCK	UINTAH	UT	N/A	30-T14S-R20E



RECEIVED
AUG 0:4 2015

DIV. OF OIL, GAS & MINING

July 16, 2015

Utah Division of Oil, Gas and Mining 1594 West North Temple, Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801

Re: Change of Operator

Whiting Oil and Gas Corporation respectfully submits change of operator sundries for Flat Rock field in Uintah County, UT.

The new operator is Cobra Oil and Gas Corporation PO Box 8206 Witchita Falls, TX 76307-8206 Phone: (940) 716-5100

Regulatory Admin for Cobra: Barbara Pappas 940-716-5103 Barbara@cobraogc.com

Please contact Barbara Pappas or myself if you should have questions or need additional information.

Best Regards

Cara Mezydio,

Engineering Technician III – Central Rockies Asset Group

(303) 876-7091

Cara.mezydlo@whiting.com



RECEIVED
AUG 0.4 2015

DIV. OF OIL, GAS & MINING

July 16, 2015

Utah Division of Oil, Gas and Mining 1594 West North Temple, Suite 1210 Box 145801 Salt Lake City, Utah 84114-5801

Re: Change of Operator

Whiting Oil and Gas Corporation respectfully submits change of operator sundries for Flat Rock field in Uintah County, UT.

The new operator is Cobra Oil and Gas Corporation PO Box 8206 Witchita Falls, TX 76307-8206 Phone: (940) 716-5100

Regulatory Admin for Cobra: Barbara Pappas 940-716-5103 Barbara@cobraogc.com

Please contact Barbara Pappas or myself if you should have questions or need additional information.

Best Regards

Cara Mezvalo,

Engineering Technician III – Central Rockies Asset Group

(303) 876-7091

Cara.mezydlo@whiting.com



## Rachel Medina < rachelmedina@utah.gov>

## **Plugged Wells**

8 messages

Rachel Medina <rachelmedina@utah.gov>
To: Barbara Pappas <br/>
barbara@cobraogc.com>

Thu, Aug 6, 2015 at 11:05 AM

Hi Barbara.

The following Whiting wells are listed on the request for the Cobra operator change, but are currently plugged. Our Division does not usually move plugged well unless the new operator has plans to reenter the wells. Will this be the case for Cobra?

CHIMNEY ROCK 32-11	32	130S	210E 4304733445
UTE TRIBAL 32-11A	32	140S	200E 4304733621
FLAT ROCK 13-32-14-20	32	1 <b>4</b> 0S	200E 4304736992
FLAT ROCK 14-32-14-20	32	140S	200E 4304736993
FLAT ROCK 15-32-14-20	32	140S	200E 4304736994
UTE TRIBAL 8-25-14-19	30	140S	200E 4304739053

Also, the following wells were listed on the exhibit but are not currently operated by Whiting. They will not move in the operator change.

Flat Rock 30-3A 4304730729 Ute Tribal 30-1 4304715764 Ute Tribal 30-4A 4304716520

Thanks!

Rachel Medina Division of Oil, Gas & Mining Bonding Technician 801-538-5260

Rachel Medina <rachelmedina@utah.gov>
To: Barbara Pappas <br/>
barbara@cobraogc.com>

Thu, Aug 6, 2015 at 2:36 PM

Hi Barbara,

Cobra is also taking over 3 State/Fee wells that have been shut in for over a year. Because of this our Petroleum Engineer is requesting a shut in plan and full cost bonding. For the shut in plan you will need to submit an outline and time frame of the plans for each well. To determine full cost bonding you will need to submit a plugging estimate, our engineer will evaluate the cost and set the bond for each well at the estimate or depth bonding (as outline in the rules), whichever is greater.

Please let me know if you have any questions.

Thanks!

[Quoted text hidden]

**Barbara Pappas** <br/>
<br/>
To: Rachel Medina <rachelmedina@utah.gov>

Thu, Aug 6, 2015 at 3:10 PM

Rachel:

I have forwarded to my managers and hopefully will have an answer for you soon.

Thanks,

Barbara

From: Rachel Medina [mailto:rachelmedina@utah.gov]

Sent: Thursday, August 06, 2015 3:37 PM

To: Barbara Pappas <barbara@cobraogc.com>

Subject: Re: Plugged Wells

[Quoted text hidden]

## Rachel Medina < rachelmedina@utah.gov>

Fri, Aug 14, 2015 at 8:58 AM

To: Barbara Pappas <barbara@cobraogc.com>

Hi Barbara,

The Division received confirmation that the plugged wells need to be moved to Cobra. At this point we are waiting for shut in plans and plugging estimates on the following wells.

**UTE TRIBAL 32-1A UTE TRIBAL 32-3A** UTE TRIBAL 32-4A

Thanks!

[Quoted text hidden]

#### Charlie Gibson < charlie@cobraogc.com>

Wed, Aug 19, 2015 at 8:40 AM

To: "rachelmedina@utah.gov" <rachelmedina@utah.gov>

Cc: Rory Edwards <rory@cobraogc.com>, Bobby Hess <br/> <br/> Shess@cobraogc.com>, Kyle Gardner

<kgardner@cobraogc.com>, Barbara Pappas <barbara@cobraogc.com>

Rachel,

We have studied the wells listed below and our estimate to plug the wells is \$20,000/well. We also believe that the wells still have economic potential and plan on working on the wells by 10-1-2015 to attempt to reestablish production. Let me know if you have any questions.

## Charlie Gibson

**Operations Manager** 

## Cobra Oil & Gas

(940)716-5100 (o)

(940)781-6260 (c)

From: Rachel Medina [mailto:rachelmedina@utah.gov]

Sent: Friday, August 14, 2015 9:59 AM

To: Barbara Pappas <barbara@cobraogc.com>

Subject: Re: Plugged Wells

Hi Barbara.

[Quoted text hidden] [Quoted text hidden]

## Rachel Medina < rachelmedina@utah.gov>

To: Dustin Doucet <dustindoucet@utah.gov>

Wed, Aug 19, 2015 at 4:46 PM

What are you thoughts on the full cost bonding and the shut in plan? [Quoted text hidden]

## **Dustin Doucet < dustindoucet@utah.gov>**

To: Rachel Medina <rachelmedina@utah.gov>

Wed, Aug 19, 2015 at 6:16 PM

Without more supporting evidence of their P&A cost estimate, I don't feel comfortable with the estimate provided. It appears several plugs may need to be drilled out to properly isolate formations with open perfs with cement as required by rule. I doubt this was taken into consideration in their estimates. Since they are proposing to work the wells over by October 1, 2015, I would be willing to accept the \$30,000 depth bond per well to get these transferred and let them get the work done with the caveat that we will require more information on P&A costs and would require full cost bonds if found to be more than \$30K per well if the work is not done by October 1, 2015.

[Quoted text hidden]

Dustin K. Doucet
Petroleum Engineer
Division of Oil, Gas and Mining
1594 West North Temple, Ste 1210
Salt Lake City, Utah 84116
801.538.5281 (ofc)
801.359.3940 (fax)

web: www.ogm.utah.gov

## Rachel Medina < rachelmedina@utah.gov>

Thu, Aug 20, 2015 at 9:09 AM

To: Charlie Gibson < charlie@cobraogc.com>

Cc: Rory Edwards <a href="mailto:rory@cobraogc.com">rory@cobraogc.com</a>, Bobby Hess <a href="mailto:bhess@cobraogc.com">bhess@cobraogc.com</a>, Kyle Gardner <a href="mailto:kgardner@cobraogc.com">kgardner@cobraogc.com</a>, Barbara Pappas <a href="mailto:barbara@cobraogc.com">barbara@cobraogc.com</a>

gardner@cobiaogc.com2, Darbara i appas sparbara@cobiaogc.co

Hi Charlie,

The following is our Petroleum Engineer's review;

-Ute Tribal 32-1A, Ute Tribal 32-3A and Ute Triabl 32-4A are each required to have a \$30,000.00 individual bond. -Cobra's plan to put the wells on production by October 1, 2015 is accepted, however a condition has been placed that if the wells are not producing by October 1st the Division will require a new P&A estimate be

submitted and reviewed for full cost bonding.

Please submit bonding for each well, if Cobra needs the new bonding forms again please let me know. As soon as the bond is received we can begin to process the operator change.

Thanks!

[Quoted text hidden]



## Rachel Medina < rachelmedina@utah.gov>

## **Utah Change of Operator from Whiting to Cobra**

1 message

Charlie Gibson < charlie@cobraogc.com>

Thu, Aug 13, 2015 at 2:17 PM

To: "rachelmedina@utah.gov" <rachelmedina@utah.gov>

Cc: Jeff Dillard <ieff@cobraogc.com>, Bob Osborne <br/> <br/>bob@cobraogc.com>, Stephen Howard

<Showard@basinoilandgas.com>, Caven Crosnoe <ccrosnoe@scglaw.com>, Rory Edwards <rory@cobraogc.com>,

Phil Rugeley <phil@cobraogc.com>, Rick Haskin <rick@cobraogc.com>, Barbara Pappas

<barbara@cobraogc.com>

Dear Rachel.

We have been informed by Whiting Oil and Gas Corporation that you have requested an email from Cobra Oil & Gas Corporation acknowledging that we have agreed to assume all plugging, abandoning and reclamation obligations for the wells described below. In accordance with the terms and conditions of the Purchase and Sale Agreement (Agreement) between Whiting Oil and Gas Corporation (Seller) and Cobra Oil & Gas Corporation, et al (Buyer), please be advised the Buyer assumed the obligation to plug and abandon all wells located on the Lands and reclaim all well sites located on the Lands regardless of when the obligations arose. Accordingly Cobra Oil and Gas Corporation, as Operator, assumes those obligations and liabilities associated with the wells described below:

32-11

CHIMNEY ROCK 32130S 210E4304733445

UTE TRIBAL 32- 32140S 200E4304733621

11A

FLAT ROCK 13-32140S 200E4304736992

32-14-20

FLAT ROCK 14-

32140S200E4304736993

32-14-20

FLAT ROCK 15- 32140S 200E4304736994 32-14-20

UTE TRIBAL 8-25-14-19 30140S 200E4304739053

Flat Rock 30-3A 4304730729

Ute Tribal 30-1 4304715764

Ute Tribal 30-4A 4304716520

Sincerely,

## **Charlie Gibson**

**Operations Manager** 

Cobra Oil & Gas

(940)716-5100 (o)

(940)781-6260 (c)